

Badjia (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Damie</u>												
	Dambara	50	No system									1320
	Jaway	300	No system									1319
	Ngeluhun	666	1/6 - bore hole	1992	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1313
			2/6 - hand dug well	2003	NACSA	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1314
			3/6 - bore hole	1992	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1315
			4/6 - hand dug well	2004	OTHER	dry 3 months/year	OTHER - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1316
			5/6 - hand dug well	2006	Islamic Development Bank	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1317
			6/6 - hand dug well	2010	SALWACO	not finished						- 1318
<u>Fallay</u>												
	Bumpewo	1255	No system									1323
	Pelewahun	800	No system									1321
	Pendebu	153	No system									1322
<u>Kpallay</u>												
	Fallah	250	hand dug well	2009	SALWACO	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1297
	Gumahun	520	hand dug well	2005	NACSA	dry 6 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1296
	Jokibu	550	hand dug well	2010	SALWACO	not finished						- 1299
	Kpakru	245	No system									1301
	Kugbanhu	250	No system									1300
	Ngiyewoma	420	hand dug well	1992	Bo Pujehun	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1298
	Njandama 1	150	No system									1302
	Njandama3	160	No system									1303
<u>Niagbahun</u>												
	Baama 1	200	No system									1287
	Bangima	45	No system									1291
	Jellu 1	120	No system									1293
	Jellu 2	95	No system									1294
	Kbewama	275	No system									1292
	Kpetema	425	No system									1288

Badjia (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Njagbahun												
	Kpowabu	350	bore hole	1991	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1286
	Ngalahun	120	No system									1290
	Njagbahun	400	bore hole	1991	Bo Pujehun	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1285
	Solima	175	No system									1289
	Yovuhun	50	No system									1295
Sei												
	Geima	104	No system									1306
	Koindu	160	No system									1310
	Korjehun	250	hand dug well	2009	SALWACO	dry 4 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1304
	Madina	40	No system									1307
	Ngeihun	200	No system									1311
	Norniamma	1500	hand dug well	2009	SALWACO	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1305
	Sahun	170	No system									1312
	Sasso	350	No system									1308
	Sembehun	150	No system									1309

5 sections 34 villages - 25 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Badjia - summary / 9 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	4	2 082	0	4 (100%)	4	4 (100%)	0 (0%)	0 (0%)	4 (100%)
hand dug well	10	6 154	2	2 (20%)	8	4 (50%)	2 (20%)	3 (30%)	3 (30%)
	14	8 236	2	6 (42,9%)	12	8 (67%)	2 (14%)	3 (21%)	7 (50%)

Bagbo (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Bum</u>												
	Balleh	250	No system									1332
	Bumkarku	330	1/2 - bore hole	1987	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			2/2 - hand dug well	2005	World Vision	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Gballeh	257	1/2 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			2/2 - hand dug well	2007	World Vision	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Gbatorma	149	1/2 - hand dug well	2008	World Vision	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			2/2 - hand dug well	2008	SALWACO	not finished						-
	Mandu 1	140	hand dug well	2007	World Vision	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Tokpumbu 2	102	No system									1331
<u>Jimmi</u>												
	Bandajuma	320	1/3 - bore hole	2010	SALWACO	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			2/3 - bore hole	1987	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
		640	3/3 - bore hole	2008	CARITAS	working	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Farbu	100	hand dug well	2008	World Vision	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Gbangoya	120	hand dug well	1987	World Vision	dry 1 month/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Gordie	98	No system									1381
	Jimmi	242	01/19 - hand dug we	2008	World Vision	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			02/19 - bore hole	1987	Bo Pujehun	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			03/19 - hand dug we	2008	CARITAS	dry 1 month/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
			04/19 - hand dug we	2007	World Vision	dry 1 month/year	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			05/19 - hand dug we	2007	World Vision	dry 4 months/year	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			06/19 - hand dug we	2003	UNHCR	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			07/19 - bore hole	2009	SALWACO	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			08/19 - hand dug we	2003	UNHCR	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			09/19 - hand dug we	2008	SALWACO	not finished						-
			10/19 - hand dug we	2008	World Vision	dry 6 months/year	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			11/19 - hand dug we	1999	Oxfam	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			12/19 - hand dug we	2004	IRC	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			13/19 - hand dug we	2010	Evangelical Lutheran S/L	not finished						-

Bagbo (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Jimmi</u>												
	Jimmi	242	14/19 - bore hole	1986	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1346
			15/19 - bore hole	2006	<i>SALWACO</i>	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1347
			16/19 - hand dug we	2007	<i>World Vision</i>	dry 3 months/year	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1348
			17/19 - hand dug we	2001	<i>UNHCR</i>	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1349
			18/19 - hand dug we	2005	<i>UNHCR</i>	dry 5 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1350
			19/19 - hand dug we	2001	<i>UNHCR</i>	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1351
	Kakama	530	bore hole	1987	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1357
	Kanga	75	No system									1382
	Kpawama	140	1/4 - hand dug well	2008	<i>ACF</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1376
			2/4 - hand dug well	2005	<i>SALWACO</i>	not finished						- 1377
			3/4 - hand dug well	2007	<i>World Vision</i>	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1378
			4/4 - hand dug well	2008	<i>CARITAS</i>	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1379
	Levuma	432	1/2 - hand dug well	2006	<i>World Vision</i>	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1352
			2/2 - hand dug well	2007	<i>ACTION AID</i>	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1353
	Limba	500	1/3 - bore hole	1987	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1354
			2/3 - bore hole	1987	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1355
			3/3 - hand dug well	2006	<i>ACF</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1356
	Mandu	203	1/3 - bore hole	1987	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1358
			2/3 - hand dug well	2008	<i>World Vision</i>	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1359
			3/3 - hand dug well	2010	<i>World Vision</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1360
	Mathru	333	1/3 - bore hole	2005	<i>ACF</i>	dry 1 month/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1364
			2/3 - bore hole	1988	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1365
			3/3 - bore hole	2007	<i>World Vision</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1366
	Senehun Ngola	168	1/6 - hand dug well	2009	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1370
			2/6 - bore hole	1987	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1371
			3/6 - bore hole	1987	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1372
			4/6 - bore hole	1987	<i>CARITAS</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1373
			5/6 - hand dug well	2010	<i>World Vision</i>	dry 2 months/year	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1374
			6/6 - hand dug well	2007	<i>SALWACO</i>	not finished						- 1375

Bagbo (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Jimmi</u>												
	Waiima	203	hand dug well	2007	ACTION AID	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Yainkain	600	bore hole	1987	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
<u>Kpangbalie</u>												
	Kpangbalie	162	1/3 - hand dug well	1988	Bo Pujehun	working	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			2/3 - bore hole	2005	World Vision	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
		325	3/3 - hand dug well	2010	World Vision	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Mbwomí	225	1/2 - hand dug well	2007	World Vision	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			2/2 - hand dug well	2008	SALWACO	not finished						-
	Moigbain	250	bore hole	2007	World Vision	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Mowodeh	130	hand dug well	2007	World Vision	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Nyadehun	420	1/2 - hand dug well	1988	Bo Pujehun	working	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
		376	2/2 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
<u>Mano</u>												
	Dandabu	622	bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Manoryogbor	378	1/6 - bore hole	1987	Bo Pujehun	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			2/6 - hand dug well	2007	World Vision	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			3/6 - bore hole	2007	Bo Pujehun	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			4/6 - hand dug well	2008	SALWACO	not finished						-
			5/6 - bore hole	1987	Bo Pujehun	pump broken	K - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			6/6 - hand dug well	2007	World Vision	dry 4 months/year	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Mondorkoh	800	bore hole	1991	Bo Pujehun	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Tokpumbu 1	97	No system									1391
<u>Ngolapoi</u>												
	Bumpewo	180	hand dug well	2008	World Vision	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Deima	320	1/2 - bore hole	1988	Bo Pujehun	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			2/2 - hand dug well	2008	World Vision	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Gbainya	175	1/2 - hand dug well	2008	World Vision	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal
			2/2 - hand dug well	2008	SALWACO	not finished						-
	Kassie	150	1/2 - hand dug well	1988	Bo Pujehun	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK

Bagbo (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Ngolapoi</u>												
	Kassie	150	2/2 - hand dug well	2008	<i>World Vision</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1435
	Largowa	236	1/2 - hand dug well	2008	<i>World Vision</i>	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1428
		627	2/2 - bore hole	1988	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1431
	Mohapeiwa	120	hand dug well	2008	<i>World Vision</i>	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1440
	Moigbo	250	hand dug well	2008	<i>World Vision</i>	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1438
	Mokoba	150	hand dug well	2010	<i>World Vision</i>	not finished					-	1439
	Ngorapoi	350	bore hole	1988	<i>Bo Pujehun</i>	dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1436
	Njala	130	No system									1443
	Pangama	105	No system									1444
	Yeasan	450	1/2 - bore hole	1988	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1432
			2/2 - hand dug well	2009	<i>World Vision</i>	working	OTHER	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1433
<u>Niagorehun</u>												
	Giebena	175	hand dug well	2008	<i>ACTION AID</i>	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1454
	Kpetewama	350	hand dug well	2006	<i>ACTION AID</i>	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1452
	Mandehun	350	hand dug well	2006	<i>World Vision</i>	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1453
	Niagorehun	750	1/7 - bore hole	1988	<i>Bo Pujehun</i>	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1445
			2/7 - bore hole	1988	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1446
			3/7 - hand dug well	2008	<i>World Vision</i>	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1447
			4/7 - hand dug well	2009	<i>OTHER</i>	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1448
			5/7 - bore hole	1988	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1449
			6/7 - hand dug well	2010	<i>SALWACO</i>	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1450
			7/7 - bore hole	1988	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1451
<u>Tissama</u>												
	Fola	620	bore hole	1988	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1421
	Kutulabrama	420	hand dug well	2007	<i>World Vision</i>	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1410
	Magorehun2	180	No system									1426
	Maniabo	250	No system									1424
	Maniwa	600	bore hole	1988	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1417

Bagbo (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Tissama												
	Masagbahun	120	No system									1427
	Modamba	150	1/2 - hand dug well	2007	<i>World Vision</i>	dry 3 months/year	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			2/2 - hand dug well	2008	<i>SALWACO</i>	not finished						1411
	Mogimmy	150	No system									1412
	Momado	300	hand dug well	2007	<i>SALWACO</i>	not finished						1425
	Momajoe	500	1/7 - hand dug well	2008	<i>World Vision</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			2/7 - hand dug well	2004	<i>NACSA</i>	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			3/7 - hand dug well	2007	<i>NACSA</i>	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			4/7 - hand dug well	2010	<i>World Vision</i>	not finished						1405
			5/7 - pulley	2008	<i>World Vision</i>	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			6/7 - hand dug well	2010	<i>Evangelican Lutherhan S/L</i>	not finished						1406
			7/7 - hand dug well	1988	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Mowain	427	bore hole	1988	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Ngolawoma	350	1/2 - hand dug well	2007	<i>World Vision</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			2/2 - bore hole	2008	<i>SALWACO</i>	not finished						1413
	Sembehun	250	bore hole	1988	<i>Bo Pujehun</i>	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Tengbellah	375	1/2 - bore hole	1988	<i>Bo Pujehun</i>	pump broken	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			2/2 - hand dug well	2009	<i>World Vision</i>	pump broken	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Tissama	600	bore hole	1988	<i>Bo Pujehun</i>	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Yegeleh	407	1/3 - bore hole	1988	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			2/3 - hand dug well	1988	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			3/3 - bore hole	2010	<i>Evangelican Lutherhan S/L</i>	not finished						1420

Bagbo (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.
---------	---------	--------------------	-------------	------	---------	------------	-----------	---------------	-----------------	------------------	-----------------

7 sections 62 villages - 11 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Bagbo - summary / 51 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	45	18 798	2	34 (75,6%)	43	36 (84%)	0 (0%)	3 (7%)	40 (89%)
hand dug well	74	21 166	13	24 (32,4%)	62	48 (77%)	8 (11%)	23 (31%)	30 (41%)
	119	39 964	15	58 (48,7%)	105	84 (80%)	8 (7%)	26 (22%)	70 (59%)

Bagbwe (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Jongo</u>												
	Bandajoma	220	hand dug well	2009	German Agro Action	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1105
	Bandajuma	220	No system									1110
	Bijoa	110	No system									1112
	Buma	400	1/2 - hand dug well	1987	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1106
		300	2/2 - bore hole	2010	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1107
	Fanbu	80	No system									1108
	Gbaama	840	bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1103
	Kondiama	485	bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1104
	Kpaola	200	hand dug well	2006	German Agro Action	dry 5 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 1101
	Kpawula	200	No system									1113
	Mopendeh	150	No system									1111
	Samie	216	1/3 - bore hole	1983	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1098
			2/3 - bore hole	1983	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1099
			3/3 - bore hole	2010	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1100
	Vonoma	70	No system									1109
	Yengema	800	hand dug well	2000	Organization of African Uni	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1102
	Yengoma	848	No system									1114
<u>Kemoh</u>												
	Benduma	400	1/4 - hand dug well	1993	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1115
		500	2/4 - hand dug well	2009	NACSA	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1116
		100	3/4 - hand dug well	1993	Bo Pujehun	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 1117
		200	4/4 - hand dug well	2000	OTHER	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1118
	Kpetema	300	1/2 - hand dug well	1992	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1121
		200	2/2 - bore hole	2009	SALWACO	dry 4 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1122
	Languama	120	hand dug well	2009	German Agro Action	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1127
	Lowama	150	1/2 - hand dug well	1992	Bo Pujehun	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1123
		300	2/2 - bore hole	2009	Organization of African Uni	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1124
	Niahun	250	1/2 - bore hole	1992	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1125
			2/2 - hand dug well	2009	Organization of African Uni	dry 1 month/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 1126

Bagbwe (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Kemoh												
	Pelewahun	405	hand dug well	1996	Organization of African Uni	dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1120
	Yangambu	420	hand dug well	2009	OTHER	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1119
Niawa												
	Baali	200	1/4 - hand dug well	2005	NACSA	pump broken	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1087
		190	2/4 - hand dug well	1989	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1088
		200	3/4 - hand dug well	2010	Organization of African Uni	pump broken	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1089
		300	4/4 - hand dug well	2005	ACTION AID	pump broken	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1090
	Bangaru	20	No system									1095
	Gbonjema	550	hand dug well	2006	German Agro Action	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1094
	Kandu	100	No system									1096
	Kpoawala	26	No system									1097
	Njalakendema	360	1/3 - bore hole	2006	Bo Pujehun	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1091
		180	2/3 - bore hole	2010	OTHER	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1092
		200	3/3 - hand dug well	2005	ACTION AID	dry 5 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1093
Nyallay												
	Blama	500	hand dug well	2009	German Agro Action	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1074
	Foinda	60	No system									1086
	Gbama	219	1/4 - bore hole	1990	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1075
		300	2/4 - bore hole	2008	Korean Group	not finished						1076
		560	3/4 - hand dug well	1990	Bo Pujehun	dry 6 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1077
		311	4/4 - hand dug well	1998	ACTION AID	dry 12 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1078
	Gibina	300	No system									1079
	Keibawana	20	No system									1085
	Korwama	500	No system									1084
	Kpatou	419	No system									1081
	Kpetewoma	150	No system									1080
	Ngalu	300	1/3 - bore hole	1986	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1071
		150	2/3 - bore hole	1986	Bo Pujehun	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1072
		300	3/3 - hand dug well	2001	ACTION AID	dry 3 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1073

Bagbwe (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Nyalay</u>												
	Walihun	70	No system									1083
	Yawei	200	No system									1082
<u>Samawa</u>												
	Baama Njagor	312	hand dug well	2009	German Agro Action	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1069
	Konjo Ndorma	360	hand dug well	1995	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1061
	Konso Ngeyeihun	234	hand dug well	2009	German Agro Action	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1064
	Kpakuma	250	No system									1070
	Kpetema	300	hand dug well	2010	German Agro Action	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1062
	Mendewa	200	1/3 - bore hole	1983	Bo Pujehun	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1066
		300	2/3 - hand dug well	2004	NACSA	not finished						- 1067
		150	3/3 - hand dug well	2007	L D S Charities	pump broken	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1068
	Palima	250	bore hole	1990	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1063
	Vengema	203	hand dug well	2009	German Agro Action	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1065

5 sections 46 villages - 19 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Bagbwe - summary / 27 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	17	4 982	1	13 (76,5%)	16	14 (88%)	1 (6%)	0 (0%)	15 (88%)
hand dug well	31	9 635	1	14 (45,2%)	30	23 (77%)	4 (13%)	7 (23%)	19 (61%)
	48	14 617	2	27 (56,2%)	46	37 (80%)	5 (10%)	7 (15%)	34 (71%)

Baoma (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Bambawo</u>												
	Bangoma	65	No system									52
	Falla	515	No system									56
	Feiba	250	bore hole	1992	Bo Pujehun	dry 3 months/year	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 41
	Gbaiima	250	hand dug well	2004	ACF	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 30
	Gerihun	358	01/24 - hand dug we	2010	Caritas	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 74
			02/24 - hand dug we	2007	Care	working	PB2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 75
			03/24 - bore hole	2008	Korean Group	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 76
			04/24 - hand dug we	2008	Care	dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 77
			05/24 - hand dug we	2007	Care	working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 78
			06/24 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 79
			07/24 - bore hole	1988	Bo Pujehun	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 80
			08/24 - bore hole	2007	Korean Group	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 81
			09/24 - hand dug we	2007	Plan International	pump broken	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 82
			10/24 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 83
	Golaila		11/24 - hand dug we	2010	Caritas	working	K	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 84
			12/24 - hand dug we	2008	Celtel	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 85
			13/24 - bore hole	1993	Bo Pujehun	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 86
			14/24 - hand dug we	2003	Caritas	dry 3 months/year	PB2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 87
			15/24 - hand dug we	2004	Organization of African Uni	working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 88
			16/24 - hand dug we	2002	Plan International	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 89
			17/24 - hand dug we	2003	IRC	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 90
			18/24 - hand dug we	2003	IRC	pump broken	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 91
			19/24 - hand dug we	2003	IRC	dry 4 months/year	IN - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 92
			20/24 - hand dug we	2003	IRC	dry 3 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 93
	Golaila		21/24 - hand dug we	2003	IRC	dry 2 months/year	PB2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 94
			22/24 - bore hole	2010	Korean Group	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 95
			23/24 - hand dug we	1988	Bo Pujehun	dry 1 month/year	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 96
			24/24 - hand dug we	1987	Red Cross	working	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 97
						working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 34

Baoma (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Bambawo</u>												
Gollu	320	1/5 - bore hole	1989	Bo Pujehun		working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 23
		2/5 - hand dug well	2010	Caritas		working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 24
		3/5 - hand dug well	2010	Caritas		working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 25
		4/5 - bore hole	1989	Bo Pujehun		working	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 26
		5/5 - pulley	2001	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 27
Gondama	500	hand dug well	2004	ACF		dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 38
Jormu	2600	bore hole	1990	Bo Pujehun		dry 6 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 42
Kanjalu	250	1/2 - bore hole	1992	Bo Pujehun		dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 45
		2/2 - hand dug well	2001	ACF		working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 46
Kenemawo	85	No system										54
Komende	200	1/3 - bore hole	1999	Bo Pujehun		working	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 31
		2/3 - hand dug well	2010	Caritas		working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 32
		3/3 - hand dug well	2010	OTHER		working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 33
Konia	472	1/5 - hand dug well	2009	Caritas		working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 98
		2/5 - bore hole	1988	Bo Pujehun		working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 99
		3/5 - bore hole	1988	Bo Pujehun		working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 100
		4/5 - hand dug well	2009	SALWACO		dry 6 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 101
		5/5 - hand dug well	2010	SALWACO		working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 102
Kpetewoma	80	No system										53
Louwomie	60	No system										49
Lungi	250	hand dug well	2008	Caritas		working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 36
Maina	680	bore hole	1982	Bo Pujehun		working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 43
Matama	350	bore hole	1990	Bo Pujehun		working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 39
Mogbuama	300	hand dug well	2007	Red Cross		working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 47
Ngaihun	70	No system										51
Ngaullu	500	hand dug well	2003	ACTION AID		dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 44
Ngayaimie	244	pulley	2004	Red Cross	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 28
Njaima	40	No system										48
Nongoba	300	hand dug well	2007	Caritas		working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 35

Baoma (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Bambawo</u>												
	Palima 1	100	hand dug well	2008	Caritas	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 37
	Palima 2	350	hand dug well	2008	Caritas	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 29
	Pujehun	50	No system									50
	Tobanda	500	bore hole	1990	Bo Pujehun	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 40
	Vaahun	95	No system									55
<u>Follov</u>												
	Bangeama	30	No system									153
	Baomadi	224	1/5 - bore hole	2001	ACTION AID	dry 5 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 147
			2/5 - hand dug well	2000	Organization of African Uni	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 148
			3/5 - hand dug well	2010	OTHER	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 149
			4/5 - hand dug well	2009	OTHER	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 150
			5/5 - hand dug well	2004	OTHER	not finished						- 151
	Baomona	500	01/12 - bore hole	1988	Bo Pujehun	working	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 131
			02/12 - hand dug we	2002	OTHER	not finished						- 132
			03/12 - hand dug we	2004	OTHER	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 133
			04/12 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 134
			05/12 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 135
			06/12 - bore hole	1988	Bo Pujehun	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 136
			07/12 - bore hole	1988	Bo Pujehun	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 137
			08/12 - hand dug we	2009	OTHER	not finished						- 138
			09/12 - hand dug we	2008	Islamic Development Bank	dry 6 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 139
			10/12 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 140
			11/12 - hand dug we	2003	OTHER	dry 1 month/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 141
			12/12 - bore hole	2003	IRC	pump broken	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 142
	Gbandi	350	1/2 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 145
			2/2 - hand dug well	2004	ACTION AID	dry 6 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 146
	Nyayagoihun	12	No system									152
	Wairma	450	1/2 - hand dug well	2007	OTHER	dry 2 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 143
			2/2 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 144

Baoma (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Keimaya</u>												
	Kortumahun	100	No system									21
Kpumbu		100	1/3 - hand dug well	2000	Gosl	dry 4 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/3 - hand dug well	2009	ACTION AID	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			3/3 - hand dug well	2010	ACTION AID	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Manowa	150	No system									20
	N'jaluihun	80	No system									22
<u>Lower Pataloo</u>												
	Blamawo	250	hand dug well	2006	ACTION AID	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal
Buma		200	1/3 - bore hole	1989	Bo Pujehun	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK
			2/3 - bore hole	2007	SALWACO	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal
			3/3 - bore hole	2009	OTHER	dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working
Dogbogoma		825	1/2 - hand dug well	2007	ACTION AID	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK
			2/2 - hand dug well	2007	ACTION AID	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK
Kpakru		457	1/2 - bore hole	1980	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK
			2/2 - bore hole	1980	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK
	Kpoma	100	No system									129
M'gobbu		100	1/5 - hand dug well	2008	ACTION AID	dry 6 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/5 - hand dug well	2008	ACTION AID	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			3/5 - hand dug well	2009	Korean Group	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			4/5 - hand dug well	2009	SALWACO	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			5/5 - hand dug well	2009	ACTION AID	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Quallama	49	hand dug well	2010	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Saigaima	15	No system									130
Taninahun		110	1/2 - hand dug well	2009	ACTION AID	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			2/2 - bore hole	1983	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK
Yamariah		280	1/10 - hand dug well	2007	OTHER	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			10/10 - hand dug we	2009	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK
			2/10 - bore hole	2008	Korean Group	not finished						-
			3/10 - bore hole	2009	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK

Baoma (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Lower Pataloo</u>												
	Yamariah	280	4/10 - bore hole	1988	Bo Pujehun	working	K - stolen	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 106
			5/10 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 107
			6/10 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 108
			7/10 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 109
			8/10 - hand dug well	2002	Oxfam	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 110
			9/10 - hand dug well	2009	UNHCR	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 111
<u>Maowijeh</u>												
	Gbenima	130	bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 181
	Kigbeai	475	1/2 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 186
			2/2 - hand dug well	2010	Bo District Council	working	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 187
	Massoo	250	1/2 - bore hole	1990	Bo Pujehun	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 175
			2/2 - hand dug well	2008	Caritas	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 180
	Pelewahun	1960	1/5 - bore hole	1988	Bo Pujehun	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 190
			2/5 - bore hole	1988	Bo Pujehun	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 191
			3/5 - hand dug well	2005	OTHER	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 192
			4/5 - hand dug well	2005	OTHER	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 193
			5/5 - hand dug well	2003	World Vision	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 194
	Sawura	460	1/2 - hand dug well	2009	L D S Charities	dry 4 months/year	OTHER	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 188
			2/2 - hand dug well	2009	L D S Charities	dry 2 months/year	OTHER	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 189
	Tamgiamma	700	bore hole	1988	Bo Pujehun	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 185
	Taninihun	368	1/3 - bore hole	1993	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 182
			2/3 - bore hole	1993	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 183
			3/3 - hand dug well	2010	Islamic Development Bank	working	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 184
<u>Njaima</u>												
	Foiadu	430	1/2 - bore hole	1988	Bo Pujehun	working	OTHER	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 161
			2/2 - bore hole	1988	Bo Pujehun	working	OTHER	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 162
	Foiddu	430	1/2 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 177
			2/2 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 178
	Gbayama	2000	hand dug well	2007	ACTION AID	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 160

Baoma (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
Njaima													
	Gendema	266	1/3 - hand dug well	2006	ACTION AID	dry 4 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	154
			2/3 - hand dug well	2008	Caritas	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	155
			3/3 - hand dug well	2001	Care	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	156
	Jembeh	600	1/7 - bore hole	1980	Caritas	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK	167
			2/7 - pulley	2000	UNHCR	dry 12 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	168
			3/7 - hand dug well	2001	UNHCR	pump broken	OTHER - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working	169
			4/7 - bore hole	2000	UNHCR	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working	170
			5/7 - hand dug well	2000	UNHCR	pump broken	OTHER - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working	171
			6/7 - hand dug well	2000	UNHCR	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK	172
			7/7 - hand dug well	2002	UNHCR	dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working	173
	Kamaru	800	bore hole	1988	Bo Pujehun	dry 2 months/year	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	166
	Kanyama	1000	1/2 - hand dug well	2006	Bo Pujehun	not finished						-	164
			2/2 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK	165
	Komoru	800	bore hole	1988	ACTION AID	dry 2 months/year	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	179
	Massama	29	No system										174
	Ndama	401	hand dug well	2009	ACTION AID	dry 4 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	163
	Ngelahun	400	bore hole	1998	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	157
	Nyama	175	1/2 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	158
			2/2 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	159
Sonnah													
	Fabu	500	1/2 - hand dug well	2000	Bo Pujehun	dry 2 months/year	PB2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	5
			2/2 - hand dug well	2000	Bo Pujehun	dry 1 month/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	6
	Faikundu	150	No system										13
	Fayioma	130	hand dug well	2006	OTHER	dry 7 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	4
	Gangama	250	No system										15
	Gboyaiya	793	1/2 - bore hole	1993	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	8
			2/2 - hand dug well	2010	CARITAS	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	9
	Kanga	45	No system										14
	Kortumahun	500	hand dug well	2010	SALWACO	working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	7

Baoma (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Sonnah</u>												
	Kpatabu	830	hand dug well	1995	Bo Pujehun	dry 2 months/year	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1
	N'gualla	600	No system									16
	Nyiamma	1500	No system									12
	Sainda	207	hand dug well	2010	CARITAS	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 10
	Semabu	350	No system									11
	Tungberu	1000	1/2 - hand dug well	2005	OTHER	working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 2
			2/2 - hand dug well	2010	OTHER	working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 3
<u>Upper Pataloo</u>												
	Gbahama	1000	No system									68
	Gbahun	250	No system									70
	Gbangba	245	No system									67
	Homgbahan	300	No system									72
	Jonbuhun	365	No system									69
	Juhun	262	1/2 - hand dug well	2006	OTHER	dry 3 months/year	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 57
			2/2 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 58
	Komendeh	600	No system									73
	Kpatema	80	No system									66
	Kpomima	450	No system									71
	Matema	303	No system									65
	Pelewahun	200	hand dug well	2006	ACTION AID	working	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 59
	Yakaji	203	1/5 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 60
			2/5 - bore hole	1988	Bo Pujehun	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 61
			3/5 - bore hole	1980	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 62
			4/5 - hand dug well	2004	OTHER	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 63
			5/5 - hand dug well	2008	Caritas	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 64

Baoma (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.
---------	---------	--------------------	-------------	------	---------	------------	-----------	---------------	-----------------	------------------	-----------------

8 sections 93 villages - 32 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Baoma - summary / 61 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	65	30 893	1	49 (75,4%)	65	56 (86%)	3 (5%)	7 (11%)	54 (83%)
hand dug well	93	40 487	4	48 (51,6%)	92	72 (78%)	12 (13%)	22 (24%)	55 (59%)
	158	71 380	5	97 (61,4%)	157	128 (82%)	15 (9%)	29 (18%)	109 (69%)

Bo town (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Bo town</u>												
	2nd Bongay street	1500	1/2 - hand dug well	1992	Red Cross	working	PB2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 58
		1000	2/2 - pulley	2005	Community	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 59
	3rd Bongay street	800	pulley	1993	UNICEF	dry 3 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 60
	8th Street	900	hand dug well	2008	City council	pump broken	PB2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 64
	Adama Street	800	hand dug well	1998	ACF	dry 3 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 87
	Aeroplane	150	hand dug well	2001	NACSA	dry 2 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 115
	Agric Street 1	800	hand dug well	1996	ACF	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 85
	Agric Street 2	600	hand dug well	1996	ACF	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 86
	Ahmadiyya Pr.Sch.	10000	hand dug well	1996	Bo Pujehun	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 94
	Ahmadiyya Sec.Sch.	11000	hand dug well	1997	Bo Pujehun	pump broken	K - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 95
	Alie Street	5600	hand dug well	2008	L D S Charities	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 68
	Bandajuma lay out 1	300	hand dug well	2009	L D S Charities	dry 6 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 96
	Bandajuma lay out 2	400	hand dug well	2008	L D S Charities	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 97
	Bangali Street	400	hand dug well	2008	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 108
	Batiaba Lay out	1500	hand dug well	2007	L D S Charities	dry 2 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 91
	Berewa Lane	1000	pulley	1984	UNICEF	dry 6 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 15
	Bo Kenema Highway 1	700	hand dug well	1995	Community	dry 2 months/year	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 23
	Bo Kenema Highway 2	500	hand dug well	2006	EU	working	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 24
	Bo Kenema Highway 3	2000	hand dug well	2006	EU	dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 26
	Bo Kenema Highway 4	3500	hand dug well	2008	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 28
	Bo Kenema Highway 5	4000	pulley	1999	Community	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 29
	Braima section	3500	hand dug well	2004	L D S Charities	dry 4 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 76
	Centenary Sec.School	2300	hand dug well	1984	UMC	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 48
	Cimbo Town 1	650	hand dug well	2008	L D S Charities	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 120
	Cimbo Town 2	400	hand dug well	2008	L D S Charities	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 121
	Comenday 3	550	hand dug well	1992	Bo Pujehun	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 112
	Comenday 4	1500	hand dug well	1992	Bo Pujehun	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 113
	Comenday Section 1	500	hand dug well	1992	Bo Pujehun	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 110

Bo town (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Bo town</u>												
Comeday Section 2	500	hand dug well	1992	<i>Bo Pujehun</i>		pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 111
Diver Street	3500	hand dug well	2008	<i>Town Council</i>		pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1
Every Nation School C	5000	hand dug well	1996	<i>ACF</i>		pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 18
Fagoya Road	3000	hand dug well	2008	<i>Town Council</i>		dry 4 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 43
Fambuleh Street	2500	hand dug well	2009	<i>Bo Pujehun</i>		working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 51
Flowown Sect. Thoma	1000	hand dug well	2008	<i>L D S Charities</i>		dry 2 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 69
Gbanja Town 1	300	hand dug well	2008	<i>L D S Charities</i>		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 122
Gbanja Town 2	400	hand dug well	2008	<i>L D S Charities</i>		pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 123
Gbetehoma Section	300	hand dug well	2008	<i>Bo Pujehun</i>		dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 109
Gboba	500	hand dug well	2006	<i>City council</i>		working	PB2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 57
Gbondo Town	700	hand dug well	2008	<i>L D S Charities</i>		working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 124
Hannah Street	4000	hand dug well	2010	<i>Muslim Agency</i>		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 32
Hospital Quarter	400	bore hole	2002	<i>EU</i>		pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 114
J Quater	700	hand dug well	2009	<i>L D S Charities</i>		working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 66
Jubilie Street 1	600	pulley	2005	<i>Community</i>		dry 3 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 79
Jubilie Street 2	800	hand dug well	2007	<i>Community</i>		dry 2 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 84
Kabbie town 1	500	hand dug well	2002	<i>EU</i>		pump broken	PB2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 73
Kabbie town 2	950	hand dug well	2008	<i>City council</i>		working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 74
Kaindeyiala Old Road	3500	hand dug well	2010	<i>SALWACO</i>		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 35
Kaitibie Street	3000	pulley	1978	<i>Community</i>		-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 27
Kakua School 1	2500	hand dug well	1997	<i>Bo Pujehun</i>		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 11
Kakua School 2	2000	bore hole	2009	<i>World Bank</i>		not finished						- 12
kakua street	3000	hand dug well	1986	<i>Bo Pujehun</i>		dry 4 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 103
Kallon Street	2500	hand dug well	2010	<i>Town Council</i>		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 34
Kandeh Town Extentio	2000	hand dug well	2008	<i>Town Council</i>		working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 41
Kandeh TOWN, Sanno	2500	hand dug well	2008	<i>Town Council</i>		dry 2 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 40
Kandeh Town,Lahai St	3500	hand dug well	2008	<i>Town Council</i>		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 39
Karimu Street	850	hand dug well	2008	<i>L D S Charities</i>		dry 1 month/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 20

Bo town (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Bo town</u>												
	Kayangba Street	250	pulley	1980	SALWACO	dry 3 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 81
	Kennedy Market	4500	hand dug well	2005	NACSA	not finished						- 37
	Kindia Town	2500	hand dug well	2008	<i>City council</i>	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 106
	Kissy Town Sam Stree	700	bore hole	1992	<i>Bo Pujehun</i>	pump broken	PB2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 118
	Kowama Section	7000	hand dug well	2008	<i>Town Council</i>	dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 38
	Kulanda Town 1	600	hand dug well	2008	<i>L D S Charities</i>	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 104
	Kulanda Town 2	3000	hand dug well	2005	<i>Bo Pujehun</i>	dry 12 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 105
	Macrobert Street	650	hand dug well	1984	<i>EU</i>	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 93
	Madona School Comm	720	hand dug well	2007	<i>SABABU</i>	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 5
	Manjama Market	6000	hand dug well	2010	<i>Town Council</i>	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 31
	Manjama Section	3500	hand dug well	2010	<i>L D S Charities</i>	dry 11 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 33
	Masec Agric. Commun	920	hand dug well	2000	<i>Community</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 21
	Masec Agric. Commun	600	hand dug well	2006	<i>Community</i>	pump broken	OTHER - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 22
	Mboguba Street	1600	hand dug well	2009	<i>L D S Charities</i>	dry 2 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 90
	Mesima Old Railway Li	3000	hand dug well	1996	<i>ACF</i>	dry 12 months/year	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 17
	Mesima Old Railway Li	500	hand dug well	2008	<i>Town Council</i>	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 7
	Mesima Old Railway Li	120	pulley	2007	<i>Muslim Agency</i>	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 8
	Mesima Old Railway Li	105	hand dug well	2008	<i>Town Council</i>	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 9
	Mesima School (UMC)	900	hand dug well	1995	<i>Bo Pujehun</i>	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 6
	Model School Commu	3500	hand dug well	2003	<i>UNICEF</i>	dry 2 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 42
	Musa Street	2600	hand dug well	2005	<i>Lesen Enterprise</i>	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 2
	National Islamic Schoo	850	hand dug well	2007	<i>Bo Pujehun</i>	dry 5 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 3
	Nduvuibu 1	300	hand dug well	2008	<i>L D S Charities</i>	dry 4 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 98
	Nduvuibu 2	250	hand dug well	2008	<i>L D S Charities</i>	dry 7 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 99
	Nduvuibu 3	300	pulley	2001	<i>Community</i>	dry 8 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 100
	Nduvuibu 4	600	hand dug well	2008	<i>L D S Charities</i>	dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 101
	New Barracks Police S	2500	hand dug well	2005	<i>UNDP</i>	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 49
	New Life Service Scho	500	hand dug well	2005	<i>SABABU</i>	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 4

Bo town (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Bo town</u>												
	New London Anzarul P	950	hand dug well	2002	NACSA	not finished					-	67
	New York 1	850	hand dug well	2008	UNICEF	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	New York 2	770	hand dug well	2008	L D S Charities	not finished					-	71
	New York 3 Thomas st	650	hand dug well	2008	L D S Charities	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Ngalu Street 1	200	pulley	1998	Community	dry 2 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Ngalu Street 2	400	pulley	1998	Community	dry 3 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Nikibu Sect.SLMB Pr.S	1200	hand dug well	1996	Bo Pujehun	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Njagboi Street 1	200	pulley	1981	SALWACO	dry 1 month/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Njagboi Street 2	300	hand dug well	2008	L D S Charities	dry 6 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Njagboima 2	350	hand dug well	2008	NACSA	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Njai Town	2500	hand dug well	2007	L D S Charities	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	NTC Compound	600	hand dug well	1999	NTC Social Welfare	dry 4 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Nyagolihun Town	900	hand dug well	2008	L D S Charities	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Oba Town 1	500	hand dug well	1992	Bo Pujehun	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Oba Town 2	200	hand dug well	1992	Bo Pujehun	dry 1 month/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	OLD Koribondo Road	5000	hand dug well	2009	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Old Rail Way Quater	3000	bore hole	2009	Town Council	not finished					-	16
	Police Barracks Quarte	3000	hand dug well	1979	Bo Pujehun	working	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Police Barracks Quarte	2500	hand dug well	2008	Police Community	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	S D A Pr: Sch.	3000	hand dug well	1997	ACF	pump broken	IN - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Sam street	500	bore hole	1992	Bo Pujehun	pump broken	K - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Sambo Street	800	hand dug well	2008	City council	dry 2 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Sandemaho lay out	1300	hand dug well	2008	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Sandi Street	1000	pulley	1979	Community	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Sowo Street 1	1500	pulley	1997	Community	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Sowo Street 2	900	pulley	1985	UNICEF	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	St Therisa Police Scho	1500	bore hole	2008	Korean Group	dry 12 months/year	OTHER - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Tangabay street	450	hand dug well	2008	L D S Charities	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working

Bo town (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Bo town</u>												
Tengbewabu Section	2500	hand dug well	2006	EU		dry 5 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 25
Tommy Street	900	hand dug well	2008	Town Council		dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 36
Torgboi Town,Orlando	2500	hand dug well	2008	L D S Charities		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 52
U.B.C School	1300	bore hole	2000	Community		dry 2 months/year	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 56
UCC JSS	2000	bore hole	1980	EU		working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 61
UCC SSS	1800	hand dug well	2008	EU		dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 62
UMC Pr: Sch.	500	hand dug well	1997	Bo Pujehun		pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 63
Vaccum street	700	hand dug well	1990	Red Cross		pump broken	PB2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 55
West ward section	300	pulley	1996	ADB		dry 3 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 77
Yemoh Town	1500	hand dug well	2007	Town Council		dry 5 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 44
Yemoh Town Commun	1500	hand dug well	2006	Community		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 46
Yemoh Town St. Poul	950	hand dug well	2006	Anglican Mission		dry 4 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 47
Yemoh Town, BDEC S	1000	hand dug well	1997	Bo Pujehun		dry 1 month/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 45

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee: presence of a Committee of Users

Pump CareTaker: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Bo town					P U M P			SEASONALITY		
Type	Total	Popul. Approxim	Not finished	Functional all the year	installed	working	Dry>3m	seasonal	Alw. water	
bore hole	8	11 400	2	1 (12,5%)	6	2 (33%)	1 (12%)	1 (12%)	4 (50%)	
hand dug well	101	181 915	3	30 (29,7%)	99	54 (55%)	17 (17%)	23 (23%)	58 (57%)	
	109	193 315	5	31 (28,4%)	105	56 (53%)	18 (17%)	24 (22%)	62 (57%)	

Bumpeh Ngao (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Bongor</u>												
	Goryela	195	hand dug well	1988	FABRA	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 617
	Lugbu	195	1/2 - bore hole	1988	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 618
			2/2 - hand dug well	2002	NACSA	not finished						619
	Majama	195	hand dug well	1988	FABRA	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 616
	Mbelobu	115	No system									622
	Mougemba	95	No system									621
	Moyotu	150	hand dug well	1991	NACSA	dry 5 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 620
	Ngayama	195	hand dug well	1988	FABRA	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 615
<u>Bumpeh</u>												
	Bellor	400	hand dug well	2009	World Vision	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 712
	Boweh	176	1/4 - bore hole	2010	World Hope	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 685
			2/4 - bore hole	1980	FABRA	dry 4 months/year	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 686
			3/4 - hand dug well	2002	Oxfam	dry 5 months/year	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 687
			4/4 - hand dug well	2005	OTHER	dry 3 months/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 688
	Bumpehun	176	1/9 - hand dug well	2008	World Vision	dry 2 months/year	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 689
			2/9 - hand dug well	1990	UNDP	dry 2 months/year	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 690
			3/9 - hand dug well	1990	OTHER	not finished						691
			4/9 - bore hole	2010	World Hope	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 692
			5/9 - bore hole	1990	UNDP	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 693
			6/9 - hand dug well	2008	OTHER	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 694
			7/9 - hand dug well	2009	World Vision	dry 3 months/year	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 695
			8/9 - hand dug well	2005	OTHER	dry 3 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 696
			9/9 - bore hole	1980	FABRA	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 697
	Dassmu	172	1/2 - hand dug well	2006	Network Movement Develo	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 715
			2/2 - hand dug well	2008	World Vision	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 716
	Fanima	20	No system									725
	Fewanema	110	hand dug well	2008	World Vision	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 702
	Fongiyah	80	No system									734
	Gbojama	90	No system									739

Bumpeh Ngao (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Bumpeh												
	Hanga	120	hand dug well	2008	<i>World Vision</i>	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 701
	Kawayah	99	No system									730
	Kawoma	100	No system									733
	Kawoma 2	60	No system									740
	Konia	176	1/4 - bore hole	1980	<i>FABRA</i>	pump broken	K - stolen	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 681
			2/4 - bore hole	2010	<i>World Hope</i>	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 682
			3/4 - bore hole	1980	<i>FABRA</i>	pump broken	K - stolen	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 683
			4/4 - hand dug well	2008	<i>World Vision</i>	dry 4 months/year	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 684
	Konie	80	No system									731
	Kotumahun	250	hand dug well	2005	<i>Network Movement Develop</i>	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 718
	Kowama	62	1/3 - hand dug well	2008	<i>World Vision</i>	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 708
			2/3 - bore hole	1989	<i>FABRA</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 710
			3/3 - hand dug well	2010	<i>World Vision</i>	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 711
	Mamboma	60	No system									732
	Mbawoma	100	No system									735
	Mogogoing	65	hand dug well	2001	<i>World Vision</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 705
	Mokowu	100	No system									728
	Mongela	99	No system									736
	Monghati	150	hand dug well	2008	<i>SALWACO</i>	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 719
	Nganyahun	60	No system									737
	Ngeaihun	180	hand dug well	2008	<i>SALWACO</i>	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 720
	Ngeibu	100	bore hole	2010	<i>World Hope</i>	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 713
	Ngiyah 4	40	No system									723
	Ngliyahfull	250	hand dug well	2004	<i>FABRA</i>	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 704
	Nguabu	285	hand dug well	2008	<i>World Vision</i>	dry 2 months/year	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 706
	Nguala	100	No system									727
	Njagbama	40	No system									742
	Njaluihun	60	No system									726

Bumpeh Ngao (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Bumpeh</u>												
	N-Vakie	166	1/3 - hand dug well	2008	<i>World Vision</i>	dry 2 months/year	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 698
			2/3 - hand dug well	1985	<i>FABRA</i>	dry 2 months/year	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 699
			3/3 - bore hole	1985	<i>FABRA</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 700
	Nyagorehun	200	hand dug well	2007	<i>World Vision</i>	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 722
			1/2 - bore hole	1988	<i>FABRA</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 721
	Semabu Folobu	240	hand dug well	2005	<i>Network Movement Develo</i>	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 717
	Sembrehun Ngombi	20	No system									738
	Sembrehun1	300	bore hole	1989	<i>FABRA</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 703
	Sembrehun2	62	hand dug well	2004	<i>NACSA</i>	dry 4 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 709
	Sembekihun	30	No system									741
	Solima	320	bore hole	2010	<i>World Hope</i>	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 714
	Volima	20	No system									729
	Vulahun	60	No system									724
	Waima	200	bore hole	2007	<i>World Vision</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 707
<u>Foya</u>												
	Banda	46	No system									844
	Batihun	45	No system									849
	Benduma	35	No system									843
	Bobobu	35	No system									850
	Foya	192	1/3 - hand dug well	2008	<i>World Vision</i>	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 840
			2/3 - hand dug well	2008	<i>World Vision</i>	working	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 841
			3/3 - hand dug well	2008	<i>SALWACO</i>	not finished						- 842
	Kacarma	20	No system									851
	Kondiama	60	No system									847
	Kpetema	50	No system									845
	Kpetewama	55	No system									848
	Ndambu	30	No system									852
	Niagorehun	45	No system									846

Bumpeh Ngao (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Kpetema												
	Balehun	400	hand dug well	2009	World Vision	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 605
	Benduma	208	hand dug well	1988	FABRA	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 598
	Botalama	20	No system									611
	Guwella	243	bore hole	1988	FABRA	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 604
	Hasting	180	No system									613
	Hotawuloma	110	No system									609
	Jaiwengar	210	No system									612
	Jenehun 3	125	hand dug well	2000	FABRA	working	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 607
	Kaikumba	243	bore hole	1988	FABRA	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 603
	Kpakpabu	120	No system									614
	Kpanguma	208	1/2 - bore hole	1988	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 596
			2/2 - hand dug well	2009	NACSA	dry 7 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 597
	Kpejebu	75	No system									608
	Kpondemei	150	No system									610
	Missilla	208	hand dug well	2009	NACSA	dry 8 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 601
	Mogiba	125	bore hole	2010	World Hope	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 606
	Senehun	208	1/2 - hand dug well	1988	FABRA	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 599
			2/2 - hand dug well	2000	FABRA	working	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 600
	Yonnie	243	hand dug well	2009	World Vision	dry 6 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 602
Sahn												
	Banda Sahn	140	No system									638
	Gandema	140	hand dug well	2008	SALWACO	not finished					-	635
	Kpanayougo	286	1/2 - hand dug well	1988	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 633
			2/2 - hand dug well	2008	World Vision	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 634
	Manoma	70	No system									646
	Mowotowa	590	bore hole	1988	FABRA	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 637
	Ngeabema	120	No system									640
	Njorhabohu	60	No system									645

Bumpeh Ngao (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
<u>Sahn</u>													
	Sahn Junction	170	No system									642	
	Samabugbatoh	620	bore hole	1988	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	636	
	Sembuhun Woyeibu	110	No system									641	
	Tabilahun	160	No system									639	
	Tongo Field	286	hand dug well	1988	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	632	
	Torkoubu	30	No system									644	
	Victoria	130	No system									643	
<u>Serabu</u>													
	Farma	70	No system									594	
	Kpanguma	120	No system									592	
	Makeybie	70	No system									588	
	Ndukpubu	350	bore hole	1988	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	586	
	Ngulema	460	hand dug well	2010	World Vision	dry 4 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	587
	Nittewo	110	No system									590	
	Njagbaudima	75	No system									595	
	Njanema	125	No system									593	
	Njombohun	85	No system									589	
	Nyagorehun	95	No system									591	
	Serabu	3350	1/3 - hand dug well	2009	ADDO	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	583
			2/3 - hand dug well	2009	ADDO	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	584
			3/3 - hand dug well	2008	World Vision	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	585
<u>Sewama</u>													
	Bambara	166	1/2 - bore hole	1987	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK	657
			2/2 - hand dug well	2010	World Vision	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK	658
	Banda Town	126	1/3 - bore hole	1988	FABRA	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	649
			2/3 - hand dug well	2009	World Vision	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working	650
			3/3 - hand dug well	2005	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK	651
	Bolokar	85	No system									678	

Bumpeh Ngao (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Sewama</u>												
	Bondayilahun	142	1/2 - hand dug well	1989	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 666
			2/2 - hand dug well	2008	World Vision	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 667
	Buma	215	1/2 - hand dug well	1988	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 652
			2/2 - hand dug well	1988	FABRA	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 653
	Bunibu	217	bore hole	1989	FABRA	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 671
	Fonima	126	bore hole	1988	FABRA	working	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 648
	Juhun	216	hand dug well	2008	SALWACO	not finished					-	660
	Kania	142	hand dug well	2006	World Vision	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 664
	Katehun	217	bore hole	1989	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 669
	Kobaibu	126	hand dug well	2005	SALWACO	dry 7 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 647
	Konasu	65	No system									675
	Mafallon	166	1/2 - bore hole	1987	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 655
			2/2 - bore hole	1987	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 656
	Makailie	142	bore hole	1989	FABRA	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 665
	Modinawo	170	No system									674
	Mofoi	217	hand dug well	2010	World Vision	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 668
	Mogbevhoh	75	No system									677
	Mokpende	166	bore hole	1987	FABRA	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 654
	Mowoto	120	1/3 - bore hole	1987	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 661
			2/3 - hand dug well	2009	NACSA	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 662
			3/3 - bore hole	1987	FABRA	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 663
	Nguabu	110	No system									680
	Nyadehun	100	hand dug well	2010	ADDO	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 673
	Nyondehun2	90	No system									679
	Old Town	217	bore hole	1989	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 670
	Tissana	560	bore hole	1989	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 672
	Walahun	180	No system									676
	Yengemawo	380	bore hole	1987	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 659

Bumpeh Ngao (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Taninahun</u>												
	Badayah	70	No system									823
	Bagalu	80	No system									832
	Bambai	250	No system									830
	Benduma	120	No system									811
	Bobobu	150	No system									802
	Bumpewo	200	No system									807
	Dodo	130	No system									826
	Foiwama	200	hand dug well	2009	SALWACO	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 774
	Fulaninahun	70	1/2 - hand dug well	2006	FABRA	dry 2 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 770
			2/2 - hand dug well	2009	World Vision	dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 771
	Gabiyah	100	No system									778
	Gadama Ngitiwaya	250	No system									796
	Gbaguma	200	No system									836
	Gelehung	80	No system									809
	Godama Jajaima	250	No system									813
	Godama Ngombi	200	No system									787
	Gudi	120	No system									797
	Hagai	220	No system									782
	Histy	150	No system									795
	Hotawuiloma	250	No system									801
	Jelenga	200	No system									794
	Jennie	200	No system									788
	Kagai	80	No system									815
	Kagbima	250	No system									806
	Kamaru	100	No system									835
	Kowama Gbaby	150	No system									792
	Kpatema	150	No system									779
	Kpotiwoma	103	hand dug well	2009	World Vision	dry 2 months/year	K - stolen	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 773

Bumpeh Ngao (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Tarinahun</u>												
	Maginhun	200	No system									785
	Makayoni	800	bore hole	1987	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	763
	Manowo	200	No system									833
	Masahun	150	No system									800
	Matagialema	200	No system									786
	Mbaima	150	No system									780
	Mbawohun	150	hand dug well	2007	World Vision	dry 2 months/year	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 772
	Mbawoma	80	No system									822
	Miciela	200	No system									827
	Mocomby	200	No system									799
	Mogabai	50	No system									825
	Mogagba	350	bore hole	2010	World Hope	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 765
	Mogboda	80	No system									821
	Mokibi	150	No system									784
	Mokie Lemei	250	No system									819
	Mokobo	250	No system									789
	Mokoro	150	No system									814
	Momado	150	No system									805
	Momokanie Junction	200	No system									808
	Mongibidu	120	No system									824
	Motoko	150	No system									793
	Movuyah	400	bore hole	1980	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 757
	Moyowu	200	No system									818
	Nagbana	200	No system									790
	Ngadurhun	120	No system									812
	Ngalahun 1	100	No system									838
	Ngalahun 2	80	No system									839
	Ngiyah	100	No system									810

Bumpeh Ngao (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Taninahun</u>												
	Ngiyeiboi	400	hand dug well	2008	<i>World Vision</i>	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 764
	Ngolahun	500	1/2 - bore hole	1995	<i>FABRA</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 775
			2/2 - hand dug well	2006	<i>NACSA</i>	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 777
	Nguwala	200	No system									791
	Nitiwo	130	No system									783
	Njabahun	120	No system									834
	Njagbama	200	No system									831
	Nyadahun	200	No system									820
	Patama Semeon	50	No system									828
	Patama Wayeibu	200	No system									829
	Pelewahun	150	1/2 - hand dug well	2010	<i>World Vision</i>	dry 3 months/year	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 768
			2/2 - bore hole	2003	<i>FABRA</i>	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 769
	Pilewahun 3	150	No system									803
	Pilewahun2	200	No system									804
	Semabu	120	No system									781
	Sembeh	420	hand dug well	2008	<i>NACSA</i>	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 767
	Sembuhun Galiawa	200	No system									817
	Taninahun	240	1/5 - hand dug well	1988	<i>FABRA</i>	pump broken	K - stolen	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 758
			2/5 - bore hole	1988	<i>FABRA</i>	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 759
			3/5 - bore hole	1988	<i>FABRA</i>	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 760
			4/5 - hand dug well	2008	<i>NACSA</i>	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 761
			5/5 - hand dug well	2008	<i>NACSA</i>	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 762
	Tiamida	250	No system									816
	Toibu	200	No system									798
	Tugbobu	800	1/2 - bore hole	1988	<i>FABRA</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 766
		250	2/2 - bore hole	1995	<i>FABRA</i>	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 776
	Watet Loo	50	No system									837

Walihun

Bumpeh Ngao (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Walihun</u>												
	Bondayeilahun	250	No system									751
	Fabu	110	No system									755
	Gbando	105	No system									756
	Gemiega	120	No system									750
	Lugai	120	No system									754
	Majama	110	No system									749
	Masawo	175	hand dug well	2009 ADDO		working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Pilawahun	50	No system									753
	Segima	400	bore hole	1981 FABRA		working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK
	Tongayah	105	No system									752
	Walihun	218	1/4 - bore hole	1981 FABRA		dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
			2/4 - bore hole	1981 FABRA		dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
			3/4 - bore hole	1981 FABRA		dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
			4/4 - hand dug well	2007 Islamic Development Bank	working		K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
<u>Yengema</u>												
	Kanga	100	No system									629
	Komeude	170	No system									631
	Kowama	130	No system									630
	Kpandobu	250	hand dug well	1990 SALWACO		dry 5 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Madina	45	No system									627
	Mojajoe	150	No system									628
	Ndebuma	250	1/2 - bore hole	1988 FABRA		working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			2/2 - hand dug well	1990 World Vision		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Ngeahun	40	No system									626

Bumpeh Ngao (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
---------	---------	--------------------	-------------	------	---------	------------	-----------	---------------	-----------------	------------------	-----------------	------

10 sections 222 villages - 139 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Bumpeh Ngao - summary / 83 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	51	13 253	0	35 (68,6%)	51	40 (78%)	2 (4%)	4 (8%)	45 (88%)
hand dug well	80	25 247	5	30 (37,5%)	75	65 (87%)	15 (19%)	27 (34%)	33 (41%)
	131	38 500	5	65 (49,6%)	126	105 (83%)	17 (13%)	31 (24%)	78 (60%)

Gbo (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Gbo</u>												
Baluhun	80	No system										1200
Benduma	40	No system										1192
Bissibu	150	bore hole	2000	ACTION AID		dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1188
Boforfu	100	No system										1202
Bonyeya	70	No system										1201
Fargoya	15	No system										1196
Gbagalama	30	No system										1203
Gbaiima	212	1/9 - hand dug well	1989	Korean Group		working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1176
		2/9 - hand dug well	1989	Korean Group		dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1177
		3/9 - hand dug well	2009	Care		working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1178
		4/9 - bore hole	2010	Korean Group		pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1179
		5/9 - bore hole	2010	Korean Group		pump broken	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1180
		6/9 - hand dug well	2008	SALWACO		dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1181
		7/9 - hand dug well	2009	Korean Group		dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1182
		8/9 - hand dug well	2009	OTHER		dry 4 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1183
		9/9 - hand dug well	2009	NACSA		dry 3 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1184
Gbeworbu	170	No system										1204
Heima	56	No system										1191
Kortumahun Mavie	62	No system										1195
Kossa	25	No system										1193
Magihun	120	hand dug well	1997	ACTION AID		dry 4 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1189
Massahun	37	No system										1194
Mokabie	200	hand dug well	1990	Care		dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1185
Nagbema	50	No system										1198
Ngolala	170	hand dug well	1997	ACTION AID		dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1190
Ngoyiahum 2	120	No system										1199
Nyagoihun	100	1/2 - hand dug well	1999	Islamic Development Bank		dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1186
	70	2/2 - bore hole	2009	NACSA		dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1187
Semehun	125	No system										1197

Gbo (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Gbo</u>												
<u>Maryu</u>												
Bajawo	50	No system										1226
Dodo	140	1/3 - hand dug well	2009	NACSA		dry 3 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1218
		2/3 - hand dug well	2006	<i>Islamic Development Bank</i>	not finished							- 1219
		3/3 - hand dug well	2004	<i>Islamic Development Bank</i>	not finished							- 1220
Gbagoma	30	No system										1224
Majiamama	60	No system										1228
Mogibissie	220	No system										1222
Motimor	40	No system										1223
Njabomie	68	No system										1225
Sembbehun	240	hand dug well	2004	Care		not finished						- 1221
Yakagi	20	No system										1227
<u>Nvaiwa</u>												
Barlu	30	No system										1213
Dambu	80	No system										1216
Gbandi	250	1/2 - bore hole	2006	Care		dry 4 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1205
	200	2/2 - hand dug well	2000	<i>Korean Group</i>		dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1206
Katumahun	180	1/2 - hand dug well	2003	<i>Bo Pujehun</i>		dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1207
	60	2/2 - hand dug well	2009	<i>Korean Group</i>		dry 10 months/year	IN - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1208
Malambi	21	No system										1215
Molendeh	120	1/2 - hand dug well	2009	<i>Bo Pujehun</i>		dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1210
	200	2/2 - hand dug well	1998	<i>Bo Pujehun</i>		dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1211
Ngagama	75	No system										1212
Palaiwahun Ngeyah	110	No system										1217
Pujehun	150	hand dug well	2009	<i>Korean Group</i>		dry 4 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1209
Sembeck	34	No system										1214

Gbo (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
---------	---------	--------------------	-------------	------	---------	------------	-----------	---------------	-----------------	------------------	-----------------	------

3 sections 39 villages - 27 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Gbo - summary / 12 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	5	894	0	0 (0%)	5	2 (40%)	1 (20%)	2 (40%)	2 (40%)
hand dug well	21	3 644	3	2 (9,5%)	18	14 (78%)	5 (24%)	11 (52%)	2 (10%)
	26	4 538	3	2 (7,7%)	23	16 (70%)	6 (23%)	13 (50%)	4 (15%)

Jaima Bongor (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Lower Baimba</u>												
	Bendu	466	1/3 - bore hole	1982	Bo Pujehun	working	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 238
			2/3 - bore hole	1982	Bo Pujehun	working	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 239
			3/3 - hand dug well	2008	Bo District Council	not finished						240
	Buma	600	hand dug well	1996	ACF	dry 8 months/year	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 243
	Kandor	750	1/2 - hand dug well	1993	Bo Pujehun	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 241
			2/2 - hand dug well	1993	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 242
	Kpekuma	300	1/2 - bore hole	1988	OTHER	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 236
			2/2 - hand dug well	2010	OTHER	dry 3 months/year	OTHER	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 237
	Mano	150	No system									244
<u>Lower Kama</u>												
	Jorbohun	1500	1/2 - hand dug well	2008	SALWACO	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 216
			2/2 - hand dug well	2010	SALWACO	dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 217
	Koribondo	100	1/10 - bore hole	2009	Korean Group	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 218
			10/10 - hand dug we	2010	Bo District Council	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 227
			2/10 - bore hole	2009	Korean Group	dry 12 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 219
			3/10 - bore hole	2009	Korean Group	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 220
			4/10 - bore hole	2009	Korean Group	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 221
			5/10 - bore hole	1986	Korean Group	pump broken	OTHER - stolen	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 222
			6/10 - hand dug well	2008	Bo Pujehun	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 223
			7/10 - hand dug well	1986	Bo Pujehun	pump broken	OTHER - stolen	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 224
			8/10 - bore hole	1986	Bo Pujehun	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 225
			9/10 - bore hole	2010	Bo District Council	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 226
	Kpetema	600	1/2 - bore hole	1980	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 212
			2/2 - hand dug well	2010	Bo Pujehun	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 214
	Lungi	600	hand dug well	2001	Care	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 228
	N'gbaigama	400	bore hole	1992	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 215
<u>Lower Nyiwa</u>												
	Folawa	800	bore hole	1988	Bo Pujehun	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 252
	Folur	300	hand dug well	2010	Roman Catholic	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 247

Jaima Bongor (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Lower Nyiwa</u>												
	Foyama	100	No system									254
	Kannba	120	No system									253
	Kponima1	400	bore hole	1986	Bo Pujehun	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 250
	Lagar	500	bore hole	1987	Bo Pujehun	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 251
	Mano	400	1/2 - hand dug well	2010	OTHER	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 245
			2/2 - bore hole	1980	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 246
	Soguman	77	1/2 - bore hole	1987	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 248
			2/2 - hand dug well	2010	Roman Catholic	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 249
<u>Nepondo</u>												
	Lowama	200	1/3 - hand dug well	2010	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 260
			2/3 - bore hole	1986	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 261
			3/3 - hand dug well	2010	Roman Catholic	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 262
	Madina	100	1/2 - bore hole	1981	OTHER	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 256
			2/2 - hand dug well	2010	L D S Charities	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 257
	Ngobeu	200	1/2 - bore hole	1981	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 258
			2/2 - hand dug well	2010	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 259
	Yiabama	500	bore hole	1982	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 255
<u>Tonguwa</u>												
	Gbama	750	1/4 - bore hole	1985	Bo Pujehun	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 271
			2/4 - bore hole	1986	Bo Pujehun	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 272
			3/4 - bore hole	1982	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 273
			4/4 - hand dug well	2010	OTHER	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 274
	Heigbama	350	1/2 - bore hole	1990	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 275
			2/2 - hand dug well	2010	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 276
	Kponima	1000	bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 277
	Maboma	666	1/6 - bore hole	1980	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 278
			2/6 - bore hole	1985	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 279
			3/6 - bore hole	1990	Bo Pujehun	pump broken	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 280
			4/6 - bore hole	1987	Bo Pujehun	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 281

Jaima Bongor (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Tonguwa												
	Maboma	666	5/6 - bore hole	1986	Bo Pujehun	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			6/6 - hand dug well	2006	OTHER	pump broken	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Nagbana	400	bore hole	1980	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Yiama	500	No system									284
Upper Baimba												
	Baomahun	114	1/7 - hand dug well	2010	OTHER	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/7 - pulley	2005	Bo District Council	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			3/7 - pulley	2005	Bo District Council	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			4/7 - hand dug well	2006	Bo Pujehun	working	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK
			5/7 - pulley	2007	OTHER	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			6/7 - hand dug well	2010	Bo District Council	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			7/7 - bore hole	1985	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK
	Gagama	350	hand dug well	2010	Bo District Council	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Kpoyama	150	No system									213
	Sulehun	200	1/3 - hand dug well	2009	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			2/3 - bore hole	1987	Bo Pujehun	working	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			3/3 - hand dug well	2009	OTHER	dry 4 months/year	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Telu	416	1/6 - hand dug well	2010	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			2/6 - bore hole	1987	Bo Pujehun	working	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK
			3/6 - bore hole	1987	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK
			4/6 - bore hole	1987	Bo Pujehun	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			5/6 - hand dug well	2006	Other	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working
			6/6 - bore hole	1987	Bo Pujehun	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
Upper Kama												
	Mende Kelema	286	1/3 - bore hole	1986	Bo Pujehun	dry 5 months/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/3 - bore hole	1986	Bo Pujehun	dry 6 months/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working
			3/3 - hand dug well	2009	Bo District Council	not finished						-
	Mile 30	300	hand dug well	2010	Roman Catholic	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	N'dombu	550	bore hole	1986	Bo Pujehun	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal

Jaima Bongor (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Upper Kama</u>												
	N'godie	310	bore hole	1986	Bo Pujehun	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 233
	Walihun	3000	bore hole	1986	Bo Pujehun	dry 7 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 229
<u>Upper Nyiawa</u>												
	Galleuhun	400	No system									268
	Gbuehun	500	No system									267
	Junehun	500	No system									269
	Nyanahun	500	bore hole	1991	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 264
	Pelewahun	200	bore hole	1984	Bo Pujehun	dry 1 month/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 263
	Samie	600	hand dug well	2007	World Vision	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 265
	Yeldema	200	hand dug well	2009	Other	dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 266

8 sections 45 villages - 8 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee: presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Jaima Bongor - summary / 37 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	45	20 549	0	23 (51,1%)	43	32 (74%)	5 (11%)	5 (11%)	35 (78%)
hand dug well	34	13 919	2	15 (44,1%)	31	27 (87%)	4 (12%)	9 (26%)	19 (56%)
	79	34 468	2	38 (48,1%)	74	59 (80%)	9 (11%)	14 (18%)	54 (68%)

Kakua (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Koieh</u>												
	Fallu	400	1/2 - bore hole	2010	<i>Bo District Council</i>	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			2/2 - bore hole	1988	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	869
	Kailia	300	bore hole	1988	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	871
	Njaluahun	155	hand dug well	2009	<i>ACTION AID</i>	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	870
<u>Kpandabu</u>												
	Ganahun	340	bore hole	1985	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	885
	Kpatama	592	bore hole	1985	<i>Bo Pujehun</i>	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	883
	Kpetema	387	1/2 - bore hole	2008	<i>Korean Group</i>	not finished					-	886
			2/2 - hand dug well	2010	<i>L D S Charities</i>	dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	887
	Mahuama	840	bore hole	1983	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	884
<u>Nquabu</u>												
	Biomah	253	hand dug well	2000	<i>CARITAS</i>	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	879
	Falawhun	375	1/3 - hand dug well	1984	<i>Bo Pujehun</i>	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	880
			2/3 - hand dug well	1984	<i>Bo Pujehun</i>	not finished					-	881
			3/3 - bore hole	2000	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	882
<u>Nyallay</u>												
	Bandajuma	624	1/3 - hand dug well	2009	<i>L D S Charities</i>	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	895
			2/3 - hand dug well	1998	<i>ACTION AID</i>	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	896
			3/3 - hand dug well	2001	<i>CARITAS</i>	not finished					-	897
	Bevehun	845	1/2 - bore hole	2010	<i>Bo Pujehun</i>	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	888
			2/2 - pulley	2009	<i>OTHER</i>	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Jandama	1200	1/2 - bore hole	1989	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	890
			2/2 - bore hole	1989	<i>Bo Pujehun</i>	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Nyandehun	2988	1/3 - bore hole	1988	<i>Bo Pujehun</i>	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			2/3 - bore hole	1988	<i>Bo Pujehun</i>	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	893
			3/3 - bore hole	2010	<i>Korean Group</i>	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	894
<u>Nyawa</u>												
	Fenghun	480	1/3 - hand dug well	2007	<i>CARITAS</i>	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			2/3 - bore hole	1988	<i>Bo Pujehun</i>	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working

Kakua (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Nyawa												
	Fenghun	480	3/3 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 876
	Gbumgbeh	517	1/2 - hand dug well	2009	ACTION AID	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 877
			2/2 - hand dug well	2010	ACTION AID	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 878
Samami												
	Bongoma	317	1/5 - hand dug well	2009	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 857
			2/5 - bore hole	2009	SALWACO	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 858
			3/5 - hand dug well	2006	ACTION AID	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 859
			4/5 - hand dug well	2007	ACTION AID	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 860
			5/5 - pulley	2003	Bo Pujehun	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 861
	Fallah	200	bore hole	2009	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 855
	Juama	200	bore hole	2007	NACSA	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 854
	Kebbie Town	900	hand dug well	2007	L D S Charities	dry 4 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 853
	Massan	102	bore hole	2009	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 856
Samami Guabu												
	Bahoma	250	hand dug well	2004	UNICEF	dry 3 months/year	OTHER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 910
	Biaima	200	bore hole	2009	Korean Group	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 903
	Borbu	350	hand dug well	1993	GTZ	dry 1 month/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 900
	Clinic	1000	hand dug well	2008	L D S Charities	dry 1 month/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 899
	Fulawahun	200	1/3 - hand dug well	2002	UNICEF	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 911
		300	2/3 - bore hole	2004	GTZ	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 912
		100	3/3 - hand dug well	2007	ACTION AID	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 913
	Gbanahun	500	bore hole	1987	Bo Pujehun	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 909
	Kpaitayma	300	1/2 - hand dug well	2010	L D S Charities	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 907
		200	2/2 - bore hole	2009	Korean Group	not finished						- 908
	Kpanguma	600	1/2 - bore hole	1990	Bo Pujehun	pump broken	K - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 901
		300	2/2 - hand dug well	2009	SABABU	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 902
	Kpanguma Road	500	hand dug well	2008	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 898
	Manjama	500	hand dug well	2010	L D S Charities	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 906
	Manjama Clinic	300	hand dug well	1990	Korean Group	dry 1 month/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 905

Kakua (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.																																													
<u>Samami Guabu</u>																																																									
	Pindegumahun	250	bore hole	2010	Korean Group	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK																																													
<u>Sewa</u>																																																									
	Dandabu	400	hand dug well	2003	ACTION AID	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working																																													
	Kanga	125	hand dug well	2010	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK																																													
	Kendeyama	178	1/2 - hand dug well	2010	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK																																													
		300	2/2 - hand dug well	2008	L D S Charities	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK																																													
	Kpawula	115	hand dug well	2010	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK																																													
	Nyagolihun	600	hand dug well	2008	L D S Charities	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working																																													
<u>Sindehun</u>																																																									
	Baoma Lungbebu	575	bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK																																													
	Sagohun	130	bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK																																													
<u>9 sections 39 villages - 0 with no system at all</u>																																																									
Caption: Not working: pump problem and/or no water all year long. Seasonal: provides water but not all year long (<=3months dry) Not finished: construction started but site not finished Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka Users Committee presence of a Committee of Users Pump CareTaker.: a person trained to maintain the pump Tools Spare Parts are available in the community Money contribution is done by the community for maintenance																																																									
Kakua - summary / 39 villages <table border="1"> <thead> <tr> <th rowspan="2">Type</th> <th rowspan="2">Total</th> <th rowspan="2">Popul. Approxim</th> <th rowspan="2">Not finished</th> <th rowspan="2">Functional all the year</th> <th colspan="2">P U M P</th> <th colspan="3">SEASONALITY</th> </tr> <tr> <th>installed</th> <th>working</th> <th>Dry>3m</th> <th>seasonal</th> <th>Alw. water</th> </tr> </thead> <tbody> <tr> <td>bore hole</td> <td>28</td> <td>20 377</td> <td>2</td> <td>21 (75%)</td> <td>26</td> <td>21 (81%)</td> <td>0 (0%)</td> <td>0 (0%)</td> <td>26 (93%)</td> </tr> <tr> <td>hand dug well</td> <td>31</td> <td>12 300</td> <td>2</td> <td>15 (48,4%)</td> <td>30</td> <td>23 (77%)</td> <td>3 (10%)</td> <td>9 (29%)</td> <td>17 (55%)</td> </tr> <tr> <td></td> <td>59</td> <td>32 677</td> <td>4</td> <td>36 (61%)</td> <td>56</td> <td>44 (79%)</td> <td>3 (5%)</td> <td>9 (15%)</td> <td>43 (73%)</td> </tr> </tbody> </table>													Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY			installed	working	Dry>3m	seasonal	Alw. water	bore hole	28	20 377	2	21 (75%)	26	21 (81%)	0 (0%)	0 (0%)	26 (93%)	hand dug well	31	12 300	2	15 (48,4%)	30	23 (77%)	3 (10%)	9 (29%)	17 (55%)		59	32 677	4	36 (61%)	56	44 (79%)	3 (5%)	9 (15%)	43 (73%)
Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY																																																		
					installed	working	Dry>3m	seasonal	Alw. water																																																
bore hole	28	20 377	2	21 (75%)	26	21 (81%)	0 (0%)	0 (0%)	26 (93%)																																																
hand dug well	31	12 300	2	15 (48,4%)	30	23 (77%)	3 (10%)	9 (29%)	17 (55%)																																																
	59	32 677	4	36 (61%)	56	44 (79%)	3 (5%)	9 (15%)	43 (73%)																																																

Komboya (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Kemoh</u>												
	Banyama	300	hand dug well	2010	German Agro Action	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1052
	Gbanama	40	No system									1058
	Gumahun	1000	1/2 - bore hole	1988	OTHER	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1053
		406	2/2 - hand dug well	2008	NACSA	dry 3 months/year	IN - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1054
	Kobodalla	300	No system									1059
	Korkortie	200	No system									1056
	Manyama	35	No system									1057
	Nyagohun 1	400	No system									1060
	Poyama	150	hand dug well	2010	German Agro Action	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1055
<u>Kensua</u>												
	Bendallu	500	No system									1051
	Bendu	170	hand dug well	2010	German Agro Action	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1041
	Fulawahun	80	No system									1047
	Garama	200	hand dug well	1998	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1044
	Gbeworbu	300	No system									1049
	Kenjama	45	No system									1048
	Komboya 2	379	hand dug well	2009	World Bank	not finished						- 1043
	Komboya Gbayi	326	hand dug well	2008	Bo District Council	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1042
	Ngiewabu	200	No system									1050
	Njawor	400	hand dug well	2010	German Agro Action	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1038
	Nyagohun	600	1/2 - bore hole	1992	Bo Pujehun	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1045
		500	2/2 - hand dug well	2009	NACSA	not finished						- 1046
	Semabu 2	400	hand dug well	2010	German Agro Action	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1040
	Yendehum	420	hand dug well	1992	Bo Pujehun	dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 1039
<u>Mangaru</u>												
	Banda Juma	100	No system									1029
	Baomahun	580	No system									1024
	Foindu	98	No system									1018

Komboya (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Mangaru</u>												
	Ketuma	210	No system									1019
	Kpamanjama	350	No system									1017
	Kpawuma	300	No system									1026
	Lorgbama	100	No system									1021
	Majeibu	300	No system									1022
	Nduga	550	No system									1020
	Ngulubu	55	No system									1023
	Norgoba	150	No system									1028
	Segbehun	220	No system									1027
	Songaru	250	hand dug well	2010	German Agro Action	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Yengema	200	No system									1025
<u>Sei</u>												
	Fuya	100	No system									1015
	Gbitima	40	hand dug well	2009	German Agro Action	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Njala	600	1/5 - hand dug well	2009	NACSA	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/5 - bore hole	1990	OTHER	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK
			3/5 - bore hole	1990	OTHER	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK
			4/5 - bore hole	1990	OTHER	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK
			5/5 - hand dug well	2009	Other	dry 2 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Pelewahun1	200	hand dug well	2010	German Agro Action	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Semabu 1	300	No system									1014
	Talia 1	120	No system									1013
<u>Tongorwa</u>												
	Baayah	500	No system									1034
	Kenyema	125	No system									1037
	Lorwuma	300	No system									1033
	Mano	250	No system									1035
	Ngekohun	150	hand dug well	2010	German Agro Action	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK

Komboya (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Tongorwa</u>												
	Pelewahun2	600	hand dug well	2010	German Agro Action	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1031
	Tallia	225	No system									1036
	Teibar	500	hand dug well	2010	German Agro Action	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1030

5 sections 49 villages - 31 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Komboya - summary / 18 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	5	3 400	0	5 (100%)	5	5 (100%)	0 (0%)	0 (0%)	5 (100%)
hand dug well	19	6 591	2	10 (52,6%)	17	14 (82%)	0 (0%)	5 (26%)	12 (63%)
	24	9 991	2	15 (62,5%)	22	19 (86%)	0 (0%)	5 (21%)	17 (71%)

Lugbu (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Gao</u>												
	Bondayilahun	100	No system									971
	Bontiwo	600	1/4 - hand dug well	2007	<i>World Vision</i>	dry 5 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/4 - bore hole	1988	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			3/4 - hand dug well	2008	<i>SALWACO</i>	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
			4/4 - hand dug well	2007	<i>ACTION AID</i>	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Daama	145	hand dug well	2006	<i>World Vision</i>	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Faama	500	bore hole	1989	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Kitorma	110	hand dug well	2007	<i>World Vision</i>	dry 2 months/year	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Kpatobu	230	hand dug well	2001	<i>OTHER</i>	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK
		1000	1/3 - hand dug well	2006	<i>ACTION AID</i>	dry 5 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working
			3/3 - hand dug well	2006	<i>ACTION AID</i>	dry 3 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Kpatubo	1000	2/3 - bore hole	1982	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Kuadima	500	1/3 - hand dug well	2005	<i>ACTION AID</i>	dry 6 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			2/3 - hand dug well	2009	<i>SALWACO</i>	dry 1 month/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
			3/3 - bore hole	1989	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Upper Sama	200	pulley	2003	<i>Bo Pujehun</i>	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
		500	1/5 - bore hole	1986	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			2/5 - hand dug well	2008	<i>World Bank</i>	not finished						-
			3/5 - bore hole	1986	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			4/5 - bore hole	1984	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			5/5 - bore hole	1984	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK

Kaqbevu

Baioma	230	No system										947
Bamba	550	bore hole	1990	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK	938
Bethy	125	No system										950
Gola	150	hand dug well	2008	<i>World Vision</i>	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	942
Komende	204	hand dug well	2008	<i>World Vision</i>	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal	946
Lower Sama	200	1/4 - bore hole	1976	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK	934
		2/4 - bore hole	1976	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK	935

Lugbu (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Kaqbevu												
	Lower Sama	200	3/4 - hand dug well	2006	<i>World Vision</i>	dry 4 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			4/4 - hand dug well	2008	<i>SALWACO</i>	not finished						936
	Moforay	250	hand dug well	2008	<i>World Vision</i>	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Mogbongbon	250	hand dug well	2008	<i>World Vision</i>	dry 3 months/year	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working
	Mokobo	120	No system									949
	Mokondo	170	hand dug well	2007	<i>World Vision</i>	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Momando	150	No system									948
	Mosorgbo	240	hand dug well	2010	<i>World Vision</i>	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Ngainga	200	bore hole	1989	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Sumbuya	500	hand dug well	2010	<i>OTHER</i>	working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
		400	hand dug well	2008	<i>World Vision</i>	dry 1 month/year	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
		2400	1/5 - hand dug well	2008	<i>World Vision</i>	dry 4 months/year	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			2/5 - hand dug well	2000	<i>NACSA</i>	dry 6 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			3/5 - bore hole	1976	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			4/5 - hand dug well	2003	<i>World Vision</i>	dry 5 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			5/5 - bore hole	1976	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Sumbuya SSS	660	hand dug well	2008	<i>World Vision</i>	dry 3 months/year	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Tawamahehun	200	hand dug well	2010	<i>World Vision</i>	dry 2 months/year	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Tawamahehun1	300	bore hole	1988	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK

Kamba

Buma	350	hand dug well	2007	<i>World Vision</i>	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	924
Feiba	1600	1/3 - bore hole	1980	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK	921
		2/3 - hand dug well	1980	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK	922
		3/3 - hand dug well	2007	<i>SALWACO</i>	not finished						-	923
Gendayma	300	hand dug well	2008	<i>SALWACO</i>	not finished						-	919
Tonguay	200	bore hole	1978	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK	920
Yambama	3000	hand dug well	2005	<i>OTHER</i>	dry 5 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	918
		1/4 - pulley	NA	<i>World Vision</i>	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	914
		2/4 - hand dug well	2008	<i>SALWACO</i>	not finished						-	915

Lugbu (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Kamba</u>												
	Yambama	3000	3/4 - bore hole	1980	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			4/4 - bore hole	1980	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
<u>Kemoh</u>												
	Benduma	600	hand dug well	2005	World Vision	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Gbalohun	100	No system									982
	Kpumbu	150	hand dug well	2010	World Vision	not finished						-
	Manowo	185	1/2 - hand dug well	2008	OTHER	not finished						979
			2/2 - hand dug well	NA	OTHER	not finished						980
	Ngeluhun	400	1/3 - bore hole	1986	Bo Pujehun	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			2/3 - bore hole	1986	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			3/3 - hand dug well	2008	World Vision	not finished						-
	Ngiehun	800	1/3 - hand dug well	2009	World Vision	dry 3 months/year	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			2/3 - bore hole	1989	Bo Pujehun	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			3/3 - hand dug well	2008	World Vision	dry 3 months/year	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal
<u>Magbo</u>												
	Benduma Sewa	150	hand dug well	2007	World Vision	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Hiima	800	1/2 - bore hole	1986	Bo Pujehun	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
		500	2/2 - hand dug well	2007	World Vision	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Karley	700	1/5 - hand dug well	1982	Bo Pujehun	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
		300	2/5 - bore hole	1986	Bo Pujehun	dry 1 month/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
		100	3/5 - hand dug well	2007	OTHER	not finished						-
		75	4/5 - hand dug well	2010	NACSA	dry 12 months/year	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
		110	6/6 - hand dug well	2005	SABABU	not finished						-
	Kpatema	200	hand dug well	2009	World Vision	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Tongay	110	No system									1005
	Venima	101	No system									1004
<u>Yorma</u>												
	Bangerma	500	1/2 - hand dug well	2009	World Vision	not finished						-
		200	2/2 - bore hole	1987	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK

Lugbu (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Yorma												
	Bevehun	150	hand dug well	2007	<i>World Vision</i>	dry 6 months/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 985
	Gondama	115	1/2 - hand dug well	1980	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 992
		65	2/2 - hand dug well	2005	<i>World Vision</i>	dry 4 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 993
	Kpetewoma	250	1/6 - bore hole	1989	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 986
		165	2/6 - bore hole	1989	<i>Bo Pujehun</i>	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 987
		110	3/6 - hand dug well	1999	<i>Oxfam</i>	working	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 988
		100	4/6 - hand dug well	2009	<i>SABABU</i>	working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 989
		64	5/6 - bore hole	1989	<i>Bo Pujehun</i>	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 990
		82	6/6 - hand dug well	2009	<i>NACSA</i>	pump broken	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 991
	Kpowubu	106	No system									994

6 sections 48 villages - 9 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee: presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts: are available in the community

Money contribution: is done by the community for maintenance

Lugbu - summary / 39 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	28	22 029	0	24 (85,7%)	27	26 (96%)	0 (0%)	2 (7%)	26 (93%)
hand dug well	53	32 336	12	6 (11,3%)	40	32 (80%)	14 (26%)	20 (38%)	7 (13%)
	81	54 365	12	30 (37%)	67	58 (87%)	14 (17%)	22 (27%)	33 (41%)

Naiwa Lenga (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Baimba												
	Banda	100	hand dug well	2009	Gosl	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1278
	Benduma	300	hand dug well	2010	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1273
	Korbu	145	1/4 - hand dug well	2009	NACSA	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1274
			2/4 - hand dug well	2006	Islamic Development Bank	dry 4 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1275
			3/4 - hand dug well	2006	Islamic Development Bank	dry 4 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1276
			4/4 - hand dug well	2010	Gosl	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1277
	Kortu	250	hand dug well	2009	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1272
	Kpangbama	70	No system									1282
	Kpendembu	500	hand dug well	2000	Islamic Development Bank	dry 4 months/year	IN - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1280
	Mamboma	40	No system									1281
	Njagbema	133	1/3 - hand dug well	2009	SALWACO	dry 2 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1269
			2/3 - hand dug well	2006	Islamic Development Bank	not finished						1270
			3/3 - hand dug well	2006	Islamic Development Bank	dry 4 months/year	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1271
	Somu	100	No system									1283
	Torkpobu	500	hand dug well	2002	Islamic Development Bank	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1279
	Yallu	200	No system									1284
Lower Naiwa												
	Gbwandoma	200	No system									1266
	Konima	150	hand dug well	2003	Islamic Development Bank	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1258
	Korlehun	10	No system									1268
	Luawa	86	No system									1267
	Mbellu	450	hand dug well	2010	Gosl	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1257
	Mblama	380	bore hole	1986	Bo Pujehun	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1254
	Ngiehun	400	hand dug well	2010	Gosl	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1253
	Nyandeyama	456	bore hole	1986	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1256
	Tondonya	600	bore hole	1986	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1255
	Wengbema	307	1/7 - hand dug well	2009	Gosl	not finished						1259
			2/7 - hand dug well	2006	Islamic Development Bank	pump broken	IN - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1260

Naiwa Lenga (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
<u>Lower Naiwa</u>													
	Wengbema	307	3/7 - hand dug well	2005	NACSA	pump broken	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1261
			4/7 - bore hole	1986	Bo Pujehun	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1262
			5/7 - bore hole	1986	Bo Pujehun	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1263
			6/7 - bore hole	1986	Bo Pujehun	dry 4 months/year	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1264
			7/7 - hand dug well	1986	Bo Pujehun	pump broken	K - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1265
<u>Upper Naiwa</u>													
	Bendu	250	hand dug well	2000	Islamic Development Bank	pump broken	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1249
	Kowa	450	hand dug well	2000	Islamic Development Bank	dry 3 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	1248
	Meima	400	hand dug well	2000	Islamic Development Bank	dry 1 month/year	PB2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	1251
	Ngogbebou	1500	No system										1252
	Saama	315	hand dug well	2000	Islamic Development Bank	dry 5 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1250
<u>Yelenga</u>													
	Heidibu	200	pulley	2004	Islamic Development Bank	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1244
	Kongobahun	125	1/2 - hand dug well	2009	SALWACO	working	OTHER	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1242
			2/2 - hand dug well	2000	Islamic Development Bank	dry 7 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1243
	Kpar	216	1/3 - hand dug well	2000	Islamic Development Bank	dry 6 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1239
			2/3 - hand dug well	2009	SALWACO	working	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1240
			3/3 - hand dug well	2000	Islamic Development Bank	dry 4 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1241
	Njaima	200	1/2 - hand dug well	2000	Islamic Development Bank	dry 5 months/year	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1229
			2/2 - bore hole	2007	SALWACO	not finished						-	1230
	Njakor	200	No system										1247
	Sahu	264	1/6 - hand dug well	2007	NACSA	dry 4 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1231
		325	2/6 - bore hole	1985	West Germany	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal	1232
		336	3/6 - bore hole	1985	West Germany	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working	1233
		320	4/6 - hand dug well	2010	SABABU	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1234
		324	5/6 - bore hole	1985	West Germany	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working	1235
		170	6/6 - pulley	2008	OTHER	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1236
	Semabu	500	hand dug well	2010	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1237
	Sourma	200	No system										1245

Naiwa Lenga (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Yelenqa</u>	Tamballu	500	hand dug well	2004	Islamic Development Bank	dry 7 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1238
	Tomkpombu	250	No system									1246

4 sections 36 villages - 11 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Naiwa Lenga - summary / 25 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	10	3 542	1	4 (40%)	9	8 (89%)	3 (30%)	1 (10%)	5 (50%)
hand dug well	33	8 954	2	7 (21,2%)	32	24 (75%)	13 (39%)	6 (18%)	12 (36%)
	43	12 496	3	11 (25,6%)	41	32 (78%)	16 (37%)	7 (16%)	17 (40%)

Selenga (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Kaduawo												
	Bowo	95	No system									1136
	Bunkelya	90	No system									1138
	Gbaneba3	400	hand dug well	2006	NACSA	dry 11 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Gbangba	200	1/2 - bore hole	1985	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
		150	2/2 - hand dug well	2000	Islamic Development Bank	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Gbangba4	100	No system									1135
	Kaneya	100	No system									1133
	Segbema	100	1/2 - hand dug well	2000	Islamic Development Bank	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
		300	2/2 - hand dug well	2000	Islamic Development Bank	pump broken	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Sembbehun	120	No system									1134
	Whuwema	80	No system									1137
Mokpendeh												
	Damballa	250	1/6 - bore hole	1985	FABRA	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
		120	2/6 - hand dug well	2000	Islamic Development Bank	dry 2 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
		200	3/6 - hand dug well	2000	Islamic Development Bank	dry 3 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
		250	4/6 - bore hole	1985	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
		500	5/6 - bore hole	NA	OTHER	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
		200	6/6 - hand dug well	2000	Other	pump broken	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Damballa 17	280	No system									1154
	Gbeyahun	100	hand dug well	2003	Islamic Development Bank	dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Gbeyahun 2	270	No system									1153
	Gbumbeh	150	1/3 - hand dug well	2003	Islamic Development Bank	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
		200	2/3 - bore hole	1994	OTHER	working	k	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
		250	3/3 - hand dug well	2003	Islamic Development Bank	not finished						-
	Kenema Town 1	260	No system									1152
	Kpetema1	100	hand dug well	1999	Islamic Development Bank	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Njaiyama	250	bore hole	2010	SALWACO	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Tabama	150	hand dug well	1999	Islamic Development Bank	dry 2 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working

Selenga (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Tawovahun												
	Damballa 10	300	hand dug well	NA	<i>Islamic Development Bank</i>	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1158
	Damballa 11	500	bore hole	NA	OTHER	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1159
	Damballa 16	700	No system									1173
	Damballa 7	350	bore hole	2010	Korean Group	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1155
	Damballa 8	150	hand dug well	2004	<i>Islamic Development Bank</i>	dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1156
	Damballa 9	150	bore hole	NA	OTHER	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 1157
	Damballa12	260	No system									1170
	Damballa13	340	No system									1171
	Damballa14	200	No system									1500
	Damballa15	750	No system									1172
	Gbangema	150	hand dug well	1999	<i>Islamic Development Bank</i>	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1169
	Grima	100	hand dug well	1999	<i>Islamic Development Bank</i>	not finished					-	1168
	Julu Town 1	200	No system									1174
	Kassema	200	1/3 - hand dug well	1999	<i>Islamic Development Bank</i>	dry 4 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1165
			2/3 - hand dug well	1999	<i>Islamic Development Bank</i>	dry 4 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1166
		150	3/3 - hand dug well	2009	SALWACO	not finished					-	1167
	Korwama 1	100	hand dug well	NA	<i>Islamic Development Bank</i>	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1163
	Maboima 1	70	hand dug well	2000	<i>Islamic Development Bank</i>	dry 4 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1164
	Mobondeh 1	240	No system									1175
	Njaluhua 1	150	bore hole	2010	Korean Group	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1162
	Sebehun	200	1/2 - bore hole	1984	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1160
		250	2/2 - hand dug well	2010	Other	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1161

Selenga (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
---------	---------	--------------------	-------------	------	---------	------------	-----------	---------------	-----------------	------------------	-----------------	------

3 sections 37 villages - 16 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Selenga - summary / 21 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	11	3 000	0	9 (81,8%)	11	9 (82%)	0 (0%)	0 (0%)	11 (100%)
hand dug well	22	3 890	3	3 (13,6%)	19	11 (58%)	4 (18%)	10 (45%)	5 (23%)
	33	6 890	3	12 (36,4%)	30	20 (67%)	4 (12%)	10 (30%)	16 (48%)

Tikonko (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Mabawa</u>												
	Buwaima	100	No system									420
	Kassama	325	1/2 - bore hole	1986	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			2/2 - bore hole	1986	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	412
	Ngalla	150	No system									422
	Nigeria	50	No system									421
	Pujehun	50	No system									419
	Sebaru	70	No system									418
	Tebobu	120	No system									417
	Woterhun	300	hand dug well	1987	Bo Pujehun	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Yengess	1000	1/2 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			2/2 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	415
												416
<u>Mattru Njolane</u>												
	Mattru	333	bore hole	1990	UNDP	dry 4 months/year	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			1/5 - hand dug well	2004	NACSA	dry 8 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/5 - bore hole	1991	FABRA	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			3/5 - bore hole	1991	FABRA	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			4/5 - pulley	1994	OTHER	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			5/5 - hand dug well	2008	OTHER	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Njabla	230	hand dug well	2008	OTHER	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
<u>Mbainyawa</u>												
	Grima	300	1/5 - hand dug well	2008	OTHER	not finished						-
			2/5 - hand dug well	2008	OTHER	pump broken	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			3/5 - hand dug well	2003	Gosl	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			4/5 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			5/5 - hand dug well	2010	OTHER	dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Niagbema	300	1/2 - hand dug well	2010	OTHER	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			2/2 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Tikonko Wo	130	No system									430

Moku

Tikonko (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Moku												
	Adala	300	No system									403
	Bawoma Moku	550	bore hole	1992	FABRA	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 401
	Manor Bembemte	300	No system									404
	Segema	150	No system									405
	Sembehun Tabeh	600	bore hole	1992	FABRA	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 400
	Tikonko Bevehun	350	hand dug well	2009	World Vision	pump broken	K - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 402
Njabela One												
	Golahun	500	1/3 - bore hole	1987	FABRA	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 406
			2/3 - bore hole	1987	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 407
			3/3 - hand dug well	2009	World Vision	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 408
	Mokunda	300	hand dug well	1999	OTHER	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 409
	Ngalehun	385	No system									411
	Tanenehun	300	No system									410
Njabela Two												
	Bawoma	60	bore hole	1989	FABRA	pump broken	K - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 391
	Feilor	137	1/4 - bore hole	1990	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 396
			2/4 - hand dug well	2008	ACTION AID	dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 397
			3/4 - hand dug well	2009	SALWACO	not finished						- 398
			4/4 - hand dug well	2007	ACTION AID	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 399
	Magbema	137	1/4 - bore hole	1989	FABRA	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 387
			2/4 - pulley	2007	German Agro Action	dry 3 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 388
			3/4 - bore hole	2007	Korean Group	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 389
			4/4 - bore hole	1989	FABRA	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 390
	Magihun	305	1/2 - hand dug well	2007	ACTION AID	dry 2 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 394
			2/2 - bore hole	1989	FABRA	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 395
	Ngadorhun	300	1/2 - hand dug well	2009	ACTION AID	pump broken	K - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 392
			2/2 - bore hole	1990	FABRA	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 393
	Ngodama	411	1/9 - bore hole	1989	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 378
			2/9 - hand dug well	2008	CARITAS	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 379

Tikonko (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
Njaba Two													
	Ngodama	411	3/9 - hand dug well	2010	NACSA	not finished					-	380	
			4/9 - hand dug well	2008	CARITAS	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	381
			5/9 - bore hole	1989	FABRA	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	382
			6/9 - hand dug well	2007	ACTION AID	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	383
			7/9 - hand dug well	2010	ACTION AID	dry 4 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	384
			8/9 - bore hole	1989	FABRA	pump broken	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	385
			9/9 - hand dug well	1994	ACF	dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	386
Seiwa													
	Ballie	500	No system									1495	
	Bawama	80	No system									1498	
	Borbabu	150	hand dug well	2008	World Vision	not finished					-	328	
	Dodo	66	1/3 - bore hole	1988	FABRA	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	318
			2/3 - hand dug well	2002	Other	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	319
			3/3 - hand dug well	2008	World Vision	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	320
	Gawuha	150	1/4 - bore hole	2007	OTHER	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working	321
			2/4 - hand dug well	2001	UNICEF	not finished						-	322
			3/4 - hand dug well	2003	ACTION AID	not finished						-	323
			4/4 - hand dug well	2010	CARITAS	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK	324
	Gbalehun	400	1/2 - hand dug well	2008	World Vision	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	312
			2/2 - bore hole	1991	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	313
	Gbanahun	70	No system									1497	
	Gbewabu	300	1/2 - bore hole	2008	OTHER	dry 6 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	337
			2/2 - hand dug well	2010	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	338
	Gendema	400	bore hole	1993	FABRA	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	307
	Julah	450	bore hole	1992	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK	317
	Kamdala	800	hand dug well	2010	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	339
	Kigbia	300	hand dug well	2006	OTHER	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	327
	Kokofolo	200	1/3 - bore hole	1991	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK	331
			2/3 - hand dug well	2010	CARITAS	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK	332

Tikonko (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Seiwa												
	Kokofolo	200	3/3 - hand dug well	2007	ACTION AID	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 333
	Kpetema	150	hand dug well	2008	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 326
	Lembama	200	hand dug well	2007	ACTION AID	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 329
		65	1/2 - bore hole	1987	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 285
			2/2 - hand dug well	2010	World Vision	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 286
	Ngelehum	125	1/4 - hand dug well	2005	ACF	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 348
			2/4 - hand dug well	2007	CARITAS	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 349
			3/4 - hand dug well	2006	ACF	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 350
			4/4 - bore hole	1989	FABRA	pump broken	K - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 351
	Ngibina	80	No system									1499
	Niama	300	hand dug well	2001	UNICEF	dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 325
	Njala	200	hand dug well	2008	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 340
	Njonboahun	125	1/2 - hand dug well	2010	SALWACO	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 341
			2/2 - hand dug well	2000	OTHER	dry 3 months/year	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 342
	Orviamu	100	No system									1494
	Pelewahun	125	1/2 - hand dug well	2008	World Vision	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 314
			2/2 - bore hole	1991	FABRA	working	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 315
	Potain	150	No system									1493
	Sami	133	1/3 - bore hole	2009	OTHER	pump broken	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 334
			2/3 - hand dug well	2010	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 335
			3/3 - hand dug well	2010	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 336
	Sembuhun	600	hand dug well	2009	CARITAS	dry 3 months/year	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 330
	Siame	350	1/2 - hand dug well	2002	OTHER	not finished						- 305
			2/2 - bore hole	1989	FABRA	dry 1 month/year	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 306
	Sugbehun	650	No system									1496
	Sunga	150	1/4 - hand dug well	2001	Care	dry 5 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 308
			2/4 - hand dug well	2000	World Vision	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 309
			3/4 - hand dug well	2010	Care	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 310
			4/4 - hand dug well	2009	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 311

Tikonko (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Seiwa												
	Taninihun	160	bore hole	1987	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 288
		170	hand dug well	2010	World Vision	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 289
	Tikonko	200	01/15 - pulley	2001	UNICEF	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 290
			02/15 - bore hole	2010	Korean Group	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 291
			03/15 - hand dug we	2009	World Vision	pump broken	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 292
			04/15 - bore hole	1989	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 293
			05/15 - hand dug we	2001	Oxfam	dry 4 months/year	IN - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 294
			06/15 - hand dug we	2009	World Vision	dry 2 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 295
			07/15 - hand dug we	2010	World Vision	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 296
			08/15 - bore hole	1989	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 297
			09/15 - bore hole	1989	FABRA	pump broken	K - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 298
			10/15 - hand dug we	2001	OTHER	working	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 299
			11/15 - bore hole	1989	FABRA	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 300
			12/15 - hand dug we	2009	World Vision	dry 1 month/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 301
			13/15 - bore hole	1989	FABRA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 302
			14/15 - hand dug we	2009	World Vision	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 303
			15/15 - hand dug we	2003	OTHER	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 304
	Towama	200	1/5 - hand dug well	2009	World Vision	dry 1 month/year	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 343
			2/5 - bore hole	1990	SALWACO	working	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 344
			3/5 - bore hole	1990	FABRA	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 345
			4/5 - hand dug well	2008	Other	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 346
			5/5 - hand dug well	2008	NACSA	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 347
	Vgangain	150	hand dug well	2000	World Vision	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 287
	Wubange	250	hand dug well	2008	SALWACO	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 316
Sendeh												
	Maboima	125	1/4 - bore hole	2009	Korean Group	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 374
			2/4 - bore hole	1989	Bo Pujehun	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 375
			3/4 - hand dug well	2007	ACTION AID	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 376
			4/4 - hand dug well	2007	ACTION AID	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 377

Tikonko (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Sendeh</u>												
Nyadeyama	166	1/3 - bore hole	1989	FABRA		dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 371
		2/3 - hand dug well	2009	SALWACO		dry 2 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 372
		3/3 - bore hole	1989	FABRA		working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 373
Sembbehun	125	1/4 - bore hole	1989	FABRA		working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 359
		2/4 - bore hole	2009	Korean Group		dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 360
		3/4 - bore hole	2009	Korean Group		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 361
		4/4 - hand dug well	2010	OTHER		working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 362
Sembbehun New	333	1/6 - hand dug well	2007	SALWACO		not finished					-	365
		2/6 - bore hole	1989	FABRA		working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 366
		3/6 - hand dug well	2001	FABRA		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 367
		4/6 - hand dug well	1989	FABRA		working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 368
		5/6 - bore hole	2009	Korean Group		working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 369
		6/6 - bore hole	2009	Korean Group		pump broken	K - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 370
Sembbehuntuba	350	1/2 - bore hole	1989	FABRA		working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 363
		2/2 - pulley	1999	UNICEF		dry 2 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 364

8 sections 68 villages - 19 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee: presence of a Committee of Users

Pump CareTaker: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Tikonko - summary / 49 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	55	15 675	0	36 (65,5%)	53	42 (79%)	4 (7%)	3 (5%)	48 (87%)
hand dug well	75	18 051	8	29 (38,7%)	67	47 (70%)	9 (12%)	17 (23%)	41 (55%)
	130	33 726	8	65 (50%)	120	89 (74%)	13 (10%)	20 (15%)	89 (68%)

Valunia (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Dei</u>												
Baomahun	833	1/6 - bore hole	1980	FABRA	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	556
		2/6 - pulley	2000	OTHER	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	557
		3/6 - bore hole	1980	FABRA	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	558
		4/6 - hand dug well	2010	NACSA	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	559
		5/6 - hand dug well	2010	NACSA	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	560
		6/6 - hand dug well	2010	NACSA	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	561
<u>Delenqa</u>												
Bumpeh	340	No system										564
Gbuuhun	120	No system										568
Hendegboma	25	No system										577
Kanjawo	200	No system										581
Kogonpa	450	No system										569
Konima		No system										575
Korwama	400	No system										572
Kpewama	350	No system										580
Lablama	480	No system										574
Mendekelema	380	No system										573
Moyorgbo	430	No system										566
Ngoijahun	210	No system										570
Njagbla	300	No system										576
Njagulem	450	No system										565
Nyandehun	200	No system										567
Palema	30	No system										579
Pateiya	37	No system										578
Pujehun Dei	560	No system										563
Semabu	120	No system										571
Sembekihun	370	No system										562
Sengema	100	No system										582

Valunia (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Kendebu												
	Gonyobu 1	72	No system									471
	Gonyobu 2	30	No system									472
	Koivama	85	No system									470
	Kpetema	15	No system									474
	Majendu	50	No system									467
	Masao	184	No system									466
	Nelebu	130	No system									469
	Njaluahun	30	No system									475
	Nyadehun	20	No system									473
	Nyanyahun	42	No system									468
	Sengima	550	1/2 - hand dug well	2009	SALWACO	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			2/2 - hand dug well	2000	<i>Islamic Development Bank</i>	working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
Lunia												
	Banjema	100	hand dug well	2000	<i>Islamic Development Bank</i>	pump broken	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Baoma 2	46	No system									539
	Barrie	80	hand dug well	2008	<i>Palewahun Rural Develop</i>	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Bauya	20	No system									508
	Belebu	25	No system									533
	Daru	420	No system									518
	Fulawahun	150	No system									528
	Gbekeya 1	200	No system									515
	Gbekeya 2	200	No system									516
	Gruna	125	1/4 - hand dug well	2008	<i>Islamic Development Bank</i>	dry 6 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/4 - hand dug well	2005	<i>Islamic Development Bank</i>	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			3/4 - hand dug well	2005	<i>Islamic Development Bank</i>	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			4/4 - hand dug well	2005	NACSA	working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Gumahun	250	1/2 - hand dug well	1994	<i>Islamic Development Bank</i>	dry 1 month/year	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/2 - hand dug well	1994	<i>Islamic Development Bank</i>	dry 1 month/year	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working

Valunia (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Lunia</u>												
	Jilehun	45	No system									512
	Jojohun	59	No system									529
	Kamanu	55	No system									542
	Kavoma	450	No system									531
	Konema 1	29	No system									521
	Konema 2	29	No system									522
	Konema Abdulai	27	No system									537
	Kortuhun	500	hand dug well	2008	Palewahun Rural Develop	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 494
	Koyeuma	175	1/2 - hand dug well	2005	OTHER	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 499
			2/2 - hand dug well	2004	OTHER	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 500
	Kpakinbu	500	hand dug well	2002	Islamic Development Bank	dry 1 month/year	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 486
	Kpassama	800	No system									526
	Kpetema	100	1/2 - hand dug well	1991	Islamic Development Bank	dry 6 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 477
			2/2 - hand dug well	2002	Palewahun Rural Develop	pump broken	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 478
	Lekpeyama	30	No system									510
	Levuma	25	No system									527
	Lomabo	120	hand dug well	1991	Islamic Development Bank	dry 6 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 476
	Luniagelema	350	No system									519
	Mangheru	266	1/6 - bore hole	2009	Korean Group	not finished						- 480
			2/6 - hand dug well	2007	Palewahun Rural Develop	working	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 481
			3/6 - hand dug well	2006	SALWACO	dry 5 months/year	IN - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 482
			4/6 - bore hole	1984	FABRA	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 483
			5/6 - bore hole	1984	FABRA	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 484
			6/6 - hand dug well	2007	OTHER	pump broken	IN - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 485
	Manjehun	50	No system									540
	Mayebema	25	No system									523
	Mbaoma	400	hand dug well	2002	Islamic Development Bank	dry 3 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 487
	Ngagboma	35	No system									514
	Ngolala	350	hand dug well	2001	Islamic Development Bank	pump broken	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 490

Valunia (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Lunia												
	Njala	80	hand dug well	2008	Palewahun Rural Develop	dry 1 month/year	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 507
	Njala Koyeima	38	No system									538
	Njalawo	35	No system									520
	Njogahun	35	No system									534
	Njopowahun	150	1/2 - hand dug well	2002	Palewahun Rural Develop	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 501
			2/2 - hand dug well	2001	NACSA	dry 1 month/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 502
	Njopowahun 2	60	No system									513
	Nyandehun Bunder	250	No system									541
	Nyandehun2	300	1/2 - hand dug well	2001	Palewahun Rural Develop	dry 5 months/year	IN - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 488
			2/2 - hand dug well	2002	Islamic Development Bank	dry 6 months/year	PB2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 489
	Nyayamo	69	No system									532
	Pelewahun	200	1/2 - bore hole	1982	Bo Pujehun	pump broken	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 497
			2/2 - hand dug well	2008	OTHER	dry 3 months/year	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 498
	Pelewahun2	150	hand dug well	2008	Palewahun Rural Develop	dry 6 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 491
	Sembekehun Fargouy	99	No system									525
	Tendabu	100	hand dug well	2008	Palewahun Rural Develop	dry 4 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 492
	Toiyama	28	No system									536
	Tongoma	82	No system									524
	Waterloo	40	No system									511
	Weijama	94	No system									530
	Wondeh	25	No system									535
	Yawama	500	No system									517
	Yourbu	40	No system									509
Ngovo												
	Balayhun	44	No system									463
	Boniyama	11	No system									462
	Gormbu	58	No system									461
	Kpowabu	185	1/3 - hand dug well	2004	Islamic Development Bank	dry 3 months/year	IN - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 455

Valunia (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Ngovo</u>												
	Kpowabu	185	2/3 - hand dug well	2004	<i>Islamic Development Bank</i>	dry 3 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 456
			3/3 - hand dug well	2009	SALWACO	dry 3 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 457
	Kpowabu J	237	hand dug well	2007	NACSA	working	OTHER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 458
	Njala	74	No system									460
	Yamandu	252	hand dug well	2000	<i>Islamic Development Bank</i>	dry 4 months/year	IN - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 459
<u>Sei</u>												
	Foya	700	hand dug well	2009	<i>Bo Pujehun</i>	dry 7 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 545
	Gbankama	200	bore hole	1980	FABRA	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 544
	Gbonjemo	40	No system									555
	Jalilihun	150	No system									547
	Jumah	60	No system									553
	Kpakimbu	100	No system									550
	Londoma	54	No system									552
	Mossele	250	No system									554
	Ngeima	250	bore hole	1982	FABRA	dry 2 months/year	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 543
	Ngibu	38	No system									548
	Niyahun	35	No system									549
	Senbhun	80	hand dug well	2006	<i>Palewahun Rural Develop</i>	dry 6 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 546
	Tomkpobu	50	No system									551
<u>Vangelu</u>												
	Kundorma	200	1/3 - hand dug well	1999	<i>Islamic Development Bank</i>	dry 3 months/year	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 434
			2/3 - hand dug well	1999	<i>Islamic Development Bank</i>	dry 12 months/year	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 435
			3/3 - hand dug well	2009	SALWACO	dry 2 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 436
	Mandu	450	hand dug well	2009	<i>Palewahun Rural Develop</i>	dry 1 month/year	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 437
	Yambama	300	1/3 - hand dug well	1987	<i>Bo Pujehun</i>	pump broken	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 431
			2/3 - bore hole	2010	Korean Group	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 432
			3/3 - hand dug well	2009	SALWACO	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 433
<u>Yalenga</u>												

Valunia (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Yalenga</u>												
	Dasalam	110	No system									447
Jalilo	216	1/3 - hand dug well	2008	SALWACO	not finished						-	440
		2/3 - hand dug well	2000	Islamic Development Bank	dry 3 months/year	IN - not working					Not Working	441
		3/3 - hand dug well	2000	Islamic Development Bank	dry 3 months/year	IN					Seasonal	442
K Blango	500	1/2 - hand dug well	1996	Islamic Development Bank	dry 3 months/year	PB2			<input checked="" type="checkbox"/>		Seasonal	443
		2/2 - hand dug well	2010	SALWACO	working	IM2		<input checked="" type="checkbox"/>			OK	444
Kortumahun	500	No system										449
Kpetema	25	No system										452
Magbema	110	No system										450
Mogbe	500	hand dug well	2009	Palewahun Rural Develop	dry 3 months/year	IN - not working					Not Working	446
Ngiyehun	106	No system										448
Ngorahun	800	hand dug well	2010	SALWACO	dry 5 months/year	IM2			<input checked="" type="checkbox"/>		Not Working	445
Njagbema	300	1/2 - hand dug well	2001	Islamic Development Bank	dry 3 months/year	IN		<input checked="" type="checkbox"/>			Seasonal	438
		2/2 - hand dug well	2001	Islamic Development Bank	dry 3 months/year	IN		<input checked="" type="checkbox"/>			Seasonal	439
Nyama	32	No system										453
Pembema	30	No system										451
Selu	220	No system										454

8 sections 122 villages - 87 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Valunia - summary / 35 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	9	3 414	1	5 (55,6%)	8	6 (75%)	0 (0%)	1 (11%)	7 (78%)
hand dug well	55	16 449	1	13 (23,6%)	54	35 (65%)	13 (24%)	22 (40%)	19 (35%)
	64	19 863	2	18 (28,1%)	62	41 (66%)	13 (20%)	23 (36%)	26 (41%)

Wonde (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Centre Kargoi</u>												
	Kambawama	800	hand dug well	2010	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1457
			1/3 - hand dug well	1985	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1455
			2/3 - hand dug well	2010	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1456
			3/3 - hand dug well	2010	ACTION AID	dry 6 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1458
	Kpuawala	450	hand dug well	2010	ACTION AID	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1459
	Yawatu	400	bore hole	1984	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1460
<u>Lower Korgoi</u>												
	Bathurst	100	1/3 - hand dug well	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1485
			2/3 - hand dug well	2002	NACSA	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1486
			3/3 - bore hole	2010	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1487
	Ngawla	175	1/2 - hand dug well	2004	ACTION AID	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1481
			2/2 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1482
	Niagorehun	325	1/2 - hand dug well	2006	NACSA	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1489
			2/2 - hand dug well	2008	ACTION AID	dry 7 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1490
	Njala	125	1/2 - hand dug well	2007	ACTION AID	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1491
			2/2 - hand dug well	2010	ACTION AID	dry 8 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1492
	Yarnihun	205	1/2 - bore hole	2004	SALWACO	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1483
			2/2 - hand dug well	2005	ACTION AID	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1484
<u>Manyeh</u>												
	Fanima	233	1/3 - hand dug well	2010	ACTION AID	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1474
			2/3 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1475
			3/3 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1476
	Fayama	208	hand dug well	2010	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1477
	Gbugema	120	hand dug well	2010	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1470
	Kegbema	240	hand dug well	2010	L D S Charities	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1480
	Konia	150	1/2 - hand dug well	2010	ACTION AID	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1471
			2/2 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1472
	Layiahun	250	bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1473
	Pelewahun	155	1/2 - hand dug well	2010	ACTION AID	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1478

Wonde (Bo)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Manyeh</u>												
	Pelewahun	155	2/2 - hand dug well	2004	ACTION AID	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1479
<u>Upper Kargo</u>												
	Dai	500	hand dug well	2008	ACTION AID	dry 6 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1468
	Gboyma	700	1/5 - bore hole	1987	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1461
			2/5 - bore hole	1987	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1462
			3/5 - bore hole	1987	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1463
			4/5 - hand dug well	2010	ACTION AID	dry 8 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1464
			5/5 - hand dug well	2010	ACTION AID	dry 8 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1465
	Vaama	400	hand dug well	2010	ACTION AID	dry 7 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1469
	Yengema	495	1/2 - bore hole	1988	Bo Pujehun	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1466
			2/2 - hand dug well	2010	ACTION AID	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1467

4 sections 19 villages - 0 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee: presence of a Committee of Users

Pump CareTaker: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Wonde - summary / 19 villages					P U M P		SEASONALITY		
Type	Total	Popul. Approxim	Not finished	Functional all the year	installed	working	Dry>3m	seasonal	Alw. water
bore hole	12	4 341	0	12 (100%)	12	12 (100%)	0 (0%)	0 (0%)	12 (100%)
hand dug well	25	9 186	0	14 (56%)	25	19 (76%)	8 (32%)	1 (4%)	16 (64%)
	37	13 527	0	26 (70,3%)	37	31 (84%)	8 (22%)	1 (3%)	28 (76%)

Dembellia Sinkunia (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Kumbulu</u>												
	Darasalam	100	No system									1157
	Foria	20	No system									1156
	Gbuliwel	50	No system									1159
	Kolimoria	15	No system									1155
	Koworya	25	No system									1160
	Kumbulu	80	hand dug well	2008	NACSA	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Sankan	60	No system									1158
	Soya	500	1/3 - pulley	2005	Care	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/3 - hand dug well	2007	NACSA	dry 2 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			3/3 - hand dug well	2005	NACSA	not finished						1154
<u>Manna</u>												
	Bantantia	39	No system									1112
	Capintaia	58	No system									1105
	Fatafin	88	No system									1102
	Gebeia	38	No system									1106
	Herikor	160	hand dug well	2002	Care	pump broken	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Jolloia	22	No system									1109
	Longorie	20	No system									1108
	Mabelie	50	No system									1103
	Manna	132	1/4 - hand dug well	2003	CCF	dry 1 month/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
			2/4 - hand dug well	2004	Care	dry 1 month/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			3/4 - hand dug well	2003	CCF	dry 1 month/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			4/4 - hand dug well	2003	Care	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Sogoria	100	1/2 - hand dug well	2004	Care	dry 2 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
			2/2 - hand dug well	2007	Care	dry 2 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Tallaia	21	No system									1107
	Tamaguaia	6	No system									1104
	Tamalan	30	No system									1110

Dembellia Sinkunia (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Manna</u>												
	Wusuia	60	No system									1111
	Yaedia	70	1/2 - hand dug well	2002	Care	dry 1 month/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1100
			2/2 - hand dug well	2003	UNICEF	dry 3 months/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1101
<u>Mawundia</u>												
	Badembaia	350	hand dug well	2005	NACSA	working	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1128
	Bontola	90	No system									1148
	Dalabaya	66	1/3 - pulley	2003	Care	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1135
			2/3 - pulley	2005	Care	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1136
			3/3 - pulley	2005	Care	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1137
	Fullamasa	1000	1/5 - hand dug well	2008	NACSA	working	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1129
			2/5 - hand dug well	2008	NACSA	not finished						1130
			3/5 - pulley	1990	NACSA	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1131
			4/5 - pulley	2000	Cause Canada	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1132
			5/5 - hand dug well	1996	UNDP	not finished						1133
	Gbindi Hafia	50	No system									1150
	Kumidakie	50	1/2 - pulley	2004	Care	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1143
			2/2 - pulley	2004	Care	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1144
	Lambaybun	200	No system									1146
	Lereya	40	No system									1149
	Njuria	500	hand dug well	2005	NACSA	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1145
	Sagalireh	70	1/5 - pulley	2003	Care	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1138
			2/5 - pulley	2003	Care	dry 4 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1139
			3/5 - pulley	2003	Care	dry 4 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1140
			4/5 - hand dug well	1990	Islamic Development Asso	dry 1 month/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1141
			5/5 - pulley	2009	NACSA	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1142
	Tangama	200	hand dug well	2007	Care	not finished						1134
	Yonkaya	250	No system									1147
<u>Numula</u>												
	Bontalla	45	No system									1127

Dembellia Sinkunia (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Numula</u>												
	Futunkor	70	No system									1122
	Gbindi	39	1/9 - hand dug well	2003	CCF	dry 1 month/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1113
			2/9 - hand dug well	2002	Islamic Development Asso	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1114
			3/9 - pulley	2004	Care	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1115
			4/9 - hand dug well	2005	Care	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1116
			5/9 - hand dug well	2008	NACSA	dry 3 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1117
			6/9 - hand dug well	2003	Care	dry 3 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1118
			7/9 - hand dug well	2004	Care	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1119
			8/9 - pulley	2004	Care	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1120
			9/9 - hand dug well	1978	UNDP	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 1121
	Koffin	62	No system									1123
	Koromadugu	25	No system									1125
	Malonkor	30	No system									1124
	Sankawa	52	No system									1126
<u>Sinkunia</u>												
	Bantantia	100	1/2 - hand dug well	2007	Cause Canada	dry 2 months/year	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 1175
			2/2 - hand dug well	2003	Cause Canada	not finished						- 1176
	Gbindi	444	1/9 - pulley	2004	Care	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1162
			2/9 - hand dug well	1978	UNDP	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 1163
			3/9 - pulley	2003	Care	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1164
			4/9 - hand dug well	2008	NACSA	dry 2 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1165
			5/9 - pulley	2004	Care	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1166
			6/9 - pulley	2004	Care	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1167
			7/9 - pulley	2004	Care	dry 1 month/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1168
			8/9 - pulley	2004	Care	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1169
			9/9 - pulley	2004	Care	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1170
	Gbindia	55	No system									1196
	Masende	85	hand dug well	2006	Care	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1161
	Messia	150	No system									1194

Dembellia Sinkunia (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
Sinkunia													
	Momie	30	No system									1192	
	Mondeya 1	98	No system									1191	
	Mondeya 2	350	No system									1193	
Sinkunia	Sinkuni	357	13/14 - hand dug we	2007	NACSA	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	1189
			14/14 - hand dug we	2007	NACSA	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	1190
Sinkunia	Sinkunia	357	1/14 - hand dug well	2006	Cause Canada	dry 2 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	1177
			10/14 - hand dug we	2006	NACSA	dry 2 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	1186
			11/14 - hand dug we	2007	CCF	dry 3 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	1187
			12/14 - hand dug we	1989	UNDP	dry 2 months/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1188
			2/14 - hand dug well	2006	World Bank	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	1178
			3/14 - hand dug well	2005	UNICEF	dry 3 months/year	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	1179
			4/14 - hand dug well	2006	World Bank	dry 3 months/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1180
			5/14 - hand dug well	2003	CCF	dry 2 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	1181
			6/14 - hand dug well	1989	UNDP	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1182
			7/14 - hand dug well	1990	OTHER	working	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1183
			8/14 - hand dug well	2007	NACSA	dry 2 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	1184
			9/14 - hand dug well	2005	UNICEF	dry 3 months/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1185
Soya	Soya	150	1/4 - hand dug well	2008	NACSA	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1171
			2/4 - hand dug well	2005	Care	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK	1172
			3/4 - pulley	2004	Care	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1173
			4/4 - hand dug well	2006	NACSA	dry 3 months/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1174
Soyadie		60	No system									1195	

5 sections 54 villages - 34 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Dembellia Sinkunia - summary / 20 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
hand dug well	48	13 122	5	9 (18,8%)	43	36 (84%)	0 (0%)	33 (69%)	10 (21%)
	48	13 122	5	9 (18,8%)	43	36 (84%)	0 (0%)	33 (69%)	10 (21%)

Diang (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Kadabie Feh												
	Gbogoroma	530	No system									140
	Igaia	396	No system									139
	Kamafimbo	350	hand dug well	2009	MDM	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Legenkoro	231	1/4 - hand dug well	1992	NACSA	working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			2/4 - hand dug well	2010	MDM	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			3/4 - hand dug well	2005	CRS	dry 1 month/year	PB2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			4/4 - hand dug well	2006	SABABU	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
Kondembaia												
	Bendukoro	143	1/4 - hand dug well	2004	NACSA	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/4 - hand dug well	1983	SALWACO	pump broken	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			3/4 - hand dug well	2010	MDM	working	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			4/4 - hand dug well	2010	MDM	working	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Fonema	250	No system									174
	Kapampafero	102	No system									176
	Kondembaia	1500	1/15 - hand dug well	1983	SALWACO	working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
		100	10/15 - hand dug we	2008	UNICEF	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			11/15 - hand dug we	2009	SALWACO	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			12/15 - hand dug we	2010	UNICEF	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			13/15 - hand dug we	2006	CARE	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			14/15 - hand dug we	2004	OTHER	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			15/15 - hand dug we	2008	SABABU	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/15 - hand dug well	2005	OTHER	working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			3/15 - hand dug well	1984	SALWACO	working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			4/15 - hand dug well	2006	OTHER	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			5/15 - hand dug well	2003	NACSA	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			6/15 - hand dug well	2007	NACSA	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			7/15 - hand dug well	2008	UNICEF	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			8/15 - hand dug well	2004	UNICEF	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			9/15 - hand dug well	1985	UNICEF	working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK

Diang (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
Kondembia													
	Kugbania	210	No system									175	
	Madina	250	1/2 - hand dug well	2004	CARE	working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	167
			2/2 - hand dug well	1983	SALWACO	working	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	168
	Sandia	200	No system									173	
Kongbel Feh													
	Foria	750	1/2 - hand dug well	2008	Mdm	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	196
			2/2 - hand dug well	1996	SALWACO	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	197
Mandrifeh													
	Barkan	200	No system									150	
	Bigkorkor	190	No system									149	
	Danka	65	No system									151	
	Fogo	600	No system									141	
	Gombalie	360	No system									145	
	Herko	250	No system									142	
	Hermakono	150	No system									143	
	Konsoluna	200	No system									146	
	Mankonie	670	No system									148	
	Segbeyaia	500	No system									147	
	Yiben	430	No system									144	
Sokurela													
	Badela	450	1/4 - hand dug well	2005	Care	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal	187
			2/4 - hand dug well	1985	SALWACO	working	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK	188
			3/4 - hand dug well	2005	OTHER	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal	189
			4/4 - hand dug well	2007	SABABU	dry 4 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	190
	Daloala	200	No system									194	
	Dodonyia	600	hand dug well	1985	SALWACO	pump broken	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	183
	Kamaro	1500	hand dug well	1985	SALWACO	dry 2 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal	184
	Kensikoro	500	No system									192	

Diang (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Sokurela												
	Kramator	1300	1/2 - hand dug well	2007	UNICEF	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 185
		1500	2/2 - hand dug well	1985	SALWACO	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 186
	Morkumbaia	50	No system									195
	Nerekoro	400	No system									193
	Soukourolla	500	1/3 - hand dug well	1986	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 178
			1/3 - hand dug well	1986	SALWACO	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 177
			1/3 - hand dug well	2010	MDM	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 179
		466	2/3 - hand dug well	2008	CARE	pump broken	OTHER - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 181
			2/3 - hand dug well	2010	MDM	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 180
			2/3 - hand dug well	2004	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 182
	Yissaia	1000	hand dug well	1985	SALWACO	dry 3 months/year	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 191
Sonsanfeh												
	Gborgbortor	2400	No system									198
	Mansamadugu	300	No system									201
	waia	1700	No system									200
	Warwaia	1000	No system									199

6 sections 37 villages - 25 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Diang - summary / 12 villages					P U M P		SEASONALITY		
Type	Total	Popul. Approxim	Not finished	Functional all the year	installed	working	Dry>3m	seasonal	Alw. water
hand dug well	43	17 344	0	25 (58,1%)	43	30 (70%)	1 (2%)	6 (14%)	36 (84%)
	43	17 344	0	25 (58,1%)	43	30 (70%)	1 (2%)	6 (14%)	36 (84%)

F/Dembelia (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
<u>2</u>	Bumbakoro	40	No system									642	
	Damukoh	90	No system									644	
	Denabalar	100	No system									645	
	Kidibu	60	No system									643	
	Korbor Junction	80	hand dug well	1983	UNDP	pump broken	PB2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	639
	Marakar	110	No system									640	
	Sankan	70	No system									641	
<u>Baladuqu</u>													
	Faseneya	40	1/2 - hand dug well	2006	CARE	dry 6 months/year	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	716
			2/2 - pulley	2001	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	717
	Koromasilia	75	1/5 - hand dug well	2008	NACSA	dry 3 months/year	OTHER - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	718
			2/5 - hand dug well	1983	Care	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	719
			3/5 - hand dug well	2004	DRP	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	720
			4/5 - hand dug well	2004	UNICEF	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	721
			5/5 - pulley	2004	DRP	dry 3 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	722
	Loboya	62	hand dug well	2003	CARE	not finished						-	715
	Mafuna	40	No system										725
	Sellah Feh	105	No system										723
	Taneneh	30	No system										724
	Yamba Gia	110	No system										726
<u>Dogoloya</u>													
	Culumbaya	80	hand dug well	2005	NACSA	dry 3 months/year	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal	736
	Dogoloya	141	1/9 - hand dug well	2005	CARE	not finished						-	727
			2/9 - hand dug well	2006	OTHER	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	728
			3/9 - hand dug well	2006	NACSA	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	729
			4/9 - hand dug well	1988	UNDP	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	730
			5/9 - hand dug well	2007	OTHER	dry 12 months/year	OTHER - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	731
			6/9 - hand dug well	2007	CARE	not finished						-	732
			7/9 - hand dug well	1988	Islamic Development Asso	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	733

F/Dembelia (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Dogoloya												
	Dogoloya	141	8/9 - hand dug well	2007	CARE	dry 5 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 734
			9/9 - hand dug well	2004	CARE	not finished						735
Herekoh												
	Alimamyia	40	No system									679
	Hamdalie	210	1/6 - hand dug well	NA	UNDP	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 670
		300	2/6 - hand dug well	NA	Care	dry 8 months/year	PB2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 671
		150	3/6 - hand dug well	NA	Care	dry 5 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 672
		120	4/6 - hand dug well	NA	Care	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 673
		70	5/6 - hand dug well	NA	NACSA	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 674
		50	6/6 - hand dug well	NA	UNDP	dry 3 months/year	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 675
	Jawaya	120	No system									676
	Mansaraya	40	No system									678
	Mesiran	70	No system									677
Kamba												
	Dankar	80	No system									653
	Filiney	60	No system									651
	Kamba	200	No system									649
	Mamuduia	143	1/3 - hand dug well	1983	UNDP	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 646
			2/3 - hand dug well	1983	UNDP	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 647
			3/3 - hand dug well	2007	Cause Canada	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 648
	Marlonkor	70	No system									652
	Yengisa	70	No system									650
Karliya												
	Ganbakuday	70	No system									669
	Gbentu	153	1/13 - hand dug well	1984	UNDP	dry 1 month/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 655
			10/13 - hand dug we	2005	CARE	dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 664
			11/13 - hand dug we	2007	NACSA	pump broken	OTHER - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 665
			12/13 - hand dug we	2007	CARE	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 666
			13/13 - hand dug we	2005	CARE	dry 5 months/year	PB2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 667

F/Dembelia (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
<u>Karliya</u>													
Gbentu	Gbentu	153	2/13 - hand dug well	1983	UNDP	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	656
			3/13 - hand dug well	2001	UNICEF	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	657
			4/13 - hand dug well	2001	CARE	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	658
			5/13 - hand dug well	2005	CARE	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	659
			6/13 - hand dug well	2004	UNICEF	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	660
			7/13 - hand dug well	2005	CARE	dry 1 month/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal	661
			8/13 - hand dug well	2005	CARE	dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal	662
			9/13 - hand dug well	2005	CARE	dry 3 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	663
	Karliya	180	hand dug well	2004	NACSA	not finished					-	654	
	Sunbania	80	No system									668	
<u>Larkor</u>													
Kamabunor	Kamabunor	30	No system									634	
		60	No system									633	
		40	No system									636	
		50	1/3 - hand dug well	2005	Cause Canada	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	629
		60	2/3 - hand dug well	2007	Other	dry 10 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	630
		72	3/3 - hand dug well	2006	Care	working	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	631
	Kimaka	35	No system									635	
	Kumbakada	200	No system									637	
	Kumbakada1	50	pulley	2004	Care	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	632
	Larkor	200	No system									638	
<u>Musaiia</u>													
Ahmadiyya	Ahmadiyya	150	hand dug well	2006	CARE	not finished					-	702	
		100	1/2 - pulley	2005	CARE	dry 7 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	707
Kabakaia	Kabakaia		2/2 - hand dug well	2005	CARE	dry 3 months/year	IN - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	708
		50	pulley	2005	CARE	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	710
Kamasiren2		70	hand dug well	1983	UNDP	dry 4 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	681
Kamasiron	Madina	183	1/3 - hand dug well	2006	Cause Canada	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	699
			2/3 - hand dug well	2007	OTHER	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal	700

F/Dembelia (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Musaia												
	Madina	183	3/3 - hand dug well	2004	CARE	not finished					-	701
	Madogbo	401	1/5 - hand dug well	2004	CARE	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			2/5 - pulley	2004	CARE	dry 4 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			3/5 - pulley	2004	CARE	dry 10 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			4/5 - pulley	1983	UNDP	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			5/5 - hand dug well	2005	Cause Canada	dry 4 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Mageia	200	hand dug well	2007	OTHER	dry 4 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Malucoy	45	1/2 - hand dug well	2005	CARE	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			2/2 - hand dug well	2006	CARE	dry 2 months/year	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	M-Compound	50	hand dug well	1987	OTHER	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Musaia	268	1/8 - hand dug well	2007	OTHER	dry 1 month/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/8 - hand dug well	2006	OTHER	dry 7 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			3/8 - hand dug well	2007	OTHER	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			4/8 - hand dug well	2006	OTHER	pump broken	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			5/8 - hand dug well	2007	OTHER	not finished					-	693
			6/8 - hand dug well	2004	OTHER	dry 4 months/year	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			7/8 - hand dug well	2005	Cause Canada	dry 6 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			8/8 - hand dug well	1986	OTHER	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	One Man Place	40	No system									713
	One Mile	60	No system									712
	Orgon	400	hand dug well	1978	OTHER	pump broken	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Orgon Junction	400	hand dug well	1976	OTHER	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Sambasina	75	1/2 - hand dug well	2004	CARE	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			2/2 - pulley	2004	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Solenteh	70	No system									714
	Soron	70	hand dug well	2005	CARE	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Talaya	75	pulley	1985	OTHER	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Tamegia	60	hand dug well	2006	CARE	dry 2 months/year	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working

F/Dembelia (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
---------	---------	--------------------	-------------	------	---------	------------	-----------	---------------	-----------------	------------------	-----------------	------

8 sections 58 villages - 30 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

F/Dembelia - summary / 28 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
hand dug well	68	10 671	8	10 (14,7%)	59	35 (59%)	17 (25%)	24 (35%)	19 (28%)
	68	10 671	8	10 (14,7%)	59	35 (59%)	17 (25%)	24 (35%)	19 (28%)

Kabala (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Kabala												
	Amputee Camp Two	150	hand dug well	2008	CARE	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 16
	Ansarul Primary Schoo	600	hand dug well	2008	UNICEF	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 15
	Bankolia	600	hand dug well	2008	Red Cross	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 18
	Bankolia Primary Scho	1000	hand dug well	2006	UNICEF	dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 17
	Bilma Road Amputee (6000	hand dug well	2008	CARE	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 12
	Bilma Road Amputee	3000	hand dug well	2008	CARE	dry 6 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 13
	Bilma Road Amputee	600	hand dug well	2008	CARE	dry 4 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 14
	DEC Primary School 1	2500	hand dug well	2006	OTHER	pump broken	OTHER - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 33
	DEC Primary School 2	3000	hand dug well	2005	UNICEF	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 34
	Gyawuria 1	900	hand dug well	1982	UNDP	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 3
	Gyawuria 2	1500	hand dug well	2010	Good Governance	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1
	Gyawuria II	800	hand dug well	2005	Red Cross	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 31
	Govt. Hospital	6000	hand dug well	2000	MSF	pump broken	PB2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 36
	Kamasokola 1	600	hand dug well	1999	RELIEF	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 26
	Kamasokola 2	300	pulley	2000	Community	dry 3 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 27
	Kapendeyoko 1	700	hand dug well	2003	OTHER	dry 2 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 24
	Kapendeyoko 2	300	hand dug well	2010	Town Council	not finished						- 25
	Kapendeyoko School f	600	bore hole	1990	Japan	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 28
	Kapendeyoko School f	300	hand dug well	2007	SABABU	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 29
	Kathombo II	600	hand dug well	1994	UNICEF	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 23
	Koinadugu Road 1	600	hand dug well	2002	UNDP	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 8
	koinadugu Road 2	800	hand dug well	2010	Town Council	not finished						- 9
	Loma Secondary Scho	1800	hand dug well	1979	UNDP	not finished						- 37
	Police Barracks 1	12000	hand dug well	1985	UNDP	working	PB2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 19
	Police Barracks 2	600	hand dug well	2003	DFID	dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 20
	Police Barracks 3	5000	hand dug well	2003	DFID	dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 21
	Prison Quarter	11000	hand dug well	2002	MSF	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 22
	RC Central Primary	950	hand dug well	2007	UNICEF	dry 5 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 35

Kabala (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Kabala												
	Timbo Sukurala 1	700	bore hole	1978	OTHER	pump broken	PB2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 10
	Timbo Sukurala 2	5000	bore hole	2004	CARE	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 11
	WCSL Primary School	3000	hand dug well	2006	NACSA	dry 2 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 2
	WCSL Primary School	900	hand dug well	2009	NACSA	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 32
	Yogamaia Central Mos	700	bore hole	2002	OTHER	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 30
	Yogamaia Bucher Mar	1000	hand dug well	2007	OTHER	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 5
	Yogomaia Market	1500	hand dug well	2007	OTHER	dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 4
	Yogomaia mini Stadiu	1500	bore hole	2009	NACSA	dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 6
	Yogomaia Mini Stadiu	1500	bore hole	2001	NACSA	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 7

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee: presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Kabala					P U M P		SEASONALITY		
Type	Total	Popul. Approxim	Not finished	Functional all the year	installed	working	Dry>3m	seasonal	Alw. water
bore hole	6	10 000	0	3 (50%)	6	4 (67%)	0 (0%)	1 (17%)	5 (83%)
hand dug well	30	68 300	3	10 (33,3%)	28	20 (71%)	3 (10%)	9 (30%)	15 (50%)
	36	78 300	3	13 (36,1%)	34	24 (71%)	3 (8%)	10 (28%)	20 (56%)

Kasunko (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Gbonkorboh</u>												
	Kabakeh	68	No system									236
	Kabendugu	40	No system									226
	Kacompound	100	hand dug well	2006	CARe	dry 3 months/year	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kaffa	240	No system									224
	Kagbonkorgboh	68	No system									231
	Kajion	72	No system									229
	Kakimaboi	108	hand dug well	2008	Care	pump broken	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kakoyai	386	1/4 - hand dug well	2008	CCF	dry 2 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/4 - hand dug well	2009	CARE	dry 1 month/year	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			3/4 - hand dug well	2006	MDM	pump broken	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			4/4 - hand dug well	2007	NACSA	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kamasapie	316	1/3 - hand dug well	2006	CARE	dry 2 months/year	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/3 - hand dug well	2005	CCF	not finished						203
			3/3 - hand dug well	2006	NACSA	dry 2 months/year	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kamaselleh 1	68	No system									234
	Kamaselleh 2	108	No system									237
	Kamayeakain	79	No system									235
	Karkar	198	No system									230
	Kasain	100	No system									238
	Kassasi 2	60	No system									228
	Kassasie	290	1/2 - hand dug well	2003	CCF	pump broken	PB2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/2 - hand dug well	2008	CARE	pump broken	IN - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kawa	201	1/3 - hand dug well	2007	CARE	dry 4 months/year	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/3 - hand dug well	2006	CARE	dry 1 month/year	K - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working
			3/3 - hand dug well	2006	MDM	dry 4 months/year	K - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kawornoh	170	No system									233
	Kawugandaen	106	No system									227
	Kayanandan	110	No system									232
	Kayenkay	242	No system									225

Kasunko (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Gbonkorboh												
	Madinadel	636	1/4 - hand dug well	2009	SABABU	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/4 - hand dug well	2006	OTHER	not finished						218
			3/4 - hand dug well	2005	CCF	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			4/4 - hand dug well	2007	Care	pump broken	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working
	Sawuria	400	1/2 - hand dug well	2007	NACSA	dry 2 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/ - hand dug well	2005	NACSA	dry 1 month/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Tankonosidia	350	1/2 - hand dug well	2006	CARE	dry 3 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			2/2 - hand dug well	2007	Care	dry 2 months/year	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
Kakelain												
	Kabonka	68	No system									257
	Kagbasia	185	1/5 - hand dug well	2004	CARE	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			2/5 - hand dug well	2006	OTHER	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			3/5 - hand dug well	2005	CARE	working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			4/5 - hand dug well	2007	NACSA	pump broken	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			5/5 - spring box	2008	CCF	working	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Kagbolie	97	No system									253
	Kagbusuna	150	No system									249
	Kakutuhu	202	No system									254
	Kalumbay	102	No system									250
	Kamagbekalbay	509	No system									251
	Kamakaeh	70	hand dug well	2003	CARE	pump broken	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kamakalanka	108	No system									261
	Kamakeintiyea	112	No system									247
	Kamakonta 2	78	No system									255
	Kamankay	410	No system									248
	Kamasorie	238	No system									260
	Kasainpon	218	No system									259
	Kasansan	106	No system									258
	Kasokera	170	No system									256

Kasunko (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
Kakelain													
	Kassasie	235	No system									252	
	Makamaya	410	hand dug well	2003	CARE	not finished					-	245	
	New Site	45	No system									246	
Kasonko													
	Affia	60	No system									321	
	Fadugu	385	hand dug well	2006	CARE	dry 4 months/year	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	299
		1/12 - hand dug well	2002	CARITAS	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK	288	
		10/12 - hand dug we	2006	CCF	dry 5 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	297	
		11/12 - hand dug we	2006	OTHER	working	PB2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	298	
		12/12 - hand dug we	2010	OTHER	working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	312	
		2/12 - hand dug well	2002	CARITAS	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	289	
		3/12 - hand dug well	2003	SADAL	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	290	
		4/12 - hand dug well	2004	SADAL	dry 4 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	291	
		5/12 - hand dug well	1997	OTHER	dry 1 month/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	292	
		6/12 - hand dug well	2002	CARITAS	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal	293	
		7/12 - hand dug well	2002	CARITAS	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	294	
		8/12 - hand dug well	2003	OTHER	working	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	295	
		9/12 - hand dug well	2006	CARITAS	dry 5 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	296	
	Heremakono	100	No system									325	
	Kabainda	85	No system									323	
	Kabarikie	51	No system									333	
	Kabendugu	70	No system									329	
	Kabuita	500	No system									337	
	Kadubayan	60	No system									313	
	Kaduwankoh	100	No system									342	
	Kafogo	1000	1/2 - hand dug well	2008	UNICEF	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	306
		2/2 - hand dug well	2006	CARE	dry 2 months/year	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	307	
	Kagboray	30	No system									330	
	Kakanu	452	No system									335	

Kasunko (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Kasonko												
	Kakekar	150	hand dug well	2008	CARE	dry 2 months/year	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 308
	Kakondobie	75	No system									334
	Kamabinki	150	hand dug well	2002	ACF	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 300
			hand dug well	2007	CARE	pump broken	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 301
	Kamacane	78	No system									314
	Kamadorien	50	No system									324
	Kamagbama	92	No system									327
	Kamakelleh	53	No system									341
	Kamakethea 1	50	No system									319
	Kamandi	200	No system									326
	Kamapomproni	40	No system									316
	Kamasukuduina	60	No system									318
	Kamayornie	60	No system									332
	Kasaraukunday	90	No system									315
	Kasolaha	115	1/2 - hand dug well	2008	Other	dry 3 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 310
			2/2 - hand dug well	2008	Other	dry 3 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 311
	Kassasie	58	No system									328
	Kathadungbu1	30	No system									320
	Kathadungbu2	200	No system									322
	Katimbo	80	No system									338
	Kawerreh	300	No system									336
	Kayeakaysa	50	No system									340
	Kontheya	55	No system									317
	Madina Kamandi	400	No system									331
	Sagbamba	118	1/4 - pulley	2007	CARE	dry 6 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 302
			2/4 - hand dug well	2003	UNICEF	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 303
			3/4 - hand dug well	2007	CARE	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 304
		200	4/4 - hand dug well	2006	UNICEF	working	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 305

Kasunko (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Kasonko												
	Tongoya	115	No system									339
	Worndolo	100	hand dug well	2004	UNICEF	dry 5 months/year	IN - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 309
Kayaka												
Heremakono		540	1/3 - hand dug well	2009	MDM	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 266
			2/3 - hand dug well	2007	UNICEF	pump broken	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 267
			3/3 - hand dug well	2006	Care	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 268
	Kabiroo	28	No system									281
	Kabonka	101	No system									278
	Kadagbana	38	No system									282
	Kagbesenah	72	No system									287
	Kakanu	45	No system									285
	Kakarima	175	hand dug well	2004	NACSA	working	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 265
	Kamabondor	56	No system									277
	Kamadekar	99	hand dug well	2007	CARE	dry 4 months/year	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 263
	Kamakeintiyea	30	No system									280
	Kamakomen	100	hand dug well	2005	CARE	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 264
	Kamasan	60	No system									284
	Kamasunken	87	No system									271
	Kamawatten	82	No system									286
	Kapethe	42	No system									275
	Kasarokoh	58	No system									274
	Kaseinae	103	No system									273
	Kasesie	39	No system									276
	Katambar	79	No system									279
	Katerenah	75	No system									269
	Kathanta	109	No system									270
	Kawolona	52	No system									283
	Simbeck	103	hand dug well	2006	CARE	dry 4 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 262

Kasunko (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Tamiso 1</u>												
	Babakalia	55	No system									362
	Heremakono	54	No system									347
	Kabolomi	120	No system									351
	Kagbaneh	30	No system									365
	Kalassa	305	No system									353
	Kamabama	60	No system									356
	Kamagboren	100	No system									364
	Kamakenjeh	50	No system									358
	Kamakorogba	43	No system									352
	Kamasaman	37	No system									363
	Kamathanthan	160	No system									357
	Kamatoi	120	No system									345
	Kanongoh	150	No system									348
	Kasanikoro	175	1/2 - hand dug well	2006	NACSA	not finished		-				343
			2/2 - hand dug well	2006	NACSA	not finished		-				344
	Kasankorie	450	No system									355
	Madina Limba	151	No system									360
	Makeni	101	No system									350
	Senekoroh	30	No system									361
	Sherifula	400	No system									354
	Sinbeck	69	No system									349
	Sokudala	100	No system									359
	Yabakaiya	50	No system									346
<u>Tamiso2</u>												
	Kabolimba	40	No system									368
	Kaboreh	70	No system									367
	Kadala	50	No system									378
	Kafangrey	200	No system									370

Kasunko (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Tamiso2</u>												
	Kafankama	58	No system									377
	Kahatha	60	No system									369
	Kamabondeh	55	No system									381
	Kamaraya	60	No system									372
	Kamatantan	80	No system									373
	Kamayabereh	300	No system									366
	Kamaylorlohtoh	40	No system									375
	Kanghatotoh	74	No system									379
	Karakana	150	No system									371
	Kasanghan	80	No system									380
	Kasurkorya	40	No system									374
	Mongo Weredala	63	No system									376

6 sections 141 villages - 116 with no system at a

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Kasunko - summary / 25 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
hand dug well	61	19 815	5	12 (19,7%)	55	25 (45%)	9 (15%)	21 (34%)	26 (43%)
	61	19 815	5	12 (19,7%)	55	25 (45%)	9 (15%)	21 (34%)	26 (43%)

Mongo (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Bendugu</u>												
	Farakofeh	60	1/2 - hand dug well	1985	CRS	dry 2 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			2/2 - hand dug well	1989	OTHER	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Fayiya	270	hand dug well	2010	CRS	dry 6 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kondeya	300	1/2 - pulley	1984	OTHER	dry 2 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/2 - hand dug well	1986	OTHER	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Modoloforia	500	hand dug well	1978	OTHER	dry 2 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Shekuya	300	hand dug well	2010	CRS	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Tambaibalia	700	hand dug well	2010	OTHER	dry 5 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
<u>Deldugu</u>												
	Dandanfara	300	No system									1085
	Farema	270	No system									1088
	Gberimba	350	hand dug well	2010	CRS	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Kamaron	650	hand dug well	2010	CRS	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Konkowakoro	500	hand dug well	1985	OTHER	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kulakoya	320	No system									1091
	Lanfiyaya	160	No system									1090
	Masadu	200	1/4 - hand dug well	1990	OTHER	dry 3 months/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/4 - hand dug well	1990	OTHER	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			3/4 - hand dug well	2006	NACSA	dry 7 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			4/4 - hand dug well	2007	UNICEF	dry 2 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Masadukoro	200	No system									1084
	Nyankolia	450	No system									1092
	Sanikaria	300	hand dug well	2010	CRS	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Sansangbala	300	No system									1087
	Semendu	600	hand dug well	2010	CRS	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Seremorodu	300	No system									1089
	Tinko	170	No system									1083
	Walbagba	260	No system									1086

Mongo (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Mankalia</u>												
	Kamaron	125	1/4 - hand dug well	1990	OTHER	dry 2 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1063
			2/4 - hand dug well	1990	OTHER	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1064
			3/4 - hand dug well	2009	NACSA	dry 2 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1065
			4/4 - hand dug well	2009	CRS	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1066
	Kiridu	350	1/2 - hand dug well	2010	CRS	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1061
			2/2 - hand dug well	1990	OTHER	pump broken	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1062
	Lansana Balia	300	1/2 - hand dug well	2010	CRS	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1067
			2/2 - hand dug well	1990	OTHER	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1068
	Marimaya	280	No system									1073
	Moriboridu	400	hand dug well	2010	CRS	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1069
	Saccoh Seria	100	No system									1071
	Sokorlalle	110	No system									1072
	Yarador	220	No system									1070
<u>Mongo Bendugu</u>												
	Bockaria 1	120	hand dug well	1984	OTHER	dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 964
	Kansabalia	290	No system									967
	Karifaya	965	1/4 - hand dug well	1982	OTHER	dry 4 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 953
			2/4 - hand dug well	1982	OTHER	dry 1 month/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 954
			3/4 - hand dug well	1982	OTHER	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 955
			4/4 - hand dug well	2007	UNICEF	dry 4 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 956
	Satlamodia	115	hand dug well	1984	OTHER	dry 2 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 963
	Shekuya	90	hand dug well	1983	OTHER	dry 4 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 965
	Sumadu	40	hand dug well	1984	OTHER	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 952
	Tirimafeh	270	No system									966
	Walia	75	1/6 - hand dug well	2009	SABABU	dry 4 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 957
			2/6 - hand dug well	2007	CRS	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 958
			3/6 - pulley	1984	OTHER	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 959
			4/6 - pulley	1984	OTHER	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 960
			5/6 - pulley	1984	OTHER	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 961

Mongo (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Mongo Bendugu</u>												
	Yamoria	85	No system									968
<u>Mongo Bendugu</u>												
	Bafuabeh	258	No system									1016
	Bendugu	300	1/13 - hand dug well	1990	OTHER	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			10/13 - hand dug we	2005	World Vision	dry 3 months/year	PB2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			11/13 - hand dug we	2007	UNICEF	dry 4 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			12/13 - hand dug we	2010	SABABU	dry 6 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			13/13 - hand dug we	2007	UNICEF	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			2/13 - hand dug well	1990	OTHER	dry 3 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			3/13 - hand dug well	1994	OTHER	dry 2 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			4/13 - hand dug well	1990	OTHER	dry 2 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			5/13 - hand dug well	2005	NACSA	dry 7 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			6/13 - hand dug well	1990	OTHER	dry 7 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			7/13 - hand dug well	1990	OTHER	dry 1 month/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			8/13 - hand dug well	2010	OTHER	not finished					-	976
			9/13 - hand dug well	1985	OTHER	dry 3 months/year	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Dambafah	160	No system									1012
	Dankokalia	150	No system									1011
	Danyoroh	128	1/2 - hand dug well	1985	OTHER	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			2/2 - hand dug well	2010	CRS	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Denkeletor	230	No system									1017
	Firawa	250	hand dug well	1984	OTHER	dry 4 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Gbongbondor	325	1/2 - pulley	1985	OTHER	dry 4 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/2 - hand dug well	1985	OTHER	dry 3 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Herekerfeh	203	No system									1013
	Heremakono	400	hand dug well	1994	OTHER	dry 4 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Kaliyereh	200	1/3 - hand dug well	2004	CARE	dry 4 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/3 - hand dug well	2004	CARE	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			3/3 - hand dug well	2010	CRS	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK

Mongo (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Mongo Benduqu</u>												
Karawani	116	1/3 - hand dug well	1986	UNICEF		dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 982
		2/3 - hand dug well	2007	UNICEF		not finished						- 983
		3/3 - hand dug well	1985	OTHER		dry 3 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 984
Koromandor	152	1/3 - pulley	1996	OTHER	-	no pump		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 986
		2/3 - hand dug well	1996	CARE		dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 987
		3/3 - hand dug well	2005	CARE		dry 4 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 988
Lensiya	293	1/2 - hand dug well	2003	CARE		dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 998
		2/2 - hand dug well	2003	CARE		not finished						- 999
Madina	50	hand dug well	1986	OTHER		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1007
Mansoya	264	No system										1019
Mongo Kiridu	225	1/2 - hand dug well	1994	OTHER		dry 6 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1004
		2/2 - hand dug well	2010	CRS		working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1005
Nyeldu	259	No system										1010
Poreh Kalia	215	No system										1020
Serefaya	257	No system										1009
Seria	250	1/6 - hand dug well	1999	OTHER		not finished						- 992
		2/6 - hand dug well	1999	OTHER		dry 4 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 993
		3/6 - hand dug well	2007	SABABU		dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 994
		4/6 - hand dug well	1998	OTHER		dry 2 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 995
		5/6 - hand dug well	2003	OTHER		dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 996
		6/6 - hand dug well	1984	OTHER		working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 997
Siranikaro	400	No system										1014
Sokurala	165	No system										1018
Walgbasakor	196	hand dug well	1986	OTHER		working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1006
Yimbakiridu	270	No system										1015

Monoq Benduqu

Walia	75	6/6 - pulley	1984	OTHER	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	962
-------	----	--------------	------	-------	---	---------	--------------------------	-------------------------------------	--------------------------	--------------------------	-------------	-----

Morifinduqu

Dulla	160	hand dug well	2006	CRS		dry 3 months/year	PB2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1034
-------	-----	---------------	------	-----	--	-------------------	-------------------	-------------------------------------	-------------------------------------	--------------------------	-------------------------------------	------------------

Mongo (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Morifinduqu</u>												
	Farama	170	hand dug well	1987	OTHER	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1044
	Gbenekoro	350	1/2 - hand dug well	2010	CRS	dry 4 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1037
	Gberefefh	180	1/5 - hand dug well	1978	OTHER	dry 5 months/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1025
			2/5 - hand dug well	1990	OTHER	dry 7 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 1026
			3/5 - hand dug well	1990	OTHER	dry 3 months/year	PB2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1027
			4/5 - hand dug well	1997	CCF	dry 4 months/year	IN - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1028
			5/5 - hand dug well	1998	OTHER	dry 2 months/year	IN - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1029
	Gbrnekoro	350	2/2 - hand dug well	1986	OTHER	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1038
	Kombili	150	1/3 - hand dug well	2009	NACSA	dry 4 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1045
			2/3 - hand dug well	1984	OTHER	dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1046
			3/3 - hand dug well	1984	OTHER	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1047
	Namaia	370	No system									1048
	Nyenekoro	300	hand dug well	2005	CRS	dry 5 months/year	PB2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1036
	Sangbanbalia	176	No system									1051
	Semisadu	900	hand dug well	2007	CRS	dry 4 months/year	IN - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1035
	Serekolia	600	1/5 - hand dug well	2010	CRS	dry 5 months/year	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1039
			2/5 - hand dug well	1978	OTHER	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1040
			3/5 - hand dug well	2004	CRS	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1041
			4/5 - hand dug well	2005	CRS	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1042
			5/5 - hand dug well	1978	OTHER	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1043
	Sinikoro	266	1/3 - hand dug well	1985	OTHER	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1022
			2/3 - hand dug well	2010	CRS	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1023
			3/3 - hand dug well	2008	CRS	dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1024
	Sorakoror	76	No system									1050
	Tilikoro	167	1/3 - hand dug well	1970	OTHER	dry 3 months/year	PB2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1031
			2/3 - hand dug well	1970	OTHER	dry 4 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1032
			3/3 - hand dug well	2007	CRS	dry 5 months/year	PB2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 1033
	Tuba	800	hand dug well	1990	OTHER	dry 4 months/year	IN - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 1030
	Tumaria	160	hand dug well	2010	OTHER	pump broken	PB2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1021

Mongo (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
	<u>Morifinduqu</u>											
	Yenekonkoreh	196	No system									1049

7 sections 82 villages - 33 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Mongo - summary / 49 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
hand dug well	100	29 969	4	18 (18%)	96	59 (61%)	29 (29%)	41 (41%)	26 (26%)
	100	29 969	4	18 (18%)	96	59 (61%)	29 (29%)	41 (41%)	26 (26%)

Neya (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Kullor</u>												
	Bendu	160	No system									951
	Konkowaroko	410	1/2 - hand dug well	2005	UNDP	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 946
			2/2 - hand dug well	2005	UNDP	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 947
	Korodiakoro	180	No system									950
	Manson	720	hand dug well	2005	UNDP	dry 5 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 948
	Yarawadu	490	1/2 - hand dug well	2008	UNDP	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 944
			2/2 - hand dug well	2008	UNDP	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 945
	Yiraya	230	No system									949
<u>Naya2</u>												
	Manya		No system									900
<u>Neya 1</u>												
	Balla Namurya	156	No system									879
	Ballion	458	No system									853
	Banboraya	566	No system									847
	Bandakie	560	No system									851
	Bendebular Ballia	581	No system									854
	Bendu	547	No system									856
	Boroya	780	No system									860
	Donbosulia	389	No system									848
	Faragbama	370	No system									855
	Fayimbakondeya	210	No system									875
	Fundubuma	263	No system									870
	Fundusuma Kura	367	No system									852
	Gbenikoro	336	No system									861
	Kalie Sedaya	93	No system									869
	K-Ballia	379	pulley	1985	OTHER	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 844
	K-Balliomca	379	hand dug well	2008	UNICEF	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 843
	Kemoroseya	569	No system									866

Neya (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Neya 1</u>												
	Kemoya	551	No system									864
	Kenewa	410	No system									862
	Kireborodu	562	No system									858
	Kolowa Sayoya	175	No system									873
	Konde Mansoya	110	No system									878
	Konkoroya	81	No system									872
	Koremundo	250	hand dug well	1978	OTHER	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 837
	Kumbaforaya	73	No system									871
	Kunia	670	No system									877
	Kurubonta	383	1/6 - hand dug well	1985	OTHER	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 830
			2/6 - hand dug well	2008	UNICEF	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 831
			3/6 - hand dug well	1985	OTHER	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 832
			4/6 - hand dug well	2009	World Bank	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 833
			5/6 - hand dug well	2007	NACSA	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 834
			6/6 - hand dug well	2005	NACSA	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 835
	Madina	393	No system									863
	Manburuya	465	No system									876
	Mandotinia	500	1/5 - hand dug well	1987	OTHER	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 838
			2/5 - hand dug well	1987	OTHER	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 839
			3/5 - hand dug well	1987	OTHER	dry 1 month/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 840
			4/5 - hand dug well	2009	NACSA	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 841
			5/5 - hand dug well	2009	World Bank	dry 5 months/year	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 842
	Mansoyan1	376	No system									849
	Mansoyan2	270	No system									850
	Nyelaia	300	hand dug well	1985	OTHER	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 836
	Sarafelaya	673	No system									867
	Seredu	671	No system									859
	Shekuya	200	No system									874
	Soroya	631	No system									865

Neya (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Neya 1</u>												
	Tagbadu	285	No system									845
	Terero	257	No system									857
	Worekovo	450	No system									846
	Yembima	130	No system									880
	Yirandu	539	No system									868
<u>Neya 2</u>												
	Porpon	1673	hand dug well	2010	<i>World Bank</i>	dry 1 month/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 881
<u>Neya2</u>												
	Barburo	261	No system									890
	Bondofeh	241	No system									891
	Bunyifeh	667	No system									894
	Daboroma	756	No system									893
	Dalewuliafeh	150	No system									887
	Fankareyan Kura	83	No system									882
	Kandeya	373	No system									895
	Karbuya	125	No system									889
	Kekoluafeh	76	No system									886
	Kondedalamo	212	No system									897
	Maria	271	No system									884
	Shekuuya Koro	263	No system									883
	Shekya Kura		No system									901
	Sulukuya	93	No system									899
	Tenkenya	559	No system									885
	Teretoo Kura	122	No system									898
	Tinkenbu	893	No system									892
	Wosokorofeh	474	No system									896
	Yormankoro	248	No system									888

Nyedu

Neya (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Nyedu</u>												
	Banfeleh	240	No system									908
	Bankoro	103	No system									914
	Borokuma	110	No system									920
	Bumbukoro	267	1/3 - pulley	1985	World Bank	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/3 - hand dug well	2006	NACSA	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			3/3 - hand dug well	2010	World Bank	not finished						905
	Buru	237	No system									909
	Burumakundor	140	No system									912
	Fasanegbama	167	No system									916
	Kamaya	256	No system									917
	Kanyadu	160	No system									922
	Komaron	136	No system									919
	Komba Mansaraya	116	No system									923
	Kondeya	379	pulley	1985	OTHER	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Mansoya	892	No system									913
	Mantene Yiraya	130	No system									921
	Nendu	175	No system									915
	Sakuralor	239	No system									911
	Sayoya	258	No system									907
	Seraya	154	No system									918
	Seredu	350	No system									910
	Sinkenbadu	136	No system									906
<u>Saradu</u>												
	Bendu 3	520	hand dug well	2008	NACSA	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Bumbukoro	321	No system									936
	Dalema	120	No system									940
	Durukoro	629	No system									927
	Fakondia	531	No system									929

Neya (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Saradu												
	Fasumbuya	320	No system									930
	Fayiya	219	No system									935
	Gbanworoya	211	No system									937
	Kamindu	150	No system									939
	Kolakoya	125	No system									942
	Kulero	310	No system									933
	Kulia	752	No system									926
	Nerekoro	760	No system									928
	Nyandakoro	211	No system									934
	Porpon	301	No system									938
	Sandia	426	No system									925
	Sankarama	239	No system									932
	Sumaworoya	260	No system									931
	Tarawalton	100	No system									943
	Tayandu	130	No system									941

7 sections 109 villages - 96 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Neya - summary / 13 villages					P U M P		SEASONALITY		
Type	Total	Popul. Approxim	Not finished	Functional all the year	installed	working	Dry>3m	seasonal	Alw. water
hand dug well	23	10 974	1	7 (30,4%)	22	11 (50%)	2 (9%)	4 (17%)	16 (70%)
	23	10 974	1	7 (30,4%)	22	11 (50%)	2 (9%)	4 (17%)	16 (70%)

Nieni (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Barawa</u>												
	Bamba	300	No system									511
	Barawa Herko	500	No system									508
	Bonkakalia	300	No system									497
	Brimaya1	250	No system									498
	Brimaya2	300	No system									507
	Dikonoh	200	No system									501
	Dinkaya	400	No system									510
	Firawa	200	1/5 - hand dug well	1989	Other	dry 1 month/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
			2/5 - bore hole	1989	OTHER	dry 3 months/year	PB2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			3/5 - bore hole	1989	OTHER	dry 2 months/year	PB2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			4/5 - bore hole	1989	OTHER	dry 4 months/year	PB2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			5/5 - bore hole	1989	OTHER	dry 5 months/year	PB2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kalamkoro	400	No system									506
	Kanbayia	250	No system									503
	Komehya	500	No system									502
	Kulonka	700	No system									496
	Manburaya	300	No system									504
	Moria	300	No system									500
	Sereduya	600	bore hole	1980	OTHER	dry 3 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Sesalaya	300	No system									505
	Singblaya	200	No system									512
	Siramoria	400	No system									509
	Timbiran	400	hand dug well	2004	CARE	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Wankako	400	No system									499
<u>Kellian</u>												
	Abuya	140	No system									486
	Alkalia	166	1/6 - hand dug well	2007	Care	dry 2 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			2/6 - hand dug well	2007	CRS	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK

Nieni (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Kellian</u>												
	Alkalia	166	3/6 - hand dug well	2007	Care	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 457
			4/6 - hand dug well	2005	CRS	dry 8 months/year	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 458
			5/6 - hand dug well	2006	Care	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 459
			6/6 - hand dug well	2006	CRS	dry 5 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 460
	Balliaya	170	No system									480
	Bandakoro	600	No system									465
	Bathsam	130	No system									476
	belaselaya	140	No system									478
	Borukoro	260	1/2 - hand dug well	2009	Care	pump broken	IN - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 452
			2/2 - hand dug well	2007	CRS	dry 9 months/year	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 453
	Conthhya	200	No system									481
	Dataeya	200	No system									471
	Farefema	140	No system									477
	Farekoro	433	No system									464
	Felima	130	No system									474
	Funehma	100	No system									473
	Gbamayia	350	No system									468
	Gbangbanferu	200	hand dug well	2003	Care	dry 4 months/year	IN - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 461
	Gbonkolenkeh	140	No system									483
	Kaindeya	2018	hand dug well	2009	ORIENT	dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 462
	Kargboya	100	No system									472
	Konchebaefeh	130	No system									487
	Kulko	140	No system									475
	Kumala	1500	1/4 - hand dug well	2008	NACSA	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 445
			2/4 - hand dug well	2008	NACSA	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 446
			3/4 - hand dug well	2008	Care	working	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 447
			4/4 - hand dug well	2008	Care	dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 448
	Lirroh	1666	1/3 - hand dug well	2008	Other	dry 7 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 449
			2/3 - hand dug well	2007	Care	dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 450

Nieni (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Kellian</u>												
	Lirroh	1666	3/3 - hand dug well	2007	Care	dry 3 months/year	K - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 451
	Mangae Badala	130	No system									484
	Mansiraya	300	No system									466
	Moria	600	hand dug well	2006	CRS	dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 454
	Porpoifeh	50	No system									485
	Ropolo	130	No system									479
	Sesewalanya	777	No system									488
	Togo	140	No system									482
	Tunkuli	500	No system									469
	Wellington	340	No system									470
	Worombayia	400	No system									467
	Yoroya	400	No system									463
<u>Nieni</u>												
	Borkelia	531	No system									417
	Dambafayia	65	No system									413
	Danieya	200	No system									403
	Denkierayi	250	No system									418
	Fankoya	560	No system									400
	Funubakoro	750	1/2 - hand dug well	2005	Care	working	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 395
			2/2 - hand dug well	2005	Care	dry 4 months/year	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 396
	Funubakura	70	No system									424
	Gbenekoro	300	No system									420
	Hassanya	100	hand dug well	2005	Care	dry 6 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 384
	Kaloya	800	No system									423
	Kambaya1	350	No system									404
	Kambaya2	330	No system									405
	Kayia	2000	No system									406
	Kelela	70	No system									412

Nieni (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Nieni</u>												
	Komaya	80	No system									409
	Kombortambaya	350	1/2 - hand dug well	2006	Care	pump broken	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 382
			2/2 - hand dug well	2007	UNICEF	dry 4 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 383
	Konobia	400	hand dug well	2005	Care	dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 397
	Konorbayia	1500	No system									422
	Koyiya	300	No system									402
	Krutor	300	No system									421
	Kulanya	400	No system									419
	Melyifeh	70	No system									414
	Perenkoror	98	No system									410
	Satameria	80	No system									416
	Selyadu	100	No system									408
	Seweiya	600	No system									407
	Soya	623	No system									398
	Soya Yirahya	60	No system									411
	Telikoro	650	1/2 - hand dug well	2005	Care	not finished					-	385
			2/2 - hand dug well	2005	Care	not finished					-	386
	Worskorama	100	No system									401
	Yendekolia	300	No system									415
	Yiben	600	No system									399
	Yiffin	425	1/8 - hand dug well	2005	UNICEF	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 387
			2/8 - hand dug well	2007	NACSA	not finished						388
			3/8 - hand dug well	2004	CRS	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 389
			4/8 - hand dug well	2005	OTHER	dry 2 months/year	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 390
			5/8 - hand dug well	2007	UNICEF	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 391
			6/8 - hand dug well	2010	SABABU	dry 12 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 392
			7/8 - hand dug well	2005	UNICEF	working	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 393
			8/8 - hand dug well	2005	UNICEF	working	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 394

Seradu

Nieni (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
<u>Seradu</u>													
	Bakorya	100	No system									433	
	Bandaya	130	No system									439	
	Banguraya	300	No system									432	
	Contehya	100	No system									436	
	Gbenekoro	400	No system									434	
	Gbengberia	460	No system									443	
	London	60	No system									444	
	Mandrya	120	No system									438	
	Mangae	250	1/2 - hand dug well	2008	OTHER	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	429
			2/2 - hand dug well	2010	World Bank	not finished						-	430
	Marbala	500	hand dug well	2008	UNICEF	not finished						-	431
	Margboko	200	No system										437
	Parayia	220	No system										440
	Safinya	1500	No system										442
	Samaya	354	No system										441
	Sewuriya	600	No system										435
	Sumbaria	166	1/3 - hand dug well	2008	NACSA	dry 4 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	426
			2/3 - pulley	1998	OTHER	dry 4 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	427
			3/3 - hand dug well	2006	CRS	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	428
<u>Wallay</u>													
	Bandakefair	400	No system										513
	Bankoro	400	No system										522
	Chimadu	400	No system										518
	Gbenkoro	300	No system										517
	Kemeya	400	No system										523
	Keria	200	No system										519
	Konbaia	400	No system										520
	Sinkoro	300	No system										514

Nieni (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Wally</u>												
	Sokurolia	300	No system									521
	Yambia	200	No system									516
	Yarriasokurela	400	No system									515

5 sections 113 villages - 94 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Nieni - summary / 19 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	5	1 400	0	0 (0%)	5	5 (100%)	2 (40%)	3 (60%)	0 (0%)
hand dug well	41	24 664	5	8 (19,5%)	36	23 (64%)	11 (27%)	12 (29%)	13 (32%)
	46	26 064	5	8 (17,4%)	41	28 (68%)	13 (28%)	15 (33%)	13 (28%)

Sengbeh (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Bendugu</u>												
	Bendugu	1230	1/2 - hand dug well	2008	NACSA	dry 12 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 597
			2/2 - hand dug well	1983	Care	pump broken	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 598
	Ismailia	735	hand dug well	1982	UNDP	working	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 596
	Kondeya	375	1/5 - pulley	2004	Care	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 591
			2/5 - hand dug well	2007	UNICEF	working	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 592
			3/5 - pulley	2004	CCF	dry 5 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 593
			4/5 - hand dug well	1983	Care	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 594
			5/5 - hand dug well	2003	Other	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 595
	Malaforia	750	1/2 - hand dug well	1982	UNICEF	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 589
			2/2 - hand dug well	1983	UNICEF	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 590
	Malalsonia 2	87	No system									599
	Nyfrondoh	417	1/2 - hand dug well	2010	CRS	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 587
			2/2 - hand dug well	1983	Care	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 588
	Nymadugu	217	hand dug well	1983	Care	dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 585
	Yifunufeh	80	hand dug well	2007	Care	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 586
<u>Heremakonor</u>												
	Compala	185	1/2 - hand dug well	1983	Care	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 565
			2/2 - pulley	2003	Care	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 566
	Darsalam	203	1/2 - hand dug well	2006	Caritas	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 573
			2/2 - pulley	2006	Care	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 574
	Fonoiyoya	120	hand dug well	1983	Care	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 564
	Gbenikoro	749	1/9 - hand dug well	2006	CRS	pump broken	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 575
			2/9 - hand dug well	1980	UNDP	dry 2 months/year	PB2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 576
			3/9 - pulley	2006	Care	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 577
			4/9 - hand dug well	2010	Other	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 578
			5/9 - hand dug well	2006	Care	dry 3 months/year	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 579
			6/9 - pulley	2006	Care	dry 1 month/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 580
			7/9 - pulley	2006	Care	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 581
			8/9 - pulley	2006	Care	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 582

Sengbeh (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Heremakonor</u>												
	Gbenikoro	749	9/9 - hand dug well	2007	Other	dry 12 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 584
	K.Sansan	75	1/2 - pulley	2003	Care	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 567
		92	2/2 - pulley	2006	Care	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 568
	Momodumania	602	1/4 - pulley	1982	Care	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 569
			2/4 - pulley	2006	Care	dry 4 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 570
			3/4 - pulley	2006	Care	dry 12 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 571
			4/4 - pulley	2006	Care	dry 4 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 572
	Tirinya	420	No system									583
<u>Koinadugu</u>												
	Banbukono	350	1/5 - hand dug well	1983	CARE	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 533
			2/5 - hand dug well	1983	CARE	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 534
		715	3/5 - hand dug well	1983	CARE	dry 2 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 535
			4/5 - hand dug well	2008	Cause Canada	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 536
		117	5/5 - hand dug well	1983	CARE	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 537
	Dundukoh	470	hand dug well	1983	CARE	dry 4 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 531
	Kalkoya	350	hand dug well	2007	Red Cross	dry 4 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 528
	Koinadugu	1190	1/4 - hand dug well	2004	CARE	not finished						- 524
			2/4 - pulley	1983	CARE	dry 4 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 525
			3/4 - hand dug well	1983	CARE	dry 4 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 526
			4/4 - hand dug well	2007	NACSA	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 527
	Seduya	230	hand dug well	1983	CARE	dry 4 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 532
	Sengbelora	115	1/2 - hand dug well	1984	CARE	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 529
			2/2 - hand dug well	2004	CARE	not finished						- 530
<u>Lower Kamadug</u>												
	Fandugu	1321	1/3 - hand dug well	2006	Red Cross	dry 4 months/year	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 548
			2/3 - hand dug well	2007	CCF	dry 2 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 549
			3/3 - hand dug well	2007	CRS	dry 7 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 550
	Fasanoeya	452	1/4 - pulley	2003	Care	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 556
			2/4 - hand dug well	2005	Other	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 557

Sengbeh (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Lower Kamadug</u>												
	Fasanoeya	452	3/4 - hand dug well	1987	UNDP	working	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 558
			4/4 - pulley	2005	Other	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 559
	Fodaya	85	pulley	1987	UNDP	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 560
K.Sokunala		1248	1/7 - hand dug well	1987	UNDP	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 538
			2/7 - hand dug well	1982	UNDP	dry 11 months/year	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 539
			3/7 - hand dug well	2007	UNICEF	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 540
			4/7 - hand dug well	2007	UNICEF	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 541
			5/7 - hand dug well	1982	UNDP	dry 4 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 542
			6/7 - hand dug well	1987	UNDP	dry 3 months/year	PB2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 543
			7/7 - hand dug well	2007	CCF	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 544
Komoya	315	hand dug well	1982	UNDP		dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 551
Mantykauya	68	pulley	2005	Other		dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 563
Nalsayie		235	1/4 - pulley	2004	Caritas	dry 3 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 552
			2/4 - hand dug well	2003	Cause Canada	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 553
			3/4 - pulley	2004	Cause Canada	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 554
			4/4 - pulley	2004	Cause Canada	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 555
Sangbamgbo		715	1/3 - hand dug well	2006	Red Cross	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 545
			2/3 - hand dug well	2005	Caritas	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 546
			3/3 - hand dug well	2005	Caritas	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 547
Sesela	347	No system										561
Teminie Moria	424	No system										562
<u>Upper Kamadug</u>												
Badalah		171	1/4 - hand dug well	2006	Caritas	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 600
			2/4 - hand dug well	2006	Caritas	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 601
			3/4 - hand dug well	2006	Caritas	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 602
			4/4 - hand dug well	2007	OTHER	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 603
Danabalie	302	hand dug well	2006	Caritas		dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 605
Dankawali		1133	1/6 - hand dug well	2007	UNICEF	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 609
			2/6 - hand dug well	2006	Caritas	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 610

Sengbeh (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Upper Kamadug</u>												
Dankawali	1133	3/6 - hand dug well	1982	UNDP		dry 3 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 611
	3400	4/6 - hand dug well	2008	Other		not finished						- 612
		5/6 - hand dug well	1982	UNDP		dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 613
		6/6 - hand dug well	2008	CCF		dry 5 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 614
Kasuyah	240	hand dug well	2006	Caritas		dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 604
Kayonkoya	345	No system										616
Tinkifira	620	1/3 - hand dug well	2006	Caritas		dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 606
		2/3 - hand dug well	2007	SALWACO		working	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 607
		3/3 - hand dug well	2006	Caritas		dry 6 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 608
Yirafilaya Badela	316	No system										615
<u>Yiraya</u>												
Konkoya	854	1/2 - hand dug well	2009	Red Cross		dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 627
		2/2 - hand dug well	2009	Red Cross		dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 628
Moria	380	1/2 - hand dug well	2007	Red Cross		dry 3 months/year	PB2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 622
		2/2 - hand dug well	2007	Red Cross		working	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 623
Sankaria	955	1/3 - hand dug well	1989	Red Cross		dry 3 months/year	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 624
		2/3 - hand dug well	2009	Red Cross		dry 2 months/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 625
		3/3 - hand dug well	2009	SABABU		working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 626
Yiraya	1205	1/5 - hand dug well	2007	Red Cross		dry 5 months/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 617
		2/5 - hand dug well	2005	Red Cross		pump broken	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 618
		3/5 - pulley	1986	UNDP		dry 4 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 619
		4/5 - hand dug well	2007	MDM		dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 620
		5/5 - hand dug well	2005	NACSA		dry 6 months/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 621

Sengbeh (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.
---------	---------	--------------------	-------------	------	---------	------------	-----------	---------------	-----------------	------------------	-----------------

6 sections 42 villages - 6 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Sengbeh - summary / 36 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
hand dug well	76	61 437	3	13 (17,1%)	73	50 (68%)	20 (26%)	36 (47%)	17 (22%)
	76	61 437	3	13 (17,1%)	73	50 (68%)	20 (26%)	36 (47%)	17 (22%)

Sulima (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Dara</u>												
	Dara	300	No system									1313
	Kondaya	110	No system									1314
<u>Falaba 1</u>												
	Falaba	644	1/7 - hand dug well	1982	UNDP	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			2/7 - hand dug well	2010	UNDP	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			3/7 - hand dug well	2004	SADAL	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			4/7 - hand dug well	1982	UNDP	dry 4 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			5/7 - hand dug well	2010	CRS	not finished						-
			6/7 - hand dug well	2000	OTHER	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			7/7 - hand dug well	2007	Cause Canada	dry 4 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Manaday	130	hand dug well	2004	SADAL	dry 5 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Managbay	152	No system									1252
	Samun	250	No system									1253
<u>Falaba 2</u>												
	Falaba	263	1/8 - hand dug well	1982	UNDP	dry 2 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			2/8 - hand dug well	1982	UNDP	dry 3 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			3/8 - hand dug well	2004	NACSA	not finished						-
			4/8 - hand dug well	2004	SADAL	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			5/8 - hand dug well	2005	UNICEF	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			6/8 - hand dug well	1982	UNDP	working	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			7/8 - hand dug well	1982	SADAL	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			8/8 - hand dug well	2010	UNDP	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Foremura	151	hand dug well	2010	CRS	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK
	Kankaya	150	hand dug well	2004	UNDP	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Tambadia	50	hand dug well	2004	OTHER	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
<u>Fodaya</u>												
	Fodayia	200	No system									1232
	Futaredec	60	No system									1231
	Lamaya	300	No system									1233

Sulima (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Fodaya</u>												
	Maporo	50	No system									1230
	Maporo J	1500	hand dug well	2009	CRS	working	OTHER	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Tanene	120	hand dug well	2009	CRS	working	OTHER	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
<u>Ganya</u>												
	Ganya	400	1/5 - hand dug well	1984	Islamic Development Asso	dry 6 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/5 - hand dug well	1984	Islamic Development Asso	dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			3/5 - hand dug well	1984	Islamic Development Asso	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			4/5 - hand dug well	2009	NACSA	working	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			5/5 - hand dug well	2009	CRS	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Karifaya	200	No system									1217
	Kumansaseguria	250	No system									1218
	Saluya1	250	No system									1219
	Saluya2	175	No system									1220
	Tumania	150	No system									1216
	Yemanyereya	200	No system									1221
<u>Gberia Timbako</u>												
	Bamako	100	No system									1305
	Bribia	350	hand dug well	2009	CRS	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Dansiakory	300	No system									1301
	G Timbako	400	1/8 - hand dug well	2010	CRS	working	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			2/8 - hand dug well	2004	CRS	working	OTHER	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			3/8 - hand dug well	1982	UNDP	not finished						-
			4/8 - pulley	1982	UNDP	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			5/8 - hand dug well	1982	UNDP	not finished						-
			6/8 - hand dug well	1982	UNDP	not finished						-
			7/8 - hand dug well	1982	UNDP	not finished						-
			8/8 - pulley	1982	UNDP	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Karibu	230	No system									1303
	Kohba	230	No system									1300

Sulima (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
Gberia Timbako													
	Menden	200	No system									1302	
	Sogonya	1100	No system									1304	
Geria Fotombu													
G Fotombu		800	1/4 - hand dug well	1982	UNDP	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	1285
			2/4 - hand dug well	1982	UNDP	not finished						-	1286
			3/4 - hand dug well	2010	CRS	not finished						-	1287
			4/4 - hand dug well	2010	SADAL	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1288
Mesendeku		170	1/2 - hand dug well	2010	CRS	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	1289
			2/2 - hand dug well	1982	UNDP	pump broken	PB2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1290
Yogobay		107	1/2 - hand dug well	2010	CRS	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1283
			2/2 - hand dug well	1982	UNDP	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1284
Kaliyereh													
	Bajuguya	164	No system										1281
Kaliyere		900	1/4 - pulley	1982	UNDP	dry 4 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1277
			2/4 - hand dug well	1982	UNDP	not finished						-	1278
			3/4 - hand dug well	1982	UNDP	not finished						-	1279
			4/4 - hand dug well	2007	Cause Canada	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal	1280
	Konikuday	205	No system										1282
Kambaia													
Kalia		400	1/3 - pulley	1982	UNDP	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1239
			2/3 - hand dug well	1982	UNDP	pump broken	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1240
			3/3 - hand dug well	2007	Cause Canada	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal	1241
Kambaia		533	1/3 - hand dug well	2010	CRS	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1236
			2/3 - pulley	1982	UNDP	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1237
			3/3 - pulley	1982	UNDP	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1238
T Dansa		625	1/2 - hand dug well	2010	CRS	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	1242
			2/2 - hand dug well	1982	OTHER	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1243
Yendenya		225	1/2 - pulley	1982	UNDP	dry 3 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	1234
			2/2 - hand dug well	2007	Cause Canada	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	1235

Sulima (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Kambaiia</u>												
<u>Koindu Kura</u>												
Koindu K	177	1/7 - hand dug well	2010	CRS		working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1265
		2/7 - hand dug well	2009	NACSA		working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1266
		3/7 - hand dug well	1982	UNDP		not finished						- 1267
		4/7 - hand dug well	1982	UNDP		not finished						- 1268
		5/7 - hand dug well	2006	NACSA		not finished						- 1269
		6/7 - hand dug well	1982	UNDP		not finished						- 1270
		7/7 - hand dug well	1982	UNDP		pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1271
<u>Leley</u>												
Leley	150	pulley	1982	UNDP	-	no pump		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1222
<u>Limbaiia</u>												
Limbaia	287	1/4 - hand dug well	2007	Cause Canada		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1272
		2/4 - hand dug well	2007	CRS		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1273
		3/4 - hand dug well	2005	UNDP		dry 4 months/year	IM2 - stolen	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1274
		4/4 - hand dug well	2005	UNDP		dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1275
Walia	60	No system										1276
<u>Nomokoya</u>												
Fadugu	140	No system										1312
Gbanka	200	No system										1306
Gullusanya	250	No system										1311
Kabuya	250	No system										1307
Kamthamina	340	hand dug well	2009	CRS		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1197
Karibon	300	hand dug well	2009	CRS		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1199
Kidoya	200	No system										1308
Makaya	150	No system										1310
Nomokoya	600	hand dug well	2004	Cause Canada		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 1198
Sabuya	160	No system										1309
<u>Simitiya</u>												
Bianbu	400	No system										1209

Sulima (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Simitiya</u>												
	Dansadia	1500	hand dug well	2010	CRS	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1207
	Duraya	650	1/2 - pulley	1982	KIADP	dry 6 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1205
			2/2 - hand dug well	2010	CRS	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1206
	Kanaya	300	No system									1208
	Kankaba	400	hand dug well	2005	CRS	not finished						- 1200
	Kidoya	180	No system									1210
	Simithia	425	1/4 - pulley	1982	KIADP	dry 6 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1201
			2/4 - pulley	1982	KIADP	dry 6 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1202
			3/4 - hand dug well	2010	KIADP	dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1203
			4/4 - hand dug well	2007	Other	not finished						- 1204
<u>Sonkoya</u>												
	Dugurury	1500	hand dug well	2010	CRS	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1227
	Sonkoya	750	1/4 - hand dug well	2005	OTHER	not finished						- 1223
			2/4 - hand dug well	1980	KIADP	working	PB2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1224
			3/4 - hand dug well	1980	KIADP	working	PB2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1225
			4/4 - hand dug well	2005	Other	not finished						- 1226

15 sections 64 villages - 33 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee: presence of a Committee of Users

Pump CareTaker: a person trained to maintain the pump

Tools Spare Parts: are available in the community

Money contribution: is done by the community for maintenance

Sulima - summary / 31 villages					P U M P		SEASONALITY		
Type	Total	Popul. Approxim	Not finished	Functional all the year	installed	working	Dry>3m	seasonal	Alw. water
hand dug well	74	34 252	18	24 (32,4%)	55	38 (69%)	11 (15%)	9 (12%)	36 (49%)
	74	34 252	18	24 (32,4%)	55	38 (69%)	11 (15%)	9 (12%)	36 (49%)

Wara Wara Yagala (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Heremakono</u>												
	Bendukura	500	1/4 - pulley	2005	Care	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			2/4 - pulley	1983	Undp	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			3/4 - pulley	2005	CARE	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			4/4 - hand dug well	1985	UNICEF	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Heremakono	450	1/3 - hand dug well	1983	UNDP	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
			2/3 - hand dug well	1983	UNDP	not finished						-
			3/3 - hand dug well	2005	UNICEF	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Kenema	209	1/2 - hand dug well	2006	CRS	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/2 - hand dug well	1983	UNDP	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
<u>Timbo</u>												
	Affia	500	1/3 - hand dug well	2001	UNDP	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			2/3 - hand dug well	2005	UNICEF	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal
			3/3 - hand dug well	1984	UNDP	dry 2 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Kasasi	55	hand dug well	2006	CCF	dry 3 months/year	PB2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Mile 82	150	hand dug well	2009	District Council	working	PB2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
<u>Yagala</u>												
	Igia	210	1/2 - hand dug well	2007	UNICEF	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			2/2 - pulley	2004	CARE	dry 5 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kakondoi	315	hand dug well	1982	UNDP	pump broken	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kamabonka	150	1/2 - hand dug well	1982	UNDP	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
			2/2 - pulley	2005	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kamanso	110	pulley	2005	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kamasape	140	No system									764
	Kamasokola	220	1/2 - pulley	1983	UNDP	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/2 - hand dug well	2003	MSF	pump broken	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kanuka	410	1/2 - hand dug well	1983	UNDP	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal
			2/2 - hand dug well	2007	UNICEF	dry 6 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kapendiyokor	260	1/4 - hand dug well	2008	District Council	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
		350	2/4 - hand dug well	2000	CCF	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal

Wara Wara Yagala (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Yagala</u>												
	Kapendiyokor	70	3/4 - hand dug well	2010	SABABU	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 751
			4/4 - hand dug well	1984	UNDP	pump broken	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 752
	Karainkay	95	No system									768
	Kasantiya	93	No system									769
	Kasumpe	125	1/2 - pulley	2004	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 739
			2/2 - hand dug well	1983	UNDP	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 740
	Kathantiyeh	300	hand dug well	2008	CCF	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 758
	Kathombo 1	330	hand dug well	2005	CCF	dry 3 months/year	PB2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 760
	Kaworsur	296	No system									763
	Kayankula	105	No system									767
	Kayogobay	105	pulley	2005	CARE	dry 12 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 742
	Kodala	150	pulley	2004	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 746
	Konkoya	450	1/3 - hand dug well	2008	SABABU	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 743
			2/3 - hand dug well	1983	UNDP	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 744
			3/3 - pulley	2004	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 745
	Kuraykorma1	100	No system									765
	Kuraykorma2	100	No system									766
	Yagala	488	hand dug well	2005	OTHER	dry 7 months/year	PB2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 759
		400	hand dug well	2007	OTHER	working	OTHER	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 761
		500	hand dug well	2006	OTHER	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 757
<u>Yakor</u>												
	Kamayimbor	125	hand dug well	2005	Cause Canada	dry 3 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 823
	Katawoya	1470	hand dug well	1985	UNDP	dry 2 months/year	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 828
	Kayakor	1200	hand dug well	2005	UNICEF	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 826
	Konkorba	2010	spring box	2009	MDM	working	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 827
	Koyogobay	360	hand dug well	2008	Other	dry 4 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 829
	Lenkekoro	150	hand dug well	1979	UNDP	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 824
	Tonkoya	160	hand dug well	2010	MDM	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 825

Wara Wara Yagala (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Yataya</u>												
	Alusaniya	270	1/2 - hand dug well	2009	Cause Canada	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 770
			2/2 - hand dug well	1984	UNDP	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 771
	Karkoh Sokurala	1010	hand dug well	1983	UNDP	dry 3 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 804
	Makakuria	400	hand dug well	1983	UNDP	working	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 772
	Mamudia Koro	300	1/5 - hand dug well	2005	CARE	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 788
			2/5 - hand dug well	2005	UNDP	dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 789
		450	3/5 - hand dug well	2005	CCF	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 790
			4/5 - pulley	1984	UNDP	dry 4 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 791
			5/5 - pulley	2005	CARE	dry 6 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 792
	Pebu	41	1/10 - hand dug well	2005	IMAT	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 778
			10/10 - pulley	2005	IMAT	dry 4 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 787
			2/10 - hand dug well	2005	IMAT	dry 2 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 779
			3/10 - hand dug well	2005	IMAT	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 780
			4/10 - hand dug well	2005	IMAT	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 781
			5/10 - hand dug well	2005	IMAT	dry 4 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 782
			6/10 - hand dug well	2005	IMAT	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 783
			7/10 - hand dug well	2005	IMAT	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 784
			8/10 - hand dug well	2005	IMAT	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 785
			9/10 - hand dug well	2005	IMAT	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 786
	Sarakoh	230	1/2 - hand dug well	2009	SABABU	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 776
		450	2/2 - hand dug well	1982	UNDP	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 777
	Senekedugu	1100	1/5 - hand dug well	1982	UNDP	dry 5 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 797
			2/5 - hand dug well	1983	UNDP	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 798
			3/5 - hand dug well	2007	UNICEF	dry 7 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 799
			4/5 - hand dug well	2006	SABABU	not finished						800
			5/5 - hand dug well	2002	CCF	pump broken	PB2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 801
	Sokurala-B	250	1/3 - pulley	2006	CARE	dry 3 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 773
			2/3 - hand dug well	1983	UNDP	dry 3 months/year	PB2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 774
			3/3 - pulley	2006	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 775

Wara Wara Yagala (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Yataya</u>												
	Songoaballaio	300	1/2 - hand dug well	2007	CCF	dry 3 months/year	PB2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 802
			2/2 - hand dug well	1982	UNDP	dry 2 months/year	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 803
sulamania		490	1/4 - pulley	2005	CARE	dry 12 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 793
			2/4 - hand dug well	2007	OTHER	not finished						- 794
			3/4 - hand dug well	2007	OTHER	not finished						- 795
			4/4 - hand dug well	2003	UNICEF	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 796
Timbo Sokurala		900	1/2 - hand dug well	1983	UNDP	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 805
			2/2 - hand dug well	1983	UNDP	dry 3 months/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 806
Yatayah		600	1/2 - hand dug well	1984	UNDP	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 807
			2/2 - pulley	2005	Care	dry 12 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 808

5 sections 46 villages - 7 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee: presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Wara Wara Yagala - summary / 39 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
hand dug well	67	27 215	4	11 (16,4%)	63	46 (73%)	6 (9%)	34 (51%)	23 (34%)
	67	27 215	4	11 (16,4%)	63	46 (73%)	6 (9%)	34 (51%)	23 (34%)

Wara Wara Bafodia (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Bafodia												
	AL-HAKA	350	1/2 - hand dug well	2007	Cause Canada	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 97
		178	2/2 - hand dug well	2005	NACSA	dry 3 months/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 94
	B C H C	178	1/2 - hand dug well	1992	OTHER	dry 1 month/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 90
			2/2 - hand dug well	2010	Cause Canada	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 91
	B. A. S. S.	178	hand dug well	2007	Cause Canada	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 95
	Kabathie	120	No system									106
	Kakisiya	300	No system									103
	Kakuwodor	110	No system									107
	Kamadand	350	hand dug well	2007	Caritas	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 96
	Kamagbeh	250	hand dug well	1984	UNDP	dry 3 months/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 98
	Kamaka	120	No system									104
	Kamakondorbor	180	No system									100
	Kamakunor	123	No system									102
	Kamakurakunthay	120	No system									99
	Kamarena	80	No system									105
	Kasengbeh	250	No system									101
	Kayorhor		No system									108
	W C S L 1	178	hand dug well	1992	SABABU	not finished					-	92
	W C S L 2	178	hand dug well	2007	NACSA	dry 3 months/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 93
Kadanso												
	Kadanso	300	1/2 - hand dug well	2007	Cause Canada	dry 4 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 19
			2/2 - hand dug well	2007	Red Cross	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 20
	Kademgblelen	200	No system									25
	Kadendeh	85	No system									28
	Kahartha	95	No system									30
	Kahatha	96	No system									37
	Kakayor	106	No system									33
	Kakonso	500	hand dug well	2006	Cause Canada	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 18

Wara Wara Bafodia (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
<u>Kadanso</u>													
	Kamabubu1	45	No system									34	
	Kamabubu2	45	No system									35	
	Kamachen	70	No system									41	
	Kamadina	98	No system									42	
	Kamagbase	84	No system									38	
	Kamagbesena1	49	No system									31	
	Kamagbesena2	49	No system									32	
	Kamakainda	105	No system									22	
	Kamakeya	104	No system									26	
	Kamakonie	114	No system									23	
	Kamasompo	95	No system									27	
	Kamatheru	75	No system									29	
	Kanlena	80	No system									36	
	Kathadubu	101	No system									24	
	Katheneh1	35	No system									39	
	Katheneh2	35	No system									40	
	Kayenda	505	hand dug well	2006	Caritas	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	21
<u>Kamagbosie</u>													
	Kamabie	371	No system									61	
	Kopra	270	No system									60	
	Lumbahria	120	No system									59	
	Yanka	90	No system									58	
	Yankafer	300	No system									62	
<u>Kamanikie</u>													
	Kabasain	120	No system									130	
	Kamakuronthay	154	No system									128	
	Kamaninkie	105	1/2 - hand dug well	2006	Cause Canada	dry 1 month/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	124
			2/2 - hand dug well	2007	OTHER	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	125

Wara Wara Bafodia (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Kamanikie												
	Kamapindorkor	50	No system									132
	Kamawelebu	140	No system									129
	Kapakie	164	No system									127
	Kathakeyan	64	No system									133
	Kayimbor	94	No system									131
	Konkondobie	150	No system									126
Kambalia												
	Kafadugu	220	No system									89
	Kakusener	230	No system									86
	Kamaipopitorkor	250	No system									88
	Kambalia	125	1/2 - hand dug well	1992	NACSA	dry 3 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			2/2 - hand dug well	1992	NACSA	not finished						-
	Kasengben	200	No system									87
Kaponpon												
	Kadanka	455	1/2 - hand dug well	2006	Caritas	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/2 - hand dug well	2007	Red Cross	dry 5 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kadenda	150	No system									9
	Kakusan	65	No system									10
	Kamabede	50	No system									15
	Kamagbonkein	59	No system									12
	Kamakayah	40	No system									16
	Kamama	78	No system									14
	Kamaran	48	No system									8
	Kamaregben	38	No system									17
	Kasenthethé	175	hand dug well	2007	Caritas	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Kathaka	98	No system									11
	Kathekeyan	55	No system									6
	Kathengben	63	No system									13

Wara Wara Bafodia (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Kaponpon												
	Kayonkoi	60	No system									7
	W C S L Kasenthethethe	175	hand dug well	2007	Caritas	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 3
	WCSI Kaponpon	408	hand dug well	1987	UNDP	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1
Madina												
	Kasakapie	150	No system									57
	Madina	500	No system									56
Mandia												
	Kamakarayna	140	No system									68
	Kamaso	120	No system									67
	Kaworkor	200	No system									66
	Mandia	83	1/3 - hand dug well	1983	UNDP	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 63
			2/3 - hand dug well	1983	UNDP	dry 3 months/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 64
			3/3 - hand dug well	1983	UNDP	dry 2 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 65
Saicuta												
	Kabonkin	110	No system									121
	Kagbodor	200	No system									122
	Kakoya	350	hand dug well	2007	Caritas	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 113
		194	1/4 - hand dug well	1984	UNDP	dry 3 months/year	PB2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 109
			2/4 - hand dug well	2008	Cause Canada	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 110
			3/4 - hand dug well	2007	SABABU	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 111
	Kamasakar		4/4 - hand dug well	2005	Caritas	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 112
		103	No system									123
		105	No system									120
		200	1/2 - hand dug well	2007	Caritas	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 118
	Saicuta		2/2 - hand dug well	2007	Caritas	not finished						- 119
		375	1/4 - hand dug well	1998	UNDP	dry 2 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 114
			2/4 - hand dug well	2006	UNICEF	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 115
	Saicuta		3/4 - hand dug well	1986	UNDP	dry 2 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 116

Wara Wara Bafodia (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Saicuta</u>	Saicuta	375	4/4 - hand dug well	2010	NACSA	dry 1 month/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 117
<u>Saymaya</u>	Kagbaken	65	No system									53
	Kagbugu	56	No system									54
	Kamabanya	83	No system									55
	Kamadondo	160	No system									51
	Kamakonkosar	92	No system									50
	Kamakoso	108	No system									49
	Kamakukura	80	No system									48
	Kasoka	106	No system									46
	Kasorthor	250	No system									45
	Kathayeh	78	No system									47
	Kathegben	50	No system									44
	Seredugu	600	No system									52
	Syamaya	1800	hand dug well	1995	UNDP	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 43
<u>Serekunday</u>	Kabalina	180	No system									74
	Kalalauyonyon	210	No system									72
	Kamasordor	230	No system									71
	Kasasie	200	No system									73
	Serekunday	150	1/2 - hand dug well	1992	NACSA	dry 3 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 69
			2/2 - hand dug well	1992	NACSA	not finished						70
<u>Thalia</u>	Dalipothor	130	hand dug well	1992	UNDP	dry 4 months/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 82
	Kabakuda	180	hand dug well	1993	UNDP	dry 4 months/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 81
	Kafarana	230	hand dug well	1990	UNDP	dry 4 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 80
	Kosay	280	hand dug well	1993	UNDP	dry 4 months/year	PB2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 83
	Thalia	260	1/5 - hand dug well	1992	UNDP	dry 2 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 75

Wara Wara Bafodia (Koinadugu)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Thalia</u>	Thalia	260	2/5 - hand dug well	1992	NACSA	dry 3 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 76
			3/5 - hand dug well	1993	NACSA	dry 3 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 77
			4/5 - hand dug well	1994	NACSA	dry 3 months/year	PB2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 78
			5/5 - hand dug well	1994	NACSA	not finished						79

12 sections 113 villages - 85 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Wara Wara Bafodia - summary / 28 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
hand dug well	48	13 246	5	2 (4,2%)	44	27 (61%)	7 (15%)	34 (71%)	2 (4%)
	48	13 246	5	2 (4,2%)	44	27 (61%)	7 (15%)	34 (71%)	2 (4%)

Gbonkolenken (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Lower Masakon</u>												
	Katema		No system									260
	Macankay		No system									259
	Madeba		No system									262
	Maforobi	500	hand dug well	2001	SALWACO	dry 3 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 251
	Magbangba	200	hand dug well	2002	ACF	dry 1 month/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 250
	Magbuneh	600	hand dug well	2001	ACF	dry 1 month/year	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 252
	Makadeh	1500	hand dug well	2003	ACF	dry 5 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 249
	Makeba		No system									258
	Makereh		No system									261
	Mamorsiray	250	hand dug well	2001	ACF	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 255
	Mamurankay		No system									256
	Marofore	300	1/2 - pulley	2007	Africa Muslim Agency	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 253
		150	1/2 - pulley	2007	CARE	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 254
	Masuman		No system									257
	Masumana	500	1/3 - hand dug well	2000	ACF	dry 5 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 246
		300	2/3 - hand dug well	2008	ACF	not finished						- 247
			3/3 - pulley	2000	MRC	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 248
	Mayesi	600	1/2 - hand dug well	2001	ACF	dry 5 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 243
		100	2/2 - hand dug well	2001	UNICEF	dry 5 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 244
	Patifu 2	550	hand dug well	2002	SALWACO	dry 4 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 245
<u>Lower Poli</u>												
	Mafunk	200	pulley	2008	CARE	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 291
	Magbokeh	700	hand dug well	2004	CARE	dry 2 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 290
	Magbolu Bana		No system									295
	Magbolu Lol		No system									300
	Magbulu Ferry	1000	pulley	2003	Africa Muslim Agency	dry 4 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 292
	Makorgba	335	pulley	2006	CARE	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 285
	Maraka	400	1/4 - hand dug well	2007	ACF	dry 5 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 286

Gbonkolenken (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
<u>Lower Poli</u>													
	Maraka	300	2/4 - hand dug well	2002	SALWACO	dry 5 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	287
		500	3/4 - hand dug well	2002	CARE	dry 5 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	288
		100	4/4 - hand dug well	2007	MRC	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	289
	Maruba	300	hand dug well	2002	CARE	dry 4 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	293
	Matetan		No system										298
	Mathonoh		No system										299
	Mayera		No system										294
	Mayoko Patifu		No system										297
	Ronulla Line	250	pulley	2005	CARE	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	282
	Ropoli	150	hand dug well	2000	SALWACO	dry 1 month/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	283
	Royeama	400	hand dug well	2003	ACF	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	284
	Rufuthaneh		No system										296
<u>Mayepoh</u>													
	Mabai	250	No system										204
	Mabeti	400	hand dug well	2008	SALWACO	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	194
	Mafoyoka	50	No system										206
	Magbama	300	hand dug well	2008	SALWACO	not finished						-	190
	Makerah	350	hand dug well	2008	SALWACO	not finished						-	189
	Makonkori	350	1/4 - hand dug well	2003	ACF	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	181
		100	2/4 - hand dug well	2008	SALWACO	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	182
		300	3/4 - pulley	2006	Africa Muslim Agency	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	183
		450	4/4 - hand dug well	2007	4 HIM	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	184
	Mapankle	300	hand dug well	2009	SALWACO	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	188
	Masaymoi	300	pulley	2008	Africa Muslim Agency	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	195
	Masimbra	250	hand dug well	2008	SALWACO	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	180
	Masinbra	45	No system										211
	Matombo	100	1/3 - hand dug well	2008	SALWACO	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	185
		500	2/3 - hand dug well	2008	KORIA	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	186

Gbonkolenken (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Mayepoh</u>												
	Matombo	350	3/3 - hand dug well	2002	ACF	pump broken	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 187
	Mayorpoh	600	1/3 - hand dug well	2000	ACF	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 191
		200	2/3 - pulley	2008	MRC	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 192
			3/3 - hand dug well	2010	Other	not finished						- 193
	Robise	100	No system									205
	Robonthoo	30	No system									208
	Robun	40	No system									210
	Rogbutu	40	No system									207
	Roline Kanawara	50	No system									199
	Roline Kapasanna	200	No system									198
	Rolungai	300	No system									203
	Roma Kargbo	250	No system									200
	Romangero	450	hand dug well	2003	ACF	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 179
	Romawolman	300	No system									201
	Ronorllah	70	No system									209
	Roponnatank	40	No system									213
	Roranka	250	No system									197
	Rosarr	150	No system									214
	Rosent	150	No system									212
	Rotiama	400	No system									202
	Small Makeni	80	No system									196
<u>Paitfumayepoh</u>												
	Mabankra	300	hand dug well	2000	ACF	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 225
	Mabar	450	1/2 - hand dug well	2002	ACF	dry 4 months/year	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 222
			2/2 - pulley	2006	Africa Muslim Agency	dry 5 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 223
	Maburah	750	1/2 - hand dug well	2002	ACF	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 218
		200	2/2 - hand dug well	2008	SALWACO	not finished						- 219
	Makarbai	300	No system									237

Gbonkolenken (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Paitumayepoh												
	Makenteh	400	1/2 - hand dug well	2003	ACF	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 226
			2/2 - hand dug well	2008	SALWACO	not finished						- 227
	Massawa	10	No system									242
	Paitumayapoti	100	1/6 - hand dug well	2005	SALWACO	not finished						- 228
			2/6 - hand dug well	2003	ECC	working	OTHER	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 229
		200	3/6 - hand dug well	2003	ECC	not finished						- 230
			4/6 - hand dug well	2003	ECC	dry 2 months/year	Pb2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 231
		400	5/6 - hand dug well	1999	CARE	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 232
		100	6/6 - hand dug well	NA	KORIA	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 233
	Paitifu Limba	250	1/2 - hand dug well	2005	Other	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 220
		100	2/2 - hand dug well	2008	SALWACO	not finished						- 221
	Rofunk	10	No system									241
	Rogbabai	50	No system									235
	Rogbesseh	150	No system									236
	Rollot	20	No system									240
	Romadina	80	No system									239
	Romafala	30	No system									238
	Romalpha	60	No system									234
	Romano	300	hand dug well	2008	SALWACO	not finished						- 216
	Romoyamba	800	hand dug well	2001	ACF	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 224
	Romsar	200	hand dug well	2008	SALWACO	not finished						- 215
	Royama	150	hand dug well	2008	SALWACO	not finished						- 217
Paitifumayawa												
	Doyullah	80	No system									315
	Maboot	200	No system									327
	Mafainka	90	No system									323
	Mafay	300	No system									319
	Makakissa	80	No system									321

Gbonkolenken (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Paitifumayawa</u>												
	Makalie	60	No system									316
	Makenenday	250	No system									326
	Mamambo	150	No system									318
	Mamity	50	No system									309
	Mapothika	200	No system									324
	Masobi 1	180	No system									320
	Mathombo 2	40	No system									313
	Mayembray	100	No system									325
	Paitifumayawa	500	1/2 - hand dug well	1974	Seventh Day Adventist	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
			2/2 - hand dug well	1994	CARITAS	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Robath Pillah	260	No system									312
	Robish	216	No system									331
	Rokom	160	No system									322
	Rokontha	68	No system									314
	Romayllah	100	No system									328
	Romenday	100	pulley	2007	KUWAIT	dry 3 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Ropapa	200	No system									317
	Rosar1	100	No system									310
	Rosar2	250	No system									311
	Rothawa	200	No system									329
	Tawa Hill Junction	15	No system									330
	Yele	800	1/4 - hand dug well	2004	Catholic Mission	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
		900	2/4 - hand dug well	1990	SAPA	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
		200	3/4 - bore hole	2008	SALWACO	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			4/4 - hand dug well	2002	SALWACO	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Yele Simbeh	200	hand dug well	2001	SALWACO	dry 3 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
<u>Upper Masakon</u>												
	Bannie	200	No system									176

Gbonkolenken (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Upper Masakon</u>												
	Mabobo	150	pulley	2008	CARE	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 161
	Makalie	250	No system									178
	Makawo	400	pulley	2006	CARE	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 157
	Makenthie	50	No system									172
	Makompabolu	300	No system									170
	Makoso	250	No system									169
	Maramnek	200	No system									168
	Masalpah	200	No system									163
	Massakun	350	No system									164
	Matak	250	pulley	2007	Community	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 160
	Maworko	350	No system									171
	Rogbara	300	No system									165
	Roline Kana Soko	450	1/2 - pulley	2008	Africa Muslim Agency	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 155
		0	2/2 - hand dug well	2010	FAO	not finished						156
	Rolinekapabai	100	No system									167
	Romakankissa	70	No system									166
	Ronorlla	250	No system									177
	Tekohbana	200	No system									173
	Tekololo	230	No system									174
	Walbana I	350	No system									162
	Walbana II	500	hand dug well	2008	World Bank	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 154
	Warayma	500	1/2 - hand dug well	2001	ACF	pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 158
		100	2/2 - hand dug well	2007	NACSA	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 159
	Yeama	100	No system									175
<u>Upper Polie</u>												
	Komrabai	300	hand dug well	2002	SALWACO	dry 3 months/year	PB2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 148
	Mabar	800	hand dug well	2000	ACF	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 151
	Makoblo	70	No system									152

Gbonkolenken (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Upper Polie</u>												
	Masoria	450	hand dug well	2000	ACF	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 149
	Mathamp	200	1/4 - hand dug well	2002	ACF	dry 4 months/year	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 144
		300	2/4 - hand dug well	2005	CARE	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 145
		200	3/4 - pulley	2002	MRC	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 146
			4/4 - hand dug well	2010	UNICEF	not finished						- 147
	Rogbankan	100	No system									153
	Rothawa	600	pulley	2005	Africa Muslim Agency	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 150
<u>Yeben</u>												
	Mabaron	700	pulley	2007	Africa Muslim Agency	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 267
	Mabia		No system									274
	Mabutu		No system									271
	Magboba	250	pulley	2007	CARE	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 263
	Magbondoh	200	hand dug well	2007	CARE	not finished						- 268
	Magbuma		No system									272
	Magburaka Lol		No system									279
	Makonteh		No system									273
	Makump		No system									276
	Mayera		No system									269
	Patifu		No system									275
	Rogbanthang		No system									281
	Rokoma		No system									278
	Ronetur		No system									277
	Rothumu		No system									280
	Rothuu		No system									270
	Yeben	200	1/3 - pulley	2000	MRC	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 264
		208	2/3 - hand dug well	2008	CHRISTIAN CHILDREN F	dry 3 months/year	OTHER	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 265
		1000	3/3 - hand dug well	2004	ACF	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 266

Yele Manowa

Gbonkolenken (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Yele Manowa</u>												
	Komrabai	355	pulley	2004	Other	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 342
	Mabaimbay	113	No system									354
	Makomp	361	No system									347
	Makomrabai	533	No system									346
	Makoya	500	No system									359
	Malempeh	116	No system									357
	Malumpoh	197	No system									351
	Manowa	1015	pulley	2003	Other	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 341
	Marukoh	360	No system									365
	Mathamba	102	No system									352
	Matopie	108	No system									358
	Pintikili	112	No system									356
	Robekeloko	120	No system									362
	Roboff	103	No system									361
	Rochaindaro	403	No system									350
	Rochaindokom	207	No system									348
	Rogbanonkoh	350	No system									363
	Rogbarreh	300	No system									368
	Rokania	150	No system									367
	Rokel	50	No system									343
	Romaranko	153	No system									345
	Romurka	258	No system									355
	Ronetor	95	No system									364
	Rongola	49	No system									353
	Roroks	120	No system									344
	Rosint	171	No system									349
	Rotumu	96	No system									360
	Royeama	200	No system									366

Gbonkolenken (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Yele Manowa</u>												
	Yele	340	1/9 - hand dug well	2003	SALWACO	dry 3 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 332
			2/9 - hand dug well	2004	KUWAIT	working	OTHER	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 333
		500	3/9 - hand dug well	2003	SALWACO	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 334
		600	4/9 - hand dug well	2008	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 335
		500	5/9 - bore hole	2007	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 336
		311	6/9 - hand dug well	2008	Private	dry 2 months/year	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 337
		416	7/9 - hand dug well	1990	SALWACO	dry 2 months/year	IN - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 338
		150	8/9 - hand dug well	2002	DFID	dry 2 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 339
		370	9/9 - hand dug well	2009	SELH	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 340

9 sections 183 villages - 123 with no system at a

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee: presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Gbonkolenken - summary / 60 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	2	700	0	2 (100%)	2	2 (100%)	0 (0%)	0 (0%)	2 (100%)
hand dug well	77	28 735	15	10 (13%)	55	42 (76%)	14 (18%)	27 (35%)	21 (27%)
	79	29 435	15	12 (15,2%)	57	44 (77%)	14 (18%)	27 (34%)	23 (29%)

Kafe Simira (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
<u>Kaqbaya</u>													
	Bolaneh	600	No system									524	
	Magburaka Lol	350	No system									525	
	Makali	400	No system									522	
	Makumun	500	No system									523	
	Mamaya	400	No system									526	
<u>Kamaruku</u>													
	Kamaruku	800	No system									517	
	Maboi	700	No system									520	
	Mamusu	350	No system									518	
	Mayeriba	600	No system									519	
	Patefu	750	No system									521	
<u>Maonthadae</u>													
	Boloya	700	No system									464	
	Bradala	250	No system									467	
	Kabaray	400	No system									468	
	Koloya	250	No system									469	
	Maonthadae	300	1/7 - pulley	1998	CARE	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	453
		250	2/7 - pulley	1998	CARE	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	454
		500	3/7 - hand dug well	2007	SALWACO	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	455
		200	4/7 - pulley	1998	CARE	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	456
		300	5/7 - hand dug well	2010	UNICEF	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	457
		350	6/7 - pulley	2007	MRC	dry 4 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	458
		250	7/7 - hand dug well	2004	NACSA	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	459
	Makama	600	No system									465	
	Makaman	200	1/2 - hand dug well	2009	SALWACO	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	460
			2/2 - pulley	1998	CARE	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	461
	Tonkolili	104	1/2 - hand dug well	2009	HAMZA	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	462
		250	2/2 - hand dug well	2009	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	463

Kafe Simira (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
<u>Maconthadae</u>													
	Yarawaya	450	No system									466	
<u>Maforaka</u>													
	Mabonto	800	1/7 - hand dug well	2009	SALWACO	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	482
		700	2/7 - bore hole	2008	SALWACO	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	483
		400	3/7 - hand dug well	2010	JAPAN	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	484
		500	4/7 - pulley	1988	Other	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	485
		600	5/7 - hand dug well	2007	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	486
		700	6/7 - hand dug well	2009	SALWACO	dry 2 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	487
		220	7/7 - bore hole	2009	SALWACO	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	488
	Maforaka	800	hand dug well	2009	SALWACO	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	489
	Masosigbi	400	hand dug well	2007	SALWACO	not finished						-	481
	Mathapi	260	No system										490
<u>Makelfa</u>													
	Fonkuma	350	hand dug well	2009	SALWACO	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	507
	Gbafaya	400	hand dug well	2009	SALWACO	pump broken	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	506
	Kalmaro	250	No system										515
	Kunibaya	500	No system										514
	Makelfa	100	hand dug well	2009	SALWACO	pump broken	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	505
	Maranda	500	hand dug well	2008	SALWACO	pump broken	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	508
	Masombirie	800	1/4 - hand dug well	2007	NACSA	dry 12 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	509
		2000	2/4 - hand dug well	2007	SALWACO	dry 3 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	510
		600	3/4 - hand dug well	2010	PACT	dry 3 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	511
		300	4/4 - hand dug well	2008	SEP	pump broken	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	512
	Nenekoro	430	No system										516
	Nokosoya	400	No system										513
	Turuwaya	150	hand dug well	2009	SALWACO	dry 4 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	502
	Yinaya	300	1/2 - hand dug well	2006	NACSA	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	503
		2/2 - hand dug well	2009	SALWACO	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	504	

Kafe Simira (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
<u>Mayaso</u>													
	Kabumba	280	No system									496	
	Kamasedeh	490	No system									501	
	Kamatha	340	No system									500	
	Kamudugu	781	No system									499	
	Kathantha	400	No system									497	
	Masekere	370	No system									495	
	Mayaso	400	1/3 - hand dug well	2007	SALWACO	not finished					-	491	
		200	2/3 - hand dug well	2009	NACSA	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	492
		150	3/3 - hand dug well	2007	NACSA	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	493
	Sagbaba	400	hand dug well	2009	SALWACO	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	494
	Samgbaba	900	No system									498	
<u>Simiria</u>													
	Fothaneh	150	1/2 - pulley	1994	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	470
		300	2/2 - hand dug well	2007	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	471
	Magbithi	600	No system									478	
	Mahomp	500	No system									477	
	Makombo	720	No system									479	
	Makoreh	150	hand dug well	2009	SALWACO	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	475
	Sanda	150	hand dug well	2008	SALWACO	not finished					-	476	
	Simiria	300	1/3 - hand dug well	2007	SALWACO	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	472
		200	2/3 - pulley	1994	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	473
		150	3/3 - hand dug well	2009	RWSP	dry 4 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	474
	Yoni	300	No system									480	

Kafe Simira (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
---------	---------	--------------------	-------------	------	---------	------------	-----------	---------------	-----------------	------------------	-----------------	------

7 sections 51 villages - 32 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Kafe Simira - summary / 19 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	2	920	0	0 (0%)	2	1 (50%)	0 (0%)	1 (50%)	1 (50%)
hand dug well	32	13 304	3	6 (18,8%)	18	14 (78%)	4 (12%)	13 (41%)	12 (38%)
	34	14 224	3	6 (17,6%)	20	15 (75%)	4 (12%)	14 (41%)	13 (38%)

Kalasongia (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Bumbuna</u>												
	Bendugu Road	900	No system									537
	Bright Street	78	No system									538
	Bumbuna	800	1/2 - hand dug well	2007	District Council	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 527
		900	2/2 - hand dug well	2004	District Council	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 528
	Ferry Road	88	No system									532
	Kalma Street	96	No system									533
	Kamara Street	75	No system									530
	Kodo Street	89	No system									534
	Magburaka Road	100	No system									536
	Manekala Street	100	No system									535
	Old Town	93	No system									531
	Pessima Street	800	No system									529
<u>Fuladugu</u>												
	Kabumba	90	No system									586
	Kakutha	80	No system									592
	Kamasapayna	120	No system									590
	Kamasapy	90	No system									591
	Kasankoree	80	No system									587
	Kateneh	100	No system									585
	Katheauna	100	No system									588
	Kathengbeh	90	No system									589
	Kawukulu	50	No system									593
<u>Kakailay</u>												
	Daresala	50	No system									600
	Kabonka	200	No system									596
	Kaforko	50	No system									601
	Kabana	70	No system									598
	Kakarima	300	No system									594

Kalasongia (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Kakailay</u>												
	Kakuthan	100	No system									599
	Kamasikie	400	No system									595
	Kasasic	300	No system									597
<u>Kamakathe</u>												
	Kadada	600	hand dug well	2008	<i>District Council</i>	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Kadanso	58	No system									561
	Kafunkia	97	No system									563
	Kamagaray	81	No system									562
	Kamasapana	58	No system									564
	Kawonor	49	No system									565
<u>Kamakila</u>												
	Kakamaloh	20	No system									570
	Kakontha	40	No system									571
	Kamarapay	34	No system									568
	Kamarinbin	52	No system									572
	Kamera	89	No system									566
	Kasagban	90	No system									569
	Kasompona	40	No system									567
<u>Kasokira</u>												
	Kadala	200	No system									553
	Kamancay	900	hand dug well	2002	<i>World Bank</i>	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Kamathod	500	hand dug well	2009	<i>District Council</i>	not finished						-
	Kamera	66	No system									556
	Kasasic	57	No system									559
	Kasokira	60	No system									558
	Kathambo	800	hand dug well	2009	<i>District Council</i>	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kawonor	70	No system									555
	Kayakala	71	No system									557

Kalasongia (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Kasokira												
	Kegbema	900	No system									554
Kemedugu												
	Dandaya	700	No system									579
	Foria	600	No system									578
	Gbongbonba	400	No system									576
	Kemedugu1	1500	hand dug well	2004	NACSA	dry 7 months/year	OTHER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kemedugu2	900	No system									574
	Sasakala	500	No system									575
	Wondugu	500	No system									577
Lower Section												
	Ballai A	200	No system									546
	Bassia	950	No system									544
	Kabarie	80	1/2 - bore hole	2008	Indian Development Assoc	dry 12 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/2 - pulley	2004	District Council	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Kajidda	500	bore hole	2007	Indian Development Assoc	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Kapeteh	150	No system									548
	Kasokira	100	No system									547
	Kegbema	100	No system									549
	Kenegbah	300	No system									545
	Maketa	200	No system									542
	Yeben	800	No system									543
Songoni												
	Ferengbia	1500	No system									583
	Gbolia	300	No system									584
	Kegbema	300	No system									582
	Moria	150	No system									581
	Sonkonini	1000	hand dug well	2005	NACSA	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
												580

Kalasongia (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.
---------	---------	--------------------	-------------	------	---------	------------	-----------	---------------	-----------------	------------------	-----------------

9 sections 73 villages - 64 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Ref.

Kalasongia - summary / 9 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	2	580	0	0 (0%)	2	1 (50%)	1 (50%)	1 (50%)	0 (0%)
hand dug well	8	7 000	1	1 (12,5%)	7	4 (57%)	1 (12%)	2 (25%)	4 (50%)
	10	7 580	1	1 (10%)	9	5 (56%)	2 (20%)	3 (30%)	4 (40%)

Kholifa Mabang (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
<u>Kumrabai</u>													
	Kumrabai Junction	150	1/2 - hand dug well	2004	Concern	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1367
			2/2 - hand dug well	2004	Concern	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1368
	Kumrabai Station	50	1/5 - hand dug well	2005	Concern	dry 6 months/year	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1360
			2/5 - hand dug well	2006	Concern	pump broken	IM2 - stolen	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1361
			3/5 - hand dug well	2004	Concern	dry 6 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1362
			4/5 - hand dug well	2004	Concern	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1363
			5/5 - hand dug well	2004	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1364
	Magbakai	150	hand dug well	2006	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	1359
	Mamaila	150	1/2 - hand dug well	2004	Concern	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1365
			2/2 - hand dug well	2004	Concern	pump broken	IM2 - stolen	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	1366
	Masarifu	200	hand dug well	2006	Concern	dry 2 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	1358
	Matuku	250	1/5 - hand dug well	2004	Concern	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	1352
			2/5 - hand dug well	2004	Concern	dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	1353
		233	3/5 - hand dug well	2006	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1354
			4/5 - hand dug well	2006	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1355
			5/5 - hand dug well	2006	Concern	dry 2 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	1356
	Rochain	200	hand dug well	2003	Concern	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1357
<u>Mabang</u>													
	Mabang	140	1/7 - hand dug well	2005	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1369
			2/7 - hand dug well	2005	Concern	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1370
			3/7 - hand dug well	2005	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1371
			4/7 - hand dug well	2005	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	1372
			5/7 - hand dug well	2005	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1373
			6/7 - hand dug well	2005	Concern	working	OTHER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1374
			7/7 - hand dug well	2005	Concern	pump broken	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1375
	Makaneh1	38	No system										1389
	Makaneh2	38	No system										1390
	Masakie	200	hand dug well	2005	Concern	not finished					-		1383
	Mathinka Bana	150	1/4 - hand dug well	2005	Concern	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1377

Kholifa Mabang (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
<u>Mabang</u>													
Mathinka Bana	150	2/4 - hand dug well	2005	Concern		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	1378
		3/4 - hand dug well	2004	Concern		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	1379
		4/4 - hand dug well	2004	Concern		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	1380
Mayirma	67	No system											1393
Mayiseh	100	No system											1394
Robolgin	400	hand dug well	2005	Concern		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	1381
Robung	100	No system											1387
Rofoindu	20	No system											1388
Rofunk	90	No system											1392
Romacha	200	hand dug well	2005	Concern		dry 6 months/year	IM2 - stolen	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	1376
Ropatifu	200	1/2 - hand dug well	2005	Concern		not finished							1384
		2/2 - hand dug well	2005	Concern		dry 6 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1385
Rothangbai	300	hand dug well	2005	Concern		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1382
Roworreh	59	No system											1391
Royale	200	No system											1386
<u>Manoso Klafa</u>													
Bukbuka	700	hand dug well	2005	Concern		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working	1440
Mafalatha	250	hand dug well	2005	Concern		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1447
Mafalatha School	250	hand dug well	2008	Concern		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1448
Mafang	400	hand dug well	2010	Concern		dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	1446
Mafoce	200	hand dug well	2007	Concern		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1450
Magbba	400	hand dug well	2006	Concern		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1449
Manaso Klafa	425	hand dug well	2009	Concern		dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1439
		hand dug well	2004	Concern		dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1438
		1/2 - hand dug well	2006	Concern		dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1436
		2/2 - hand dug well	2006	Concern		dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1437
Marobay	300	hand dug well	2006	Concern		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1451
Marokie	150	hand dug well	2007	Concern		dry 2 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1445

Kholifa Mabang (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Manoso Klafa</u>												
	Marufiu	500	hand dug well	2006	Concern	dry 1 month/year	IM2 - stolen	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1443
	Mashumu	600	hand dug well	2005	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1441
	Mashumu School	330	hand dug well	2007	Concern	pump broken	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1442
	Rochin Come	500	hand dug well	2005	Concern	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1452
	Rochin Line	400	hand dug well	2003	Concern	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1444
	Rogbai		No system									1454
<u>Marunia Koray</u>												
	Maddina		No system									1430
	Madina		hand dug well	2008	Concern	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1418
	Magbokie	500	1/4 - hand dug well	2005	Concern	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1419
			2/4 - hand dug well	2004	Concern	dry 1 month/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1420
			3/4 - hand dug well	2004	Concern	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1421
			4/4 - hand dug well	2004	Concern	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1422
	Magbongo	500	hand dug well	2005	Concern	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1428
	Magbongo School	125	hand dug well	2005	Concern	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1429
	Marunia	250	1/4 - hand dug well	2010	Concern	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1414
			2/4 - hand dug well	2009	Concern	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1415
			3/4 - hand dug well	2005	Concern	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1416
			4/4 - hand dug well	2004	Concern	pump broken	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1417
	Mashim		No system									1431
	Mashruku	200	hand dug well	2004	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1423
	Masiaka		No system									1433
	Maworro	400	hand dug well	2005	Concern	dry 4 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 1426
	Robanbay		No system									1435
	Rogbesheh	300	hand dug well	2005	Concern	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1427
	Rokankrr	250	hand dug well	2007	Concern	dry 4 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 1425
		900	hand dug well	2005	Concern	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1424
	Rokemeh		No system									1432

Kholifa Mabang (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Marunia Koray</u>												
	Ropanplon		No system									1434
<u>Marunia Sakie</u>												
Mabai	242	1/7 - hand dug well	2005	Concern		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1405
		2/7 - hand dug well	2004	Concern		dry 2 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 1406
		3/7 - hand dug well	2004	Concern		dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1407
		4/7 - hand dug well	2008	Concern		pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1408
		5/7 - hand dug well	2004	Concern		dry 4 months/year	IM2 - stolen	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 1409
		6/7 - hand dug well	2004	Concern		dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 1410
		7/7 - hand dug well	2004	Concern		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 1411
Makong	153	hand dug well	2004	Concern		dry 3 months/year	OTHER - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1412
	300	hand dug well	2005	Concern		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Not Working 1413
Masiake	477	hand dug well	2005	Concern		dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1396
Mathankie	250	1/3 - hand dug well	2005	Concern		dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1397
	300	2/3 - hand dug well	2004	Concern		dry 7 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1398
	250	3/3 - hand dug well	2004	NACSA		working	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1399
Maworro	200	1/4 - hand dug well	2007	Concern		dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1400
	300	2/4 - hand dug well	2007	Concern		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1401
	100	3/4 - hand dug well	2009	SALWACO		dry 1 month/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1402
	500	4/4 - hand dug well	2006	NACSA		working	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1403
Rothible	400	hand dug well	2005	Concern		dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1404
<u>Robis</u>												
Mabontho	200	1/2 - hand dug well	2004	Concern		dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1341
		2/2 - hand dug well	2004	Concern		dry 6 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1342
Mamaila Gbla	300	1/2 - hand dug well	2004	Concern		dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1344
		2/2 - hand dug well	2004	Concern		dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1345
Mamanso Mo	125	1/2 - hand dug well	2005	Concern		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1350
		2/2 - hand dug well	2005	Concern		dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1351
Masiaka	250	1/2 - hand dug well	2005	Concern		dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1348
		2/2 - hand dug well	2005	Concern		dry 4 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1349

Kholifa Mabang (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Robis</u>	Primary School	200	hand dug well	2005	Concern	dry 6 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1343
	Robis	225	hand dug well	2004	Concern	dry 6 months/year	IM2 - stolen	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1347
	School	235	hand dug well	2005	Concern	working	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1346

6 sections 66 villages - 16 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Kholifa Mabang - summary / 50 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
hand dug well	96	25 368	2	21 (21,9%)	87	35 (40%)	19 (20%)	27 (28%)	48 (50%)
	96	25 368	2	21 (21,9%)	87	35 (40%)	19 (20%)	27 (28%)	48 (50%)

Kholifa Rowalla (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
<u>Lal Lenken</u>													
	Kalmaroh	700	hand dug well	1986	Indian Development Assoc	not finished					-	713	
	mabereh	400	No system									865	
	Madibie	463	No system									860	
Magbomkoh	131	1/3 - hand dug well	2010	Red Cross		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	706
		2/3 - hand dug well	2010	Red Cross		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	707
		3/3 - hand dug well	2010	Red Cross		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	708
Magbonho	200	1/3 - hand dug well	1986	Seventh Day Adventist		dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal	682
		2/3 - pulley	1978	Indian Development Assoc		dry 4 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	683
		3/3 - hand dug well	2008	SABABU		dry 1 month/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	684
Makaba	525	No system										863	
Makarr	400	hand dug well	1995	Seventh Day Adventist		dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal	686
Malongba	700	hand dug well	1992	Seventh Day Adventist		dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal	702
Maraka	175	1/2 - bore hole	2002	KADO		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	698
		2/2 - hand dug well	2010	Red Cross		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	699
Marako	550	No system										864	
Masanga	600	1/5 - hand dug well	1994	Seventh Day Adventist		dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	687
		2/5 - bore hole	2008	Korean Group		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	688
		3/5 - hand dug well	1997	DIA		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	689
		4/5 - bore hole	1997	Seventh Day Adventist		dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	690
		5/5 - hand dug well	1997	Seventh Day Adventist		dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal	691
Masanga 2	50	hand dug well	1994	Seventh Day Adventist		dry 5 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	694
Masorokoy	750	hand dug well	1995	Seventh Day Adventist		dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal	685
Matham	250	1/2 - bore hole	2008	SALWACO		dry 6 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	695
		2/2 - hand dug well	1986	Indian Development Assoc		dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	696
Mathora	200	1/3 - bore hole	1995	KADO		dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal	703
		2/3 - hand dug well	1971	Indian Development Assoc		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	704
		3/3 - bore hole	2000	DDR		dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	705
Rogbasseh	450	1/2 - hand dug well	2000	DFID		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	692
		2/2 - hand dug well	2000	ACC		dry 2 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	693

Kholifa Rowalla (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Lal Lenken</u>												
	Rogbenthne	175	1/2 - hand dug well	2010	Red Cross	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 700
			2/2 - hand dug well	2010	Red Cross	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 701
	Rogbom	270	No system									862
	Romankro	400	hand dug well	2009	SABI	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 697
	Rothatha	475	No system									861
	Rowalla	192	1/4 - hand dug well	2010	Red Cross	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 709
			2/4 - hand dug well	2010	Red Cross	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 710
			3/4 - hand dug well	2010	Red Cross	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 711
			4/4 - hand dug well	2010	Red Cross	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 712
<u>Makump</u>												
	Mabai	150	1/3 - pulley	1978	Indian Development Assoc -		no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 735
			2/3 - pulley	2001	CARE	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 736
			3/3 - bore hole	2004	CARE	dry 1 month/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 737
	Mabera	350	hand dug well	1994	Seventh Day Adventist	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 741
	Mafanta	100	1/3 - hand dug well	2003	NACSA	dry 5 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 717
			2/3 - hand dug well	2005	MODCON	dry 5 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 718
			3/3 - hand dug well	2003	NACSA	dry 5 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 719
	Magbakrr	85	1/3 - pulley	1980	Indian Development Assoc -		no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 748
			2/3 - pulley	2002	CARE	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 749
			3/3 - pulley	2002	CARE	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 750
	Makil	630	No system									856
	Makump	45	1/6 - bore hole	2002	CARDO	working	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 729
			2/6 - pulley	1995	CARE	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 730
			3/6 - pulley	1995	CARE	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 731
			4/6 - pulley	1995	CARE	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 732
			5/6 - pulley	1994	CARE	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 733
			6/6 - pulley	1994	CARE	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 734
	Makump Kp	125	1/3 - pulley	2005	CARE	dry 3 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 745
			2/3 - pulley	2005	CARE	dry 3 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 746

Kholifa Rowalla (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Makump												
	Makump Kp	125	3/3 - pulley	2005	CARE	dry 3 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 747
	Makundu	170	No system									855
Malon		521	1/9 - hand dug well	2002	UNICEF	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 720
			2/9 - bore hole	2005	Korean Group	working	K	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 721
			3/9 - bore hole	2005	CARE	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 722
			4/9 - pulley	1996	CARE	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 723
			5/9 - pulley	1996	CARE	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 724
			6/9 - pulley	1996	CARE	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 725
			7/9 - pulley	1997	Africare	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 726
			8/9 - pulley	1997	Africare	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 727
			9/9 - pulley	1997	Africare	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 728
	Maronka	450	No system									857
	Massabe	400	pulley	2009	CARE	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 744
Matali		166	1/3 - hand dug well	2002	CARE	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 714
			2/3 - hand dug well	1999	CARE	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 715
			3/3 - hand dug well	2003	CARE	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 716
	Mayatha	420	No system									859
Maymbaray		133	1/3 - pulley	2003	CARE	dry 4 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 738
			2/3 - pulley	2003	CARE	dry 4 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 739
			3/3 - hand dug well	2003	ADR	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 740
Robol		225	1/2 - bore hole	2003	KADO	pump broken	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 742
			2/2 - pulley	1992	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 743
	Ropolon	450	hand dug well	2003	ACF	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 751
	Rothuck	340	No system									858

Mamunta

Maborboh	250	No system										853
Maborie	500	bore hole	2009	District Council		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 755
Maformbo	600	pulley	1996	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 758
magbass	833	1/3 - pulley	1996	CARE	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 766

Kholifa Rowalla (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Mamunta												
	magbass	833	2/3 - pulley	1996	CARE	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 767
			3/3 - hand dug well	2010	UNICEF	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 768
	Makaprr	400	pulley	1996	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 761
	Mamunta	375	1/4 - hand dug well	2000	DFID	pump broken	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 762
			2/4 - hand dug well	2009	ACTION AID	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 763
			3/4 - hand dug well	2007	NACSA	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 764
			4/4 - pulley	1996	CARE	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 765
	Mamunta Kasethe	280	No system									854
	Masagble	632	1/3 - hand dug well	2003	CARE	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 752
			2/3 - hand dug well	2003	CARE	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 753
			3/3 - hand dug well	2008	ACTION AID	dry 2 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 754
	Masampa	385	No system									849
	Mathorkoh	200	No system									850
	Mayirma	200	No system									852
	Mayorma	400	pulley	2003	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 769
	Patefu	170	No system									851
	Rochen	437	1/2 - pulley	1996	CARE	dry 3 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 759
			2/2 - hand dug well	2010	ACTION AID	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 760
	Rogbonko	1148	hand dug well	1996	CARE	working	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 757
	Rothaimbai	950	hand dug well	1996	CARE	dry 4 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 756
Mayatha												
	Mabum	400	1/8 - pulley	2003	CARE	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 782
			2/8 - hand dug well	2010	UNICEF	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 783
			3/8 - pulley	2003	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 784
			4/8 - pulley	2003	CARE	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 785
			5/8 - bore hole	2008	District Council	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 786
			6/8 - pulley	2003	CARE	dry 5 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 787
			7/8 - pulley	2003	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 788
			8/8 - bore hole	2009	District Council	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 789

Kholifa Rowalla (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Mayatha</u>												
	Magbesseh	130	1/4 - pulley	2003	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 796
		174	1/A - pulley	2003	CARE	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 800
			1/B - pulley	2003	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 801
		130	2/4 - pulley	1996	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 797
			3/4 - bore hole	2009	District Council	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 798
			4/4 - pulley	2003	CARE	dry 4 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 799
	Makombor	50	1/2 - pulley	2003	CARE	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 770
			2/2 - pulley	2003	CARE	dry 6 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 771
	Makorie kob	175	1/2 - pulley	2003	CARE	dry 5 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 794
			2/2 - pulley	1996	CARE	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 795
	Makoriem	3150	pulley	2003	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 778
	Mamadikim	250	pulley	1996	CARE	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 793
	Mamonu	150	1/2 - pulley	2003	CARE	dry 4 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 804
			2/2 - pulley	2003	CARE	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 805
	Mamuna Lol	250	No system									847
	Mamunabara	450	pulley	2000	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 806
	Masoria	300	pulley	2003	CARE	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 777
	Masuba	275	No system									848
	Mayatha	137	1/4 - bore hole	2008	District Council	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 772
			2/4 - hand dug well	2003	CARE	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 773
			3/4 - hand dug well	2007	ACTION AID	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 774
			4/4 - hand dug well	2003	CARE	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 775
	Mayinkoko	200	pulley	2003	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 776
	Patefu1		pulley	2003	CARE	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 802
	Patefu2	178	pulley	2008	CARE	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 803
	Rogberka	83	1/3 - pulley	2003	CARE	dry 4 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 779
			2/3 - pulley	2003	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 780
			3/3 - pulley	2003	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 781
	Rothamabai	384	hand dug well	1996	CARE	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 792

Kholifa Rowalla (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Mayatha</u>												
	Station	250	1/2 - pulley	2003	CARE	dry 5 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/2 - pulley	2003	CARE	dry 5 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
<u>Mayossoh</u>												
	Ferry Junction	150	1/2 - bore hole	2009	Concern	dry 2 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			2/2 - pulley	2001	CARE	dry 4 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Mafunk	100	pulley	2003	CARE	dry 3 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Makaba	250	pulley	2003	CARE	dry 4 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Makabie	260	pulley	2003	CARE	dry 3 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Makonie	300	pulley	2003	CARE	dry 4 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Mamanor	133	1/3 - pulley	2003	CARE	dry 4 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/3 - bore hole	2009	District Council	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
			3/3 - pulley	2003	CARE	dry 6 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Masakoh	108	2/5 - pulley	2004	CARE	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			3/5 - pulley	1998	CARE	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Masang	136	1/5 - pulley	2003	CARE	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/5 - pulley	2003	CARE	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			3/5 - pulley	2003	CARE	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			4/5 - hand dug well	2010	ACTION AID	not finished						-
			5/5 - pulley	1985	CADO	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Masobinthia	235	1/2 - bore hole	2007	District Council	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			2/2 - pulley	2001	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Masokoh	108	1/5 - pulley	2004	CARE	dry 3 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			4/5 - pulley	2003	CARE	dry 12 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			5/5 - hand dug well	2010	UNICEF	not finished						-
	Masuba	110	1/2 - pulley	2003	CARE	dry 6 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/2 - pulley	2003	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Mathonkara	100	1/3 - pulley	2003	CARE	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/3 - pulley	1968	Indian Development Assoc	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			3/3 - pulley	2003	CARE	dry 6 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working

Kholifa Rowalla (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Mayossoh</u>												
	Mayossoh	400	1/4 - hand dug well	1995	NACSA	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 836
			2/4 - pulley	2003	CARE	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 837
			3/4 - pulley	2003	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 838
			4/4 - hand dug well	2004	Merlin	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 839
	Mayossoh Line	230	pulley	2003	CARE	dry 12 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 835
Robinkie		166	1/6 - pulley	2003	CARE	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 841
			2/6 - pulley	1970	Indian Development Assoc	dry 3 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 842
			3/6 - bore hole	2008	District Council	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 843
			4/6 - pulley	2003	CARE	dry 4 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 844
			5/6 - pulley	2003	CARE	dry 5 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 845
			6/6 - hand dug well	2006	NACSA	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 846
Robis		300	1/3 - hand dug well	2010	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 809
			2/3 - pulley	2004	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 810
			3/3 - hand dug well	2004	Concern	dry 6 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 811

5 sections 88 villages - 19 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Kholifa Rowalla - summary / 69 villages					P U M P		SEASONALITY		
Type	Total	Popul. Approxim	Not finished	Functional all the year	installed	working	Dry>3m	seasonal	Alw. water
bore hole	20	5 738	0	9 (45%)	20	15 (75%)	1 (5%)	8 (40%)	11 (55%)
hand dug well	57	19 882	3	15 (26,3%)	48	32 (67%)	7 (12%)	20 (35%)	27 (47%)
	77	25 620	3	24 (31,2%)	68	47 (69%)	8 (10%)	28 (36%)	38 (49%)

Kunike (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Masingbi</u>												
	Masingbi	3200	1/8 - bore hole	1993	ACF	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 62
			2/8 - hand dug well	2002	Other	dry 12 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 63
			3/8 - bore hole	2003	ACF	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 64
			4/8 - bore hole	2004	ACF	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 65
			5/8 - bore hole	2002	Korean Group	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 66
			6/8 - bore hole	2008	Korean Group	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 67
			7/8 - hand dug well	2009	Yapoo Yapoo	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 68
			8/8 - hand dug well	2010	Other	working	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 69
<u>Rolal</u>												
	Kumrabai Kinkoray	52	No system									140
	Kumrabai Makema	850	No system									139
	Mabando	250	No system									142
	Mabayla	589	No system									138
	Mamanso Sanka	800	1/3 - hand dug well	2005	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 135
			2/3 - hand dug well	2005	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 136
			3/3 - pulley	1996	MRC	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 137
	Robaka	515	No system									141
	Rogbokeh	148	No system									143
<u>Sanda</u>												
	Fabaneh	200	hand dug well	2009	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 23
	Fothaneh Four	260	No system									46
	Kondema	110	No system									42
	Kumrabai	215	No system									43
	Mabagbarie	98	No system									50
	Mabambay	300	No system									41
	Mabathof	575	bore hole	2004	Korean Group	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 21
	Machain	332	hand dug well	2005	Concern	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 20
	Mafaray	180	No system									38
	Magbana Poli	101	No system									47

Kunike (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Sanda</u>												
	Magbasia	230	hand dug well	2007	Concern	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 30
	Magbassia Jonction	100	bore hole	2010	Korean Group	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 22
	Magbonka	400	hand dug well	2009	Concern	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 31
	Makelfa	650	hand dug well	2003	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 29
	Makoto	100	No system									49
	Maquali Lol	209	No system									39
	Masiaka	965	1/2 - hand dug well	1975	Other	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 35
			2/2 - pulley	2003	MRC	dry 12 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 36
	Mathabay	230	No system									40
	Mayola	300	hand dug well	2008	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 33
	Patifu	100	1/5 - bore hole	2008	Korean Group	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 24
			2/5 - bore hole	2004	OTHER	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 25
			3/5 - pulley	1992	CADO	dry 12 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 26
			4/5 - hand dug well	1993	Merlin	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 27
			5/5 - hand dug well	1982	World Bank	dry 12 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 28
	Patifu Kanafutha	160	No system									45
	Patifu Makansera	217	No system									37
	Sarr Ben Thy	200	hand dug well	2009	Concern	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 34
	Sarr Manda	381	No system									44
	Yeaboo	190	No system									48

Semokani

Ggom Bana	102	No system										60
Kenewa	250	hand dug well	2010	Concern	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 53
Mabogba	237	No system										59
Mafulka I	300	hand dug well	2007	Concern	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 51
Mafulka II	230	hand dug well	2010	Concern	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 52
Makanthi	231	No system										61
Masorie	280	No system										54

Kunike (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Semokani</u>												
	Masothi	250	No system									55
	Maworko	200	No system									56
	Ropeti	209	No system									58
	Rowula	172	No system									57
<u>Thama</u>												
	Fothaneh	750	hand dug well	2008	Concern	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Konta	800	hand dug well	2008	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK
	Mabakoh	1000	1/3 - hand dug well	2006	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			2/3 - bore hole	2005	CARE	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			3/3 - bore hole	2009	Korean Group	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Madina	350	hand dug well	2009	Concern	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Makongbay	396	hand dug well	2007	Concern	pump broken	IM2 - stolen	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Makonteh Thoma	750	1/2 - hand dug well	2005	Concern	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
			2/2 - hand dug well	2005	NACSA	dry 12 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Makump 1	304	hand dug well	2007	Concern	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Makump 2	215	No system									17
	Makump 3	102	No system									18
	Mamantya	302	hand dug well	2009	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Matholley	550	hand dug well	2009	Concern	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	One board	250	No system									19
	Ronetor	125	hand dug well	2008	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Ropolو	400	1/2 - hand dug well	2010	UNICEF	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			2/2 - bore hole	2010	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Two house	500	hand dug well	2008	Concern	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
<u>Thambaya</u>												
	Bonkom	78	No system									106
	Fothaneh Bana	140	1/2 - hand dug well	2008	Concern	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
		619	2/2 - hand dug well	2008	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK

Kunike (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Thambaya</u>												
	Magbanto Bana	985	hand dug well	2008	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 94
	Magbanto Lol	150	bore hole	2010	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 93
	Magbolina	96	No system									97
	Makintha	101	No system									105
	Malankay	113	No system									102
	Manangba	107	hand dug well	2009	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 89
	Masagbay	606	hand dug well	2008	Concern	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 95
	Maseneh	90	No system									107
	Masheku Bana	150	No system									100
	Masheku Lol	98	No system									101
	Masiaka	102	No system									103
Mathamba	268	1/2 - hand dug well	2009	Madam		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 87
	502	2/2 - bore hole	2010	Concern		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 88
	Mawossor	108	No system									108
	Mayagba	158	No system									104
	N'Yenko	82	No system									98
	Petifu Bomo Thorlie	392	No system									111
	Robeck	58	No system									96
	Rokonto	63	No system									99
	Rosinkim	344	hand dug well	2009	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 92
	Rosint	278	No system									109
	Sumbuya	262	No system									112
	Yeama Shembu	368	No system									110
<u>Wana</u>												
	91 village	120	No system									121
	Concern	175	No system									128
	Faillah	110	No system									122
	Gbom Kamp	130	No system									125

Kunike (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Wana</u>												
	Kamakola	215	No system									131
	Lungi	55	No system									132
	Mabanta	320	No system									126
	Mabuwa	620	No system									123
	Madina	48	No system									133
	Mafondo	250	No system									120
	Magbanabom	671	1/2 - hand dug well	2008	Concern	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
		325	2/2 - hand dug well	2008	Concern	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Mandugu	333	1/2 - hand dug well	2007	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
			2/2 - hand dug well	2009	Concern	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	Mandugu Benevolent	322	hand dug well	2009	Concern	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Mandugu MPM	290	hand dug well	2010	Concern	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Mile 38	155	No system									129
	Robang	138	No system									127
	Rogbep	108	No system									130
	Rokon	580	hand dug well	2007	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Rotain	25	No system									134
	Royeama	840	No system									124
<u>Yenke</u>												
	Farama	301	No system									76
	Fothaneh Small	96	No system									81
	Gbom Kamp	253	No system									82
	Kamathor	782	No system									75
	Kumbrabai	704	No system									86
	Mabineh	500	hand dug well	2010	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	Mabrah	310	No system									77
	Magbala	309	No system									84
	Makoma	409	No system									78

Kunike (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Yenke</u>	Makonteh	230	bore hole	2010	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 71
	Maminkie	300	bore hole	2010	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 70
	Mathenemoi	600	No system									74
	Mbineh	428	No system									85
	Rogbaneh	609	hand dug well	2010	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 73
	Rowonkoh	368	No system									83
	Yeam Chain	139	No system									80
	Yeama Falma	275	No system									79

8 sections 120 villages - 76 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Kunike - summary / 44 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	16	20 457	0	12 (75%)	16	16 (100%)	0 (0%)	4 (25%)	12 (75%)
hand dug well	47	29 466	0	26 (55,3%)	47	43 (91%)	3 (6%)	16 (34%)	28 (60%)
63		49 923	0	38 (60,3%)	63	59 (94%)	3 (5%)	20 (32%)	40 (63%)

Kunike Barina (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Makali												
	Barayrin	300	bore hole	2008	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 377
	Bombeh	300	1/3 - pulley	2003	CADO	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 372
			2/3 - pulley	2003	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 373
			3/3 - hand dug well	2007	CAN	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 374
	Makali	250	1/8 - hand dug well	2004	MRC	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 378
			2/8 - hand dug well	2005	ZAIN	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 379
			3/8 - hand dug well	2008	FAO	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 380
			4/8 - bore hole	2009	Korean Group	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 381
			5/8 - hand dug well	2008	SABABU	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 382
			6/8 - hand dug well	2009	DMARK	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 383
			7/8 - hand dug well	2009	SABABU	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 384
			8/8 - hand dug well	2004	NACSA	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 385
Makumbu	350	pulley		2003	CARE	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 375
Matheneh	350	No system										386
Mayami	240	pulley		2004	CARE	dry 4 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 376
Mayatta	300	No system										388
Mayben	130	No system										387
Musira	300	1/3 - pulley		2003	CARE	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 369
		2/3 - pulley		2008	CARE	dry 1 month/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 370
		3/3 - hand dug well		2009	CONCERN	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 371

Makong

Karrfay	150	No system										449
Liberia Compound	100	No system										450
Makong	1200	No system										445
Malemoh	100	No system										451
Robise	50	No system										452
Rocamp	250	No system										448
Romgbangbaday	500	No system										447
Romgbankapose	200	No system										446

Kunike Barina (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Makong</u>												
<u>Mamuri</u>	Mamuri	300	bore hole	2002	UNICEF	working	K	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 433
	Robangbe	100	No system									436
	Robesim	60	No system									440
	Rolalay	40	No system									441
	Rolath	50	No system									443
	Romakonteh	40	No system									437
	Romsabanie	35	No system									442
	Romsese	60	No system									444
	Rosimbeck	250	No system									435
	Rosint	50	No system									439
	Rowaka	300	No system									434
	Roworreh	30	No system									438
<u>Massaba</u>	Bath Worla	50	No system									432
	Ggapill	100	No system									430
	Maforray	100	No system									429
	Magbayma	50	No system									424
	Makoni 1	60	No system									426
	Makoni 2	75	No system									427
	Makonteh	150	hand dug well	2009	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK 422
	Makoth	100	No system									431
	Maraka	40	No system									428
	Massaba	200	hand dug well	2009	Concern	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 421
	Mayenku	46	No system									425
	Rogbam	50	No system									423
<u>Mathonkara</u>	Madina	500	1/2 - pulley	1993	CARE	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 406

Kunike Barina (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Mathonkara</u>												
	Madina	500	2/2 - bore hole	2003	UNICEF	dry 1 month/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 407
	Magbfeth	140	No system									409
	Makama	300	pulley	2003	CARE	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 397
	Makankay	183	1/3 - pulley	2003	CARE	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 399
			2/3 - pulley	2003	CARE	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 400
			3/3 - pulley	2003	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 401
	Makeni Lol	30	pulley	2003	CARE	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 398
	Makethi	150	No system									408
	Makonilina	438	1/4 - pulley	2003	CARE	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 402
			2/4 - hand dug well	2005	NACSA	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 403
			3/4 - hand dug well	2002	MRC	dry 4 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 404
			4/4 - bore hole	2008	Korean Group	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 405
	Manasie	175	1/4 - pulley	2003	CARE	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 393
			2/4 - pulley	2003	CARE	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 394
			3/4 - hand dug well	2008	CONCERN	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 395
			4/4 - hand dug well	2009	CHRISTIAN CHILDREN F	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 396
	Mathonkara	250	1/2 - pulley	2000	CARE	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 391
			2/2 - bore hole	2008	CARE	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 392
	Patefutain	125	1/2 - hand dug well	2007	CARE	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 389
			2/2 - pulley	2002	CARE	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 390
<u>Wonkibor</u>												
	Farama	310	No system									415
	Fothaneh	135	No system									420
	Magbundeh	125	No system									419
	Makera	150	No system									417
	Makorgbo	450	hand dug well	2006	CONCERN	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 413
	Mapamuru	250	1/2 - hand dug well	2005	NACSA	dry 6 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 412
			2/2 - hand dug well	2005	CONCERN	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 414
	Mathombo	130	No system									418

Kunike Barina (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Wonkibor</u>												
	Royale	350	No system									416
	Wonkibor	200	1/2 - hand dug well	2006	CONCERN	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 410
			2/2 - hand dug well	2004	EU	dry 2 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 411

6 sections 60 villages - 40 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Kunike Barina - summary / 20 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	6	2 038	0	4 (66,7%)	6	5 (83%)	0 (0%)	1 (17%)	5 (83%)
hand dug well	21	5 401	0	5 (23,8%)	21	10 (48%)	2 (10%)	6 (29%)	13 (62%)
	27	7 439	0	9 (33,3%)	27	15 (56%)	2 (7%)	7 (26%)	18 (67%)

Magburaka (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Magburaka town												
	Baptist Primary School	900	pulley	2003	UNICEF	dry 10 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Boys School & Commu	3000	bore hole	2009	World Hope	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Boys School & Commu	3000	bore hole	1997	Korean group	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Boys School & Commu	2000	hand dug well	2010	Concern	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	District Council 1	900	bore hole	2008	Korean group	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	District Council 2	900	hand dug well	2009	UNICEF	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Electricity Quaters	1500	bore hole	2009	Korean group	dry 2 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Ferry Road	1000	bore hole	2009	Korean group	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Gov't Hospital 1	3000	hand dug well	2004	ACF	dry 1 month/year	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Gov't Hospital 2	2000	hand dug well	2007	UNICEF	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Gov't Technical Institut	900	hand dug well	2009	CORD	dry 1 month/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Hospital Quaters 1	1000	hand dug well	2004	Action Aid	dry 3 months/year	PB2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Hospital Quaters 2	1000	bore hole	1998	Korean group	dry 2 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Kamara St. Masorkor	600	pulley	2001	Red Cross	dry 4 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Library	2000	hand dug well	2009	NACSA	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	M C A Primary School	1000	hand dug well	2009	SABABU	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Mabom St.	800	pulley	2004	Community	working	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Magbeseh 1	1500	bore hole	2009	Korean group	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Magbeseh 2	900	pulley	2003	CARE	not finished						-
	Magbeseh St.	1000	pulley	2002	Community	dry 3 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Magbeseh St. 1	1000	hand dug well	2004	ACF	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Magbeseh St. 2	1500	hand dug well	2009	SABABU	not finished						-
	Main Lorry Park	1000	hand dug well	2007	Town Council	dry 2 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Manso St.	1000	bore hole	2007	Korean group	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Market Area	3000	bore hole	2007	Korean group	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Masorkor Lane1	2000	hand dug well	1998	Red Cross	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Masorkor Lane2	1000	pulley	2003	Red Cross	dry 7 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Police Barracks	700	hand dug well	2001	DFID	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working

Magburaka (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Magburaka town												
Post Office Road	2500	hand dug well	2004	CELTEL		dry 2 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 22
Prison Barracks	1000	hand dug well	2008	GSDP		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1
Prisons	600	hand dug well	2005	NACSA		dry 5 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 2
R C School for Boys	1000	bore hole	2009	SALWACO		dry 2 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 34
Ropolone 1	500	hand dug well	2009	Port Loko		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 5
Ropolone 2	400	pulley	1997	Red Cross		working	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 6
Ropolone 3	500	pulley	1997	Red Cross		working	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 7
Ropolone 4	500	hand dug well	2010	Red Cross		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 9
S L M B 1	1000	hand dug well	2010	Red Cross		working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 42
S L M B 2	1000	hand dug well	2010	Red Cross		working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 43
S L M B 3	900	hand dug well	2010	Red Cross		dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 44
S L M B 4	700	hand dug well	2010	Red Cross		dry 1 month/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 45
S L M B Quaters	1000	hand dug well	2004	Concern		dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 30
T D C School & Comm	2000	hand dug well	2008	SABABU		dry 4 months/year	OTHER - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 16
Town Field	1500	bore hole	2008	Korean group		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 27
U M C Compound & C	2000	hand dug well	2009	UMC		dry 2 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 24
W F P Area	1000	pulley	2004	Red Cross		working	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 40

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Magburaka

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	11	18 400	0	6 (54,5%)	11	9 (82%)	0 (0%)	3 (27%)	8 (73%)
hand dug well	25	32 700	1	10 (40%)	25	17 (68%)	2 (8%)	10 (40%)	12 (48%)
	36	51 100	1	16 (44,4%)	36	26 (72%)	2 (6%)	13 (36%)	20 (56%)

Malal Mara (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
Kiampkakolo													
	Kiampkakolo	450	1/4 - pulley	1981	Indian Development Assoc	dry 3 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 893	
			2/4 - hand dug well	2006	NACSA	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 894	
			3/4 - hand dug well	2009	Concern	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 895	
			4/4 - pulley	1981	Indian Development Assoc	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 896	
	Madora	245	1/2 - hand dug well	2002	Indian Development Assoc	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 889	
			1/2 - hand dug well	1980	Indian Development Assoc	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 888	
	Mamilleh	400	hand dug well	1978	Indian Development Assoc	dry 7 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 897	
	Mayaingbay	182	1/3 - pulley	1980	Indian Development Assoc	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 890	
			2/3 - pulley	1978	CARE	dry 3 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 891	
			3/3 - hand dug well	2007	Concern	dry 2 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 892	
	Rowaka	250	1/2 - hand dug well	1978	Indian Development Assoc	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 898	
			2/2 - hand dug well	1978	Indian Development Assoc	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 899	
Mabillehfu													
	Mabillahfu	250	1/2 - hand dug well	2007	NACSA	dry 6 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 900	
			2/2 - pulley	1997	Plan International	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 901	
	Masethaleh	4000	No system									904	
	Rogboya	2500	No system									903	
	Rothonko	2000	No system									902	
Makobba													
	Maburah	140	No system									934	
	Makoba Lol	110	No system									935	
	Makobba	850	1/2 - hand dug well	2004	Merlin	dry 5 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 928	
			2/2 - hand dug well	2003	Merlin	dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 929	
	Masugbay	200	1/2 - pulley	1981	Merlin	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 930	
			500	2/2 - hand dug well	2007	CONCERN	dry 8 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 931
	Robina	346	hand dug well	2004	CHRISTIAN CHILDREN F	working	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 932	
	Robina2	170	No system									933	
Malal													
	Makomboh	100	No system									938	

Malal Mara (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
<u>Malal</u>													
	Makosim	150	No system									944	
	Malal	650	No system									936	
	Mayami	100	No system									937	
	Mayibin	500	No system									945	
	Robinkolo	450	No system									940	
	Rogbotri	25	No system									939	
	Rokindama	60	No system									943	
	Romake	150	No system									947	
	Romsere	50	No system									946	
	Ropitfu	100	No system									941	
	Rosint	500	No system									942	
<u>Manewa</u>													
	Maberreh	400	No system									885	
	Makotho	200	No system									887	
	Mamaria	200	hand dug well	2002	Concern	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	884
	Manewa	300	hand dug well	2003	Concern	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	883
	Marokie	400	hand dug well	2003	Concern	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	882
	Mataro	100	hand dug well	2006	Concern	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	881
	Robis	300	No system										886
<u>Mara</u>													
	Mabansor	200	bore hole	2010	Korean Group	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	876
	Magbansor	300	pulley	1976	Indian Development Assoc -		no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	872
	Makay	79	No system										879
	Malianka	155	1/2 - hand dug well	1978	Indian Development Assoc	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	873
			2/2 - hand dug well	2002	Concern	dry 2 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	874
	Mara	500	1/6 - hand dug well	2009	Indian Development Assoc	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	866
			2/6 - hand dug well	1991	Indian Development Assoc	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	867
			3/6 - hand dug well	2006	SABABU	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	868

Malal Mara (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Mara</u>												
	Mara	500	4/6 - bore hole	2010	Korean Group	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 869
			5/6 - bore hole	2009	Korean Group	working	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 870
			6/6 - hand dug well	1995	ACF	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 871
	Marunda	99	No system									878
	Mashaku	58	No system									877
	Robayla	70	pulley	1987	Indian Development Assoc -	no pump		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 875
	Robung	100	No system									880
<u>Mataka</u>												
	Mafondo	60	No system									921
	Makabi	90	No system									925
	Mathonkara	120	No system									927
	Mattaka	460	No system									926
	Mayanka	30	No system									922
	Rofothana	160	No system									919
	Rofunk	80	No system									924
	Rokupr	297	hand dug well	2009	CONCERN	dry 12 months/year	IN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 918
	Ropolon Lol	80	No system									923
	Rosar	120	No system									920
<u>Rochen</u>												
	Mabon Lol	400	No system									912
	Malolim	20	No system									915
	Masuba	300	No system									913
	Mattanko	500	bore hole	1998	Indian Development Assoc	dry 3 months/year	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 911
	Rochen	2000	1/3 - hand dug well	2008	CORSON	dry 4 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 908
			2/3 - hand dug well	2008	CORSON	pump broken	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 909
			3/3 - hand dug well	2004	Merlin	dry 11 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 910
	Rofunk	200	No system									914
	Ropolon Lol	600	1/3 - pulley	1982	IN	dry 7 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 905

Malal Mara (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Rochen</u>												
	Ropolon Lol	1200	2/3 - bore hole	2008	MFG	dry 8 months/year	OTHER - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 906
			3/3 - pulley	1982	Indian Development Assoc	dry 1 month/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 907
	Rothangbay	15	No system									917
	Royal	40	No system									916

8 sections 63 villages - 40 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Malal Mara - summary / 23 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	5	2 900	0	2 (40%)	5	3 (60%)	1 (20%)	2 (40%)	2 (40%)
hand dug well	27	14 875	0	8 (29,6%)	25	18 (72%)	7 (26%)	10 (37%)	10 (37%)
	32	17 775	0	10 (31,2%)	30	21 (70%)	8 (25%)	12 (38%)	12 (38%)

Sambaia (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Borowa</u>												
	Banakoro	210	No system									677
	Gbelmakondeya	64	No system									681
	Herekoh	333	1/2 - hand dug well	2007	SALWACO	not finished					-	666
			2/2 - hand dug well	2007	SALWACO	not finished					-	667
	Kasafoni1	604	No system									678
	Kasafoni2	558	No system									679
	Kunya Hospital	2000	hand dug well	2010	ORIENT	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 673
	Kurakoroh	900	hand dug well	2009	SALWACO	not finished					-	672
	M C A Pri School	333	hand dug well	2009	NACSA	dry 2 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 668
	Morigboya	400	No system									675
	Nanfayie	266	1/3 - hand dug well	2008	SALWACO	not finished					-	669
			2/3 - hand dug well	2007	SALWACO	not finished					-	670
			3/3 - hand dug well	2008	SALWACO	not finished					-	671
	Sangbangba	215	No system									680
	Sumbuy	328	No system									674
	Wasima	648	No system									676
<u>Buyan</u>												
	Baburoh	348	No system									654
	Balandugu	75	No system									660
	Banankonkoh	500	No system									637
	Dafaria	62	No system									653
	Dandaya 1	54	No system									651
	Dandaya 2	86	No system									665
	Dankawallia	500	hand dug well	2007	SALWACO	not finished					-	634
	Farator	200	No system									659
	Ferensola	109	No system									645
	Fonema	220	No system									648
	Foray Balia	54	No system									646

Sambaia (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Buyan</u>												
	Gbamabalia	103	No system									638
	Gbassaya	500	No system									652
	Kailankoroh	450	No system									658
	Kanandugu	56	No system									662
	Kekuraya	105	No system									661
	Kensikoroh	200	No system									664
	Keradugu	610	hand dug well	2008	SALWACO	not finished				-		635
	Kombadugu	300	No system									647
	Komoya	86	No system									640
	Kongbalya	68	No system									650
	Konkoron Gbaya	604	No system									649
	Koromantor	250	No system									655
	Koyie	600	hand dug well	2007	SALWACO	not finished				-		633
	Manson Tambaia	543	No system									639
	Sakaferia	400	No system									656
	Samadugu	348	No system									643
	Sokoya	428	No system									657
	Sokurela	154	No system									642
	Sondonkoro	608	No system									641
	Unaduwa	260	No system									644
	Yambaia	102	No system									663
	Yandugu	712	No system									636
<u>Davie</u>												
	Berengbeh	400	hand dug well	2008	SALWACO	not finished				-		607
	Fenkebai	215	hand dug well	2007	SALWACO	not finished				-		608
	Heremakono	402	hand dug well	2009	SALWACO	not finished				-		605
	Kaliesakoh	105	No system									610
	Kameroh1	139	No system									611

Sambaia (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Dayie</u>												
	Kameroh2	139	No system									612
	Kameroh3	139	No system									613
	Kanmaranya	256	No system									615
	Kulifaga	500	1/2 - hand dug well	2010	SABABU	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
			2/3 - hand dug well	2005	MSF	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Mamuria	500	hand dug well	2009	SALWACO	not finished						-
	Mansodugu	125	No system									614
	Mindaia	270	No system									609
	Nunkikoro	750	hand dug well	2007	MAMIN	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
<u>Sambaia</u>												
	Ballaya1	106	No system									631
	Ballaya2	106	No system									632
	Ben Pri School	775	hand dug well	2010	SABABU	dry 3 months/year	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Foloya	270	No system									624
	Gbalakoroh1	108	No system									626
	Gbalakoroh2	108	No system									627
	Gbalakoroh3	108	No system									628
	Hospital	775	hand dug well	2010	ORIENT	dry 5 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Jalloh Street	775	hand dug well	2008	SALWACO	not finished						-
	Kabbaya	415	No system									625
	Kandaya	400	No system									630
	Kaningba	542	No system									623
	Kulmbsa	775	hand dug well	2007	NACSA	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	Rc Pri School	775	hand dug well	2010	CART	working	IM2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Shekuya	400	hand dug well	2008	SALWACO	not finished						-
	St Gro Sec School	775	hand dug well	2010	SABABU	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Tikadugu	310	No system									629

Sambaia (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.
---------	---------	--------------------	-------------	------	---------	------------	-----------	---------------	-----------------	------------------	-----------------

Ref.

4 sections 76 villages - 55 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Sambaia - summary / 21 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
hand dug well	25	14 724	15	2 (8%)	10	8 (80%)	1 (4%)	6 (24%)	3 (12%)
	25	14 724	15	2 (8%)	10	8 (80%)	1 (4%)	6 (24%)	3 (12%)

Tane (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
Maborbor Koray													
	maborbor Koray	200	No system									1272	
	Madebie	300	No system									1271	
	Makima	150	No system									1274	
	Masankoroh	75	No system									1275	
	patifu	200	No system									1273	
Makurqbeh													
	Five Mile	150	No system									1265	
	Mabendo	150	No system									1268	
	Mafoyimba	205	No system									1262	
	Magbafeth	110	No system									1261	
	Makorr	125	No system									1267	
Makurqbeh	126	1/4 - hand dug well	2008	NACSA		pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1256
	100	2/4 - hand dug well	2004	DFID		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1257
	350	3/4 - hand dug well	1993	CARE		pump broken	PB2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1258
	200	4/4 - hand dug well	1995	CARE		dry 2 months/year	K	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal	1259
	Manakela	120	No system									1263	
	Masabena	102	No system									1270	
	Masorie Kargbo	170	No system									1264	
	Mathele	300	bore hole	2003	CADO	dry 3 months/year	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working	1260
	Robankeh	105	No system									1266	
	Robarayin	250	No system									1269	
Mangay Bana													
	Kanigba	435	hand dug well	2007	ACTION AID	pump broken	OTHER - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1318
	Makargbo	400	No system									1322	
	Makeni Kayoka	280	No system									1321	
Makinth	237	1/3 - hand dug well	2009	ACTION AID		working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK	1310
	500	2/3 - hand dug well	2010	SALWACO		pump broken	OTHER - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1311
		3/3 - hand dug well	2002	ACF		working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OK	1312

Tane (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Mangay Bana</u>												
	Mamakoron	200	No system									1325
	Mangay Bana	600	1/3 - hand dug well	2003	Merlin	working	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1315
		287	2/3 - hand dug well	2007	ACF	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1316
		125	3/3 - hand dug well	2002	NACSA	dry 5 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1317
	Masakoro	250	No system									1326
	Masara	350	hand dug well	2004	SALWACO	working	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1320
	Mateporay	50	No system									1323
	Mayamba Morlia	150	No system									1324
	Roahalla	500	hand dug well	2003	ACF	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1319
	Rosengbeh	725	1/2 - pulley	2000	MRC	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1313
			2/2 - hand dug well	2002	ACF	pump broken	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working 1314
<u>Mapakie</u>												
	Maborbor	375	1/2 - hand dug well	1969	Indian Development Assoc	pump broken	OTHER - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1329
			2/2 - hand dug well	2009	SALWACO	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1330
	Mamar	130	No system									1338
	Mamara	300	hand dug well	2001	ACF	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1337
	Mapakie	550	1/2 - hand dug well	2008	SALWACO	pump broken	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1327
		240	2/2 - hand dug well	2008	ACTION AID	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1336
	Masumana Koray	250	No system									1340
	Matuflie	759	1/2 - hand dug well	2004	ACTION AID	dry 4 months/year	PB2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1334
			2/2 - hand dug well	2003	World Bank	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1335
	Mayinka	360	1/2 - hand dug well	2010	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1331
			2/2 - hand dug well	1970	CARE	working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1332
	Rogbom Sanda	100	No system									1339
	Rosinth	652	hand dug well	2004	SALWACO	dry 6 months/year	IM2 - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1328
	Rosinti	306	hand dug well	2006	CARE	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1333
<u>Mathonkara</u>												
	Mabai	103	No system									1254

Tane (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Mathonkara</u>												
	Mabekie	150	No system									1253
	Mabenthe	105	No system									1255
	Maforay	300	No system									1247
	Makeleh	600	No system									1248
	Makongblie	200	No system									1252
	Malapoh	550	No system									1250
	Malarkoh	250	No system									1246
	Mangay	350	No system									1251
Mathonkara	200	1/4 - hand dug well	2004	ACF		dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal
	300	2/4 - hand dug well	2005	ACF		dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal
	400	3/4 - hand dug well	2006	NACSA		dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	100	4/4 - pulley	2003	NRC		dry 6 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Mawargbeh	400	No system									1249
<u>Matotoka</u>												
	Bo Road 2	800	No system									1304
	Kefuma	150	No system									1307
	Mabamp	340	hand dug well	1985	CARE	dry 1 month/year	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
Macona	400	1/3 - hand dug well	1994	ACF		dry 4 months/year	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
	500	2/3 - hand dug well	2010	Red Cross		pump broken	OTHER - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	400	3/3 - hand dug well	2005	NACSA		pump broken	K - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Mafara	356	No system									1299
	Mafeka	150	No system									1296
	Maforay	250	hand dug well	2007	SALWACO	pump broken	OTHER - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Magburaka Road1	900	No system									1303
	Makeli	300	pulley	1980	CARE	-	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
Makeni Koray	350	1/2 - bore hole	2001	CADO		working	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK
	400	2/2 - hand dug well	2002	DFID		pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Makoma	150	No system									1309

Tane (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Matotoka												
	Mamakie	500	1/2 - hand dug well	2008	CARE	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1294
		200	2/2 - hand dug well	2007	SALWACO	pump broken	OTHER - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1295
	Manafel	250	No system									1297
	Manathillie	720	hand dug well	2005	CARE	pump broken	OTHER - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1292
	Mangay	800	hand dug well	2003	SABABU	dry 3 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1276
	Mara	46	No system									1300
	Masaka	450	hand dug well	2008	SALWACO	pump broken	OTHER - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1287
	Masara	350	hand dug well	1982	CADO	dry 2 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1291
	Masene1	150	No system									1301
	Masene2	100	No system									1302
	Mathainkay	400	hand dug well	2005	ACF	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Seasonal 1282
	Mathele Bo Road	150	No system									1308
	Mawollie	200	No system									1298
	Mayan	400	hand dug well	1990	CARE	dry 4 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1286
	Mayeto	360	hand dug well	2010	CEA	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1288
	Robanka 4	700	No system									1306
	Robis	300	hand dug well	2007	NACSA	pump broken	OTHER - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1285
	Rogbithon3	500	No system									1305
	Rogbum	210	hand dug well	2009	SALWACO	pump broken	OTHER - not working	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1290
	Ropollar	719	hand dug well	2004	ACF	dry 3 months/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seasonal 1289

6 sections 80 villages - 48 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee: presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Tane - summary / 32 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	2	650	0	1 (50%)	2	1 (50%)	0 (0%)	1 (50%)	1 (50%)
hand dug well	46	18 670	0	8 (17,4%)	46	20 (43%)	5 (11%)	11 (24%)	30 (65%)
	48	19 320	0	9 (18,8%)	48	21 (44%)	5 (10%)	12 (25%)	31 (65%)

Yoni (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Foindu												
	Foindu	500	hand dug well	2008	NACSA	dry 7 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1114
	Macca	350	hand dug well	2008	SALWACO	pump broken	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1119
	Mafala	235	hand dug well	2008	SALWACO	pump broken	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1118
	Mamaya	209	hand dug well	2008	SALWACO	pump broken	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1120
	Mayorgbor	600	1/3 - hand dug well	2008	SALWACO	not finished					-	1115
		500	2/3 - hand dug well	2004	Germany	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1116
		600	3/3 - hand dug well	2000	CCSL	dry 2 months/year	PB2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1117
Gaindema												
	2nd Back Pole	300	pulley	2009	Arab	dry 2 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 963
	2nd Back Street	300	pulley	2009	Arab	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 974
	91 Market	2000	bore hole	2009	Korean Group	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OK 1011
	Ahmadiyya	700	1/2 - bore hole	2010	Korean Group	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1005
		200	2/2 - hand dug well	2003	Mission	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1006
	Ansarul Road	200	1/2 - pulley	2009	Arab	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 985
			2/2 - pulley	2009	Arab	dry 3 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 986
	Back of Ansarul	400	hand dug well	2008	Korean Group	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 987
	Back Street	400	hand dug well	1999	UNICEF	dry 2 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 972
	Back Street 1	400	hand dug well	1999	UNICEF	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 952
	Benevolent School	600	hand dug well	2009	Concern	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 996
	Bo Road	400	1/7 - pulley	2009	Arab	dry 3 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 978
		300	2/7 - pulley	2009	Arab	dry 2 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 979
		350	3/7 - pulley	2009	Arab	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 980
		200	4/7 - pulley	2009	Arab	dry 3 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 981
			5/7 - pulley	2009	Arab	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 982
		1000	6/7 - pulley	1991	CARE	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 983
		250	7/7 - pulley	2009	Arab	dry 6 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 984
	Bundu Street	500	1/2 - hand dug well	2001	UNICEF	dry 3 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 994
		200	2/2 - pulley	2009	Arab	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 995
	Cemetery Road	600	hand dug well	2000	UNICEF	dry 3 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1014

Yoni (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Gaindema												
	Chapple Street	400	hand dug well	2000	UNICEF	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1017
	Comforti School	300	pulley	1983	Catholic Mission	dry 2 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1018
	Dumbuya Street	350	pulley	2009	Arab	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 973
	Fofana Street	400	1/2 - pulley	2009	Arab	dry 3 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 998
		300	2/2 - pulley	2009	Arab	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 999
	Freetown Highway	400	1/2 - hand dug well	2001	ICRC	dry 3 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1016
		500	2/2 - hand dug well	2002	UNICEF	dry 2 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1020
	Gaindema	500	hand dug well	2006	SALWACO	not finished						- 957
	Hinistas Community	250	hand dug well	2010	Concern	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 977
	Hinistas Hospital	600	bore hole	2009	Korean Group	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 976
	Jabi Street	400	1/2 - bore hole	2010	Concern	dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 960
		300	2/2 - pulley	2009	Arab	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 961
	Janneh Lane	350	hand dug well	2010	ORPHAN	dry 3 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 971
	Kabia Street	300	pulley	2009	Arab	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 975
	Kargbo Street	400	bore hole	2009	Korean Group	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1009
	Lebanese Lane	400	pulley	2009	Arab	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1008
	Madusha	800	1/2 - hand dug well	2008	SALWACO	pump broken	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 950
		200	2/2 - hand dug well	2009	SALWACO	dry 2 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 951
	Magburaka Road	500	1/9 - pulley	1991	CHRISTIAN COMMUNITY	dry 1 month/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 953
		450	2/9 - hand dug well	2001	ACTION AID	dry 2 months/year	IN	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 954
		300	3/9 - pulley	1991	CHRISTIAN COMMUNITY	dry 3 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 955
		4/9 - hand dug well	1991	CHRISTIAN COMMUNITY	dry 1 month/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 956
		5/9 - pulley	2009	Arab	-	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 990
		200	6/9 - pulley	2009	Arab	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 991
		250	7/9 - hand dug well	1996	UNICEF	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 992
		300	8/9 - hand dug well	1987	Indian Development Assoc	dry 2 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 993
		500	9/9 - bore hole	2008	SALWACO	pump broken	PB2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1002
	Matibo	500	hand dug well	2004	Concern	dry 3 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 949
	Mende Town	300	1/2 - pulley	2009	Arab	dry 2 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 988

Yoni (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Gaindema</u>												
	Mende Town	300	2/2 - pulley	2009	Arab	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 989
	Mini Stadium	1000	bore hole	2004	Korean Group	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 969
	Morfonday	400	hand dug well	2000	SALWACO	dry 4 months/year	PB2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1019
	Old Police Road	400	pulley	2009	Arab	dry 2 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 968
	Peace Village	500	bore hole	2009	Korean Group	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1007
	Police Barracks	300	hand dug well	2007	DFID	dry 1 month/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 965
	Police Station	400	bore hole	2007	Korean Group	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 964
	R . Kamandao 2	300	hand dug well	2009	SALWACO	pump broken	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1004
	R .Kamandao 1	400	bore hole	2009	Korean Group	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1003
	R .Kamandao 3	500	bore hole	2009	Korean Group	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 948
	Railway Line	400	bore hole	2009	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 959
	Saffa Street	300	pulley	2009	Arab	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1015
	Saidu Street	300	pulley	2009	Arab	dry 3 months/year	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 997
	SDA Community	400	hand dug well	2001	UNICEF	pump broken	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 962
	Teacher's Centre	400	hand dug well	2004	CONCERN	dry 1 month/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 970
	Tejan Street	400	bore hole	2009	Korean Group	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1010
	Turay street	300	pulley	2009	Arab	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1012
	UMC Road	500	hand dug well	2009	UMC	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 958
	Water Street	250	1/2 - pulley	2009	Arab	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1000
		300	2/2 - pulley	2009	Arab	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1001
	Yoni Road	300	1/2 - hand dug well	2001	UNICEF	dry 1 month/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 966
		2/2 - pulley	2009	Arab	-	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 967	
<u>Makorgba</u>												
	Gbombana	596	hand dug well	2002	Living Water International	working	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OK 1095
	Mabedu		No system									1105
	Mabola		No system									1107
	Mabop		No system									1106
	Mabudu		No system									1099

Yoni (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Makorgba</u>												
	Magbanth		No system									1102
	Makorgba	1100	hand dug well	2003	Roda	dry 2 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1092
	Makundor	400	hand dug well	2005	Roda	dry 8 months/year	PB2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1091
	Mapmant	353	1/2 - hand dug well	2002	CCSL	dry 1 month/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1096
		216	2/2 - hand dug well	2008	District Council	dry 2 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1097
	Masoya		No system									1104
	Matonneh	70	hand dug well	2005	Roda	dry 1 month/year	PB2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1090
	Rochane Makin	600	hand dug well	2006	Roda	pump broken	IN - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1094
	Rocrat	500	hand dug well	2009	SALWACO	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1089
	Roken		No system									1098
	Romes		No system									1100
	Rosent		No system									1101
	Wankely		No system									1103
<u>Malanchure</u>												
	Boryouma		No system									1230
	Maboka		No system									1235
	Mafala		No system									1226
	Makenthalie		No system									1236
	Makondu		No system									1233
	Makuntor		No system									1239
	Malanchure	1000	hand dug well	2009	Other	not finished					-	1225
	Mamampa		No system									1234
	Mamomoh		No system									1237
	Manasie		No system									1229
	Masarbay		No system									1240
	Mayira1		No system									1231
	Mayira2		No system									1232
	Petifu		No system									1228

Yoni (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Malanchure</u>												
	Robarrie		No system									1238
	Rogbama		No system									1241
	Rokomtha		No system									1227
<u>Malompor</u>												
	Banka		No system									1136
	Biela Lol		No system									1138
	Mabant		No system									1139
	Makarugb		No system									1135
	Makele		No system									1133
	Masanka		No system									1137
	Masira		No system									1134
	Rogbla		No system									1132
<u>Malonpor</u>												
	Majehun	500	pulley	1971	Indian Development Assoc	dry 5 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Maronda	150	hand dug well	2008	SALWACO	pump broken	no pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Rokaron	300	hand dug well	2008	NACSA	dry 1 month/year	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
<u>Mamaka</u>												
	Health Centre Matoi	1000	hand dug well	2003	ADB	working	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Malai	350	hand dug well	2000	SALWACO	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Mamaka	400	1/3 - hand dug well	2001	CHRISTIAN CHILDREN F	dry 3 months/year	IM2 - stolen	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
		300	2/3 - hand dug well	2009	Living Water International	working	AFR	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
		250	3/3 - hand dug well	2010	SALWACO	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Masaincla	400	hand dug well	2000	CHRISTIAN CHILDREN F	dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Masankay	250	hand dug well	2001	CHRISTIAN CHILDREN F	dry 2 months/year	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Maseteh	350	bore hole	2010	Korean Group	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Matoi 1	700	hand dug well	2003	Community	working	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Matoi Line 1	325	bore hole	2007	Korean Group	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Matoi Line 2	450	hand dug well	2003	Bangladesh	dry 4 months/year	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working

Yoni (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Mamaka												
	Rokimbi	600	1/5 - hand dug well	2000	SALWACO	dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1028
		539	2/5 - hand dug well	2004	CHRISTIAN CHILDREN F	dry 3 months/year	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1029
		200	3/5 - bore hole	2007	District Council	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1030
		300	4/5 - hand dug well	1998	SALWACO	dry 2 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1031
		600	5/5 - hand dug well	1993	SALWACO	dry 2 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1032
	SLMB Matoi	600	hand dug well	2004	Living Water International	working	AFR	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1034
	TDC School Matoi	800	hand dug well	2003	Roda	pump broken	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1036
Masengbeh												
	Magbamamoi		No system									1129
	Makan Bumdu		No system									1123
	Makema		No system									1127
	Mamamu		No system									1128
	Mamondo		No system									1121
	Mangobu		No system									1126
	Mapolie	450	hand dug well	2009	NACSA	pump broken	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1113
	Masangbo 1	800	pulley	2001	Concern	dry 4 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1111
	Masanke		No system									1131
	Masengbeh 2	700	hand dug well	2002	CARITAS	dry 2 months/year	PB2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1112
	Petifu		No system									1125
	Pothka		No system									1130
	Rogbamgbama		No system									1124
	Rogbonkeh		No system									1122
Mayira												
	Magbaesa	1000	1/3 - hand dug well	2001	UNICEF	dry 9 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1185
			2/3 - hand dug well	2001	UNICEF	dry 5 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1186
			3/3 - hand dug well	2006	UNICEF	dry 2 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1187
	Makargbo		No system									1198
	Makonkorie	500	hand dug well	1985	MCA	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1184

Yoni (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.	
<u>Mayira</u>													
	Makonta		No system									1197	
	Mamankara		No system									1199	
	Mayara		No system									1201	
	Mayira	200	1/2 - hand dug well	2007	NACSA	dry 6 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1188
		400	2/2 - hand dug well	2008	Roda	dry 6 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1189
	Robang1		No system									1196	
	Robang2		No system									1200	
	Rokupr		No system									1195	
	Roline	400	hand dug well	2005	Other	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1183
	Roline Magbortha		No system									1194	
	Romadina	400	1/2 - hand dug well	2001	Red Cross	dry 5 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1191
		125	2/2 - hand dug well	2001	AC	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1192
	Rongella	500	hand dug well	2004	SALWACO	dry 3 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1190
	Ronuary	500	hand dug well	2008	ARCK	dry 4 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1193
<u>Petifu</u>													
	Bakeloko	350	1/2 - hand dug well	2009	SALWACO	dry 7 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1074
		400	2/2 - hand dug well	2010	PB	not finished						-	1075
	Bonkababay	600	hand dug well	2001	NACSA	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1087
	Gbombana	300	hand dug well	2010	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1076
	Mafokoya	700	1/2 - hand dug well	1990	UMC	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1085
		287	2/2 - hand dug well	2002	CAR	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1086
	Magbashen Bana	400	hand dug well	2000	Watsan	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1079
	Magbashen Lol	460	hand dug well	2009	SALWACO	not finished						-	1078
	Makonday	700	pulley	1971	Indian Development Assoc	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1088
	Mayoibor	450	hand dug well	2009	District Council	dry 3 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1080
	Petifu	1628	1/5 - hand dug well	2009	Korean Group	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK	1069
		628	2/5 - bore hole	2002	Afriicare	not finished						-	1070
		900	3/5 - hand dug well	2004	Community	dry 5 months/year	OTHER - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working	1071

Yoni (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Petifu</u>												
	Petifu	800	4/5 - hand dug well	1994	Community	dry 7 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1072
		700	5/5 - pulley	2004	Community	dry 7 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1073
	Rocrocks	4080	1/4 - hand dug well	2003	GTZ	pump broken	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1081
		1000	2/4 - hand dug well	1991	UMC	dry 4 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1082
		383	3/4 - hand dug well	2008	District Council	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1083
		300	4/4 - hand dug well	2006	Ridial	dry 1 month/year	K	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1084
	Ronowla	700	hand dug well	2009	SALWACO	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1077
<u>Roke Fula</u>												
	Mabakena		No system									1222
	Makafie		No system									1209
	Makambo		No system									1220
	Makendeh		No system									1215
	Makeni	2000	hand dug well	2008	SALWACO	dry 12 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1204
	Makenthie		No system									1210
	Makomara		No system									1219
	Makondu	800	hand dug well	2008	SALWACO	dry 12 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1205
	Malokoh		No system									1211
	Malonko		No system									1207
	Mamusia		No system									1224
	Marokey		No system									1208
	Masorie		No system									1221
	Matambo		No system									1212
	Romaboro		No system									1223
	Romafonie		No system									1216
	Romagbaft	800	hand dug well	2008	SALWACO	dry 12 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1206
	Romakenthie2		No system									1214
	Romalankia		No system									1213
	Romano	800	1/2 - hand dug well	2007	Private	dry 3 months/year	PB2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1202

Yoni (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Roke Fula												
	Romano	700	2/2 - hand dug well	2009	SALWACO	dry 12 months/year	no pump	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1203
	Sumbuya1		No system									1217
	Sumbuya2		No system									1218
Ronietta												
	Bangbutt	100	1/2 - hand dug well	1990	Indian Development Assoc	dry 4 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1146
			2/2 - hand dug well	2005	Indian Development Assoc	dry 7 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1147
	Bath Bana 2		No system									1176
	Bathbana	600	1/2 - hand dug well	1991	CARE	dry 4 months/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1149
		500	2/2 - hand dug well	2004	CARE	dry 3 months/year	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1150
	Mafuntha	500	hand dug well	1990	CARE	dry 4 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1148
	Magbafth		No system									1163
	Magbayo		No system									1174
	Magbonkuma		No system									1172
	Magborie		No system									1164
	Magbosie	3000	hand dug well	2009	SALWACO	dry 4 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1153
	Makama		No system									1155
	Makoye		No system									1166
	Mamale		No system									1162
	Mamayangba	400	hand dug well	2001	Indian Development Assoc	dry 1 month/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1152
	Mamenka		No system									1165
	Manayanelo		No system									1178
	Mapayamba		No system									1161
	Mapethaka		No system									1177
	Masanka		No system									1160
	Maseria		No system									1154
	Mashalo		No system									1180
	Masuba		No system									1156
	Mayasie		No system									1179

Yoni (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
Ronietta												
	Roborllone		No system									1167
	Rokimbie		No system									1159
	Rokinmbie	300	hand dug well	1981	Indian Development Assoc	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Rokuntore		No system									1173
	Romabotoma		No system									1181
	Romises		No system									1182
	Ronietta	800	1/6 - hand dug well	2004	GTZ	working	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
		500	2/6 - hand dug well	1982	GTZ	dry 5 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
		400	3/6 - hand dug well	2010	GTZ	dry 5 months/year	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
		500	4/6 - hand dug well	2008	GTZ	dry 6 months/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
		600	5/6 - hand dug well	1994	Indian Development Assoc	dry 3 months/year	PB2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
		100	6/6 - hand dug well	1989	UMC	dry 1 month/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Ropet 1		No system									1170
	Ropet 2		No system									1171
	Rosent		No system									1175
	Royanka 1		No system									1168
	Royanka 2		No system									1169
Yoni												
	Bol Yoni	300	hand dug well	2008	Korean Group	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Chain Road	400	bore hole	2008	SSSB	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Coperative	500	1/2 - bore hole	1999	ACF	pump broken	K - not working	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
		700	2/2 - hand dug well	2009	SSSB	dry 1 month/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal
	Komrabai Y	1657	hand dug well	1990	UMC	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Makabi	370	pulley	1971	Indian Development Assoc	-	no pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Mamorka	500	hand dug well	2001	UNICEF	dry 1 month/year	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working
	Market Yoni	800	hand dug well	2008	SSSB	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK
	Masethleh	500	1/2 - hand dug well	2008	Korean Group	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not Working
		450	2/2 - bore hole	2008	Korean Group	pump broken	IM2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working

Yoni (Tonkolili)

Section	Village	Popul. Approxim	System type	Year	Done by	Functional	Pump type	Users Com.	Pump. CareT.	Tools SpareP.	Money contr.	Ref.
<u>Yoni</u>												
	Mataitai	620	1/2 - hand dug well	2009	SALWACO	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1063
		600	2/2 - hand dug well	1999	CARE	dry 3 months/year	IN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1064
	Matopie	800	hand dug well	2010	SALWACO	not finished						- 1061
	Old Market	400	1/2 - hand dug well	2001	UMC	dry 2 months/year	PB2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1050
		300	2/2 - hand dug well	2008	SSSB	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1051
	Over Stream	300	hand dug well	2008	SSSB	dry 2 months/year	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1054
	Rochain Junction	336	1/2 - bore hole	2009	SABABU	dry 4 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1057
		500	2/2 - hand dug well	2001	UNICEF	dry 3 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1058
	Royanka	300	1/2 - hand dug well	1991	SALWACO	pump broken	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1066
		250	2/2 - hand dug well	2009	APC	not finished						- 1067
	Station Road	250	hand dug well	2008	SSSB	working	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1055
	UMC Church	500	hand dug well	1993	UMC	dry 2 months/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1048
	UMC Matopie	800	hand dug well	2002	GTZ	dry 1 month/year	PB2 - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1060
	UMC Yoni	500	hand dug well	2004	UMC	dry 1 month/year	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1046
	Yoni	400	1/4 - bore hole	2008	Korean Group	working	IM2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OK 1040
		500	2/4 - hand dug well	2000	CFADA	dry 1 month/year	IM2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1041
		600	3/4 - bore hole	2007	SSSB	pump broken	K - not working	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1042
		700	4/4 - hand dug well	1970	Community	pump broken	no pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1043
	Yonibana	700	hand dug well	2010	SALWACO	pump broken	IM2 - not working	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not Working 1039
	Yss Yoni	500	bore hole	2006	UMC	dry 1 month/year	OTHER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Seasonal 1047

13 sections 227 villages - 98 with no system at all

Caption:

Not working: pump problem and/or no water all year long.

Seasonal: provides water but not all year long (<=3months dry)

Not finished: construction started but site not finished

Pump type: K = Kardia; IM2 = India Mark 2; PB = PBMark; IN = Inka

Users Committee: presence of a Committee of Users

Pump CareTaker.: a person trained to maintain the pump

Tools Spare Parts are available in the community

Money contribution is done by the community for maintenance

Yoni - summary / 129 villages

Type	Total	Popul. Approxim	Not finished	Functional all the year	P U M P		SEASONALITY		
					installed	working	Dry>3m	seasonal	Alw. water
bore hole	24	12 889	1	13 (54,2%)	23	18 (78%)	1 (4%)	4 (17%)	18 (75%)
hand dug well	131	73 608	7	16 (12,2%)	95	48 (51%)	26 (20%)	53 (40%)	45 (34%)
	155	86 497	8	29 (18,7%)	118	66 (56%)	27 (17%)	57 (37%)	63 (41%)